


DTC FLECTE JUL 23 1991



Approved for purple felected

Distribution Unformed

DEPARTMENT OF THE AIR FORCE

AIR UNIVERSITY

AIR FORCE INSTITUTE OF TECHNOLOGY

Wright-Patterson Air Force Base, Ohio

91 7 10 135

Best Available Copy






AN INTERACTIVE LIFE CYCLE COST FORECASTING TOOL

THESIS

John A. Gibson, IV Captain, USAF

AFIT/GOR/ENS/91M-5



91-05735

91-15 146

REPORT DOCUMENTATION PAGE

Form Approved
OME No. 0704 0188

| Fig. (report of proper training) — Americal (report of proper) and consequent (report of proper | rmunito (Queli mategini) (Lera scilini) (qui co inclue) — Il discolari (Stellini) (qui co readuni) in Supramini (Associatio) (mead 1807) and to the Otto Fort Municipal emercandis | Province of UB notice time to the control of the province of t | Peuring instrument in seventime (Kentom disce Shumër Drugit si Dilige in time e i i i i i i i i i i i i i i i i I i i i makin i i gentalinda ki di Republici i i i i i i i thersin I i i 1774 (1955) i Washington (1903) | | | | |
|---|---|--|---|--|--|--|--|
| 1. AGENCY USE ONLY (LEAVE DIATA | / 2 REPORT DATE March 1991 | 3 REPORT TYPE A') Master's Th | | | | | |
| 4. TITLE AND SUBTITLE | | | 5 FUNDING NUMBERS | | | | |
| An Interactive Lif | e Cycle Cost Fore | casting Tool | | | | | |
| 6 AUTHOR(S) | | | | | | | |
| John A. Gibson, IV | , Captain, USAF | | | | | | |
| 7. PERFORMING ORGANIZATION NA | ME(S) AND ADDRESS(ES) | | B. PERFORMING ORGANIZATION REPORT NUMBER | | | | |
| Air Force Institut | - • · | WPAFB OH 433-6583 | AFIT/GOR/ENS-91M-5 | | | | |
| | | | | | | | |
| 9. SPONSORING MONITORING AGE | NCY NAME(S) AND ADDRESS(ES) | | 10. SPONSORING MONITORING AGENCY REPORT NUMBER | | | | |
| | | | | | | | |
| 11. SUPPLEMENTARY NOTES | | | | | | | |
| TE DISTRIBUTION AVAILATINTY S | TATEMENT | | 126 DISTRIBUTION CODE | | | | |
| Approved for publi | c release; distri | bution | | | | | |
| unlimited | | | | | | | |
| 13. ABSTRACT (Maximum 200 words | | | | | | | |
| Enhancements were life cycle costs. manipulation, addi | These enhancemen tional options in | ts provide greater developing mo | eater ease of data odels, and the | | | | |
| cycle costs can be amount of work dor | e generated quickl ne by the computer | y and easily. could be redu | of the user. Life Analysis proved the uced with no loss of | | | | |
| information. Addi graphically throug | | | to the user are shown | | | | |
| The efforts of the | user can now be | directed towar | rds developing models how to make the tool | | | | |
| WOTK. | | | | | | | |
| | | | | | | | |
| 14. SUBJECT TERMS | | | 15. NUMBER OF PAGES | | | | |
| Life Cycle Cost Mo | dels, Computer Pr | ogramming, Cos | st 139 | | | | |
| Estimating Relation | | | | | | | |
| 17 SECIJRITY CLASSIFICATION 1 OF REPORT | 8 SECURITY CLASSIFICATION OF THIS PAGE | 19 SECURITY CLASSIFIC OF ABSTRACT | CATION 20 LIMITATION OF ABSTRA | | | | |
| Unclassified | Unclassified | Unclassifie | ed UL | | | | |

AN INTERACTIVE LIFE CYCLE COST FORECASTING TOOL

THESIS

Presented to the Faculty of the School of Engineering of the Air Force Institute of Technology

Air University

In Partial Fulfillment of the

Requirements for the Degree of

Master of Science

John A. Gibson, IV, M.S.

Captain, USAF

| Accessor Son Miles (DEC) of Birds (Section 1) Controlled (Section 2) Just document |
|--|
| By Dist institut |
| Available of College |
| Dist AV. 1 |
| A-1 |

March 1991

Approved for public release; distribution unlimited



THESIS APPROVAL

STUDENT: John A. Gibson, IV CLASS: GOR-91M

THESIS TITLE: An Interactive Life Cycle Cost Forecasting Tool.

DEFENSE DATE: 25 February 1991

COMMITTEE:

NAME/DEPARTMENT

SIGNATURE

Advisor

Dr Cain/ENS

Reader

MAJ Bauer/ENS

Preface

The purpose of this study was to enhance Dr Cain's Monte Carlo simulation for the forecasting of life cycle costs.

These enhancements provide greater ease of data manipulation, additional options in developing models, and the ability to make modifications to suit the needs of the user. Life cycle costs can be generated quickly and easily.

I chose this research topic because of my interests in economics and computer programming. I am indebted to Dr Cain for allowing me to work at my own pace and incorporate my ideas into the project.

I would also like to thank Major Morlan who in 15 minutes solved three days of computer debugging -- he didn't realize how much effort he saved me. I would also like to thank Major Bauer and Professor Reynolds for providing me with enough of a statistics background to ensure the rigor required was applied.

My deepest thanks go to my wife Sandy who put up with the never ending procession of late nights and incessant complaining.

John A. "Hoot" Gibson

Table of Contents

| | | Page |
|----------|--------------------------------------|------|
| Preface | | ii |
| List of | Figures | v |
| List of | Tables | vi |
| Abstrac | t | vii |
| I. Intro | oduction | 1 |
| | Background | 1 |
| | Objective | 3 |
| | Subobjectives and Methodologies | 3 |
| II. | Literature Review | 6 |
| | Introduction | 6 |
| | Life Cycle Cost Models | 6 |
| | Analogy Estimates | 7 |
| | Parametric Methodology | 8 |
| | Engineering or bottom up methodology | 11 |
| | Random Number Generation | 12 |
| | Overview | 12 |
| | General Sampling Techniques | 15 |
| | Inverse Transformation | 15 |
| | Composition | 16 |
| | Acceptance/Rejection | 16 |
| | | 17 |
| | Summary | 17 |
| III. | Methodology | 19 |
| | Overview | 19 |
| | Cost Estimating Relationships | 19 |
| | Beta and Triangular Distributions | 21 |
| | Beta Distribution | 22 |
| | Triangular Distribution | 24 |
| | Software Verification and Validation | 25 |
| IV. | Implementation | 27 |
| _ * • | | e, |
| | Overview | 27 |
| | Data Input Modification | 27 |
| | Software Verification and Validation | 33 |
| | Verification | 33 |

| | Validat | ion . | • | | | | • | • | | • | | • | 36 |
|---------------|----------|--------|------|------|----------|-----|---|---|---|---|---|---|-----|
| Rando | om Varia | | | | | | | | | | | | |
| | Normali | | | | | | | | | | | | |
| | Compari | son o | f Me | eans | ; , | | • | • | | | • | • | 44 |
| | Compari | | | | | | | | | | | | 44 |
| Progr | ram Modi | ficat | ion | • | • | • • | • | • | • | • | • | • | 45 |
| V. Conclusior | ns and F | Recomm | enda | atic | ns | • | • | • | • | • | • | • | 48 |
| Goal | Realiza | tion | • | | • | | • | • | • | | | | 48 |
| Recor | nmendati | | | | | | | | | | | | 48 |
| | Random | | | | | | | | | | | | 48 |
| | Validat | cion C | hec | k. | • | • • | • | • | • | • | • | • | 49 |
| Appendix A: | User's | Manua | 1 | | • | | • | • | • | • | • | • | 50 |
| Appendix B: | Flowcha | art . | • | | • | | • | • | • | • | | • | 65 |
| Appendix C: | FORTRAN | N sour | ce (| code | : | | • | • | • | • | • | • | 71 |
| Bibliography | | | • | • • | • | | • | • | • | • | • | • | 138 |
| Vita | | | | | | | | | | | | | 120 |

List of Figures

| Figu | ire | | | | Page |
|------|---|------|---|---|------|
| 1. | Cost Representation for Parametric Method | | _ | • | 11 |
| 2. | Nine Beta Distributions | | | | 23 |

List of Tables

| Tabl | e | Page |
|------|---|------|
| 1. | Cost Estimate by Analogy | 9 |
| 2. | Echo Check Example of CER Data Consisting of 3 Slope Parameters | 34 |
| 3. | Hand Generated Expected Life Cycle Cost of a Weapon System Consisting of Eight Components | 39 |

Abstract

Enhancements were applied to an existing tool designed to estimate life cycle costs. These enhancements provide greater ease of data manipulation, additional options in developing models, and the ability to make modifications to suit the desires of the user. Life cycle costs can be generated quickly and easily.

Analysis proved the amount of work done by the computer could be reduced with r loss of information. Additionally, the paths available to the user are shown graphically through flow charts — aiding in the learning process. The efforts of the user can now be directed towards developing moders instead of spending those efforts on deciphering how to make the tool work.

AN INTERACTIVE LIFE CYCLE COST FORECASTING TOOL

I. Introduction

Background

Numerous programs within the United States require federal funding in order for them to survive -- one of them being the Department of Defense (DoD). "The acquisition of major weapon systems is a costly and long-term effort, often requiring the commitment of billions of dollars over a period of years" (COEA:2).

The funding necessary for a single weapon system can span more than two decades (like the B-52 bomber and C-141 transport aircraft). This occurs because weapon systems cannot just be bought off the shelf, used for a certain period of time, and then thrown away. Future weapon systems must be tested and modified to assure the American public their money is being spent on projects capable of meeting and suppressing the threat the systems were designed against. Once a weapon system has been procured, additional funding is needed to maintain and operate it. In other words, money is constantly required for the efficient

functioning of a weapon system throughout its entire life, hence the term life cycle cost (LCC). The AF Systems

Command Manual 173-1, Cost Estimating Procedures, defines

LCC.

LCC is the government's total cost of owning a system, subsystem, or component over its full life. It includes development, production, operating, and support costs. (AFSCM:5-1)

"Since life cycle costing includes all the phases of a program's life, a more realistic look at the budgetary effect is achieved" (Sumner:3). A weapon system whose anticipated procurement cost is the lowest of all systems competing for selection may not be the cheapest in the long run. If its research and development or maintenance costs are significantly higher than another system's, it may not be the best choice from the cost perspective.

Another important factor deals with the time when money for a weapon system is to be spent. The choice of whether to spend millions of dollars today versus delaying the payment until the following year can be extremely critical in deciding when a weapon system becomes available for use (or available at all). The value of money today is always more than the value of the same dollar amount of money in the future. Therefore, if the expected return on the funding of a weapon system is below an alternative's, and

the price of the weapon system is not anticipated to significantly increase over the following year, then it may be in the best interest of the United States government to delay funding of the weapon system until next year. As Sumner stated,

Since the stages of a program occur chronologically, LCC allows for the 'timing' of the money spent. Therefore, the timing of money spent by competing programs can be a very significant factor. (Sumner:3)

Objective

The purpose of this research was to enhance Dr Cain's Monte Carlo simulation for the forecasting of life cycle costs. The enhancements include (but are not limited to): providing the user with a choice of distributions in aiding him to estimate the expected life cycle cost of the system in question, modifying the software structure to accommodate better data input, and creating documentation in the form of detailed flow charts. An additional goal of this research was to determine if the number of random numbers currently generated for each random variable and cost estimating relationship (CER) was necessary.

Subobjectives and Methodologies

Following are the study's subobjectives and the methods used to achieve them.

Data Input Modification Modify the program so data can

be changed per element instead of having to reenter the entire data set.

Upon entering data into Dr Cain's program, the only way a change could be made to one or a few of the inputs was to completely reenter the entire data set. This input procedure was modified by first saving the original data set into two external files, and then prompting the user if any changes to one or more of the data needed to be made.

Software Verification and Validation A test model provided by Dr Cain was used to verify and validate the LCC.FOR computer code.

<u>Documentation</u> Develop detailed flow charts to graphically present what the computer code does, and also increase the user-friendliness of the software.

No flow charts existed for Dr Cain's program. Dr Cain felt flow charts would be a good idea to help eliminate the need of having just the computer code available to obtain an understanding of how the program LCC.FOR operates. Detailed flow charts were developed to graphically represent the action taking place in the computer code.

Alternative Distribution Incorporate the triangular distribution to complement the existing beta distribution in generating random variables.

The original program only allowed for using the beta distribution in calculating random variables and CER's. The

addition of the simpler triangular distribution provides the user with an alternative to the somewhat complicated and less intuitive beta distribution.

Random Variable Sampling Reduction The program LCC.FOR currently obtains 750 random samples in estimating the life cycle cost of a system. Determine if any information is lost by reducing the number of samples taken to 500 or 250.

The methodology used in assessing this subobjective was done by first testing whether the data samples taken were normally distributed. The next steps involved comparing the means and variances of runs generated from both sample sizes.

<u>Program Modification</u> Include a list of instructions to the user of the program LCC.FOR so modifications can be made to the program to suit their individual needs.

A list of pertinent changes was presented so any user of the program LCC.FOR could incorporate more cost elements and/or modify the number of samples generated.

II. Literature Review

Introduction

The purpose of this chapter is to review literature pertinent to the forecasting of life cycle costs (LCC's). The areas of literature that must be reviewed for this effort include theoretical life cycle costing methods and random number generation.

Life Cycle Cost Models

As stated earlier, "life cycle costs reflect the cumulative costs of developing, procuring, and operating a system, subsystem, of component over its full life" (COEA:6; AFSCM:5-1). The importance of providing accurate cost estimates over the life of a system cannot be underestimated. Cost is sometimes the only factor that can be directly compared between competing projects. The Program Analysis and Evaluation (PA&E) Office of the Assistant Secretary of Defense states, "Cost estimates are as important as operational effectiveness measures in a cost and operational effectiveness analysis" (COEA:15). The literature suggests there are three types of LCC models (COEA:15; Seldon:23):

- 1. Estimating by analogy
- 2. Parametric methodology

3. Engineering, or bottom up estimates

"Estimates by analogy and the parametric methodology are both 'top down' methods, because they examine the program as a whole" (Seldon:16). The engineering estimate is a bottom up method because it is comprised of detailed costs of every component that is contained within the whole program (Seldon:16).

Analogy Estimates

Estimating by analogy is the easiest of the three methods because it requires the least amount of detail. "Analogy estimates are conducted by adjusting the known costs of existing systems similar to the one in question to arrive at cost projections" (COEA:15). In other words, the cost of a current project is related to that of a previous one. Of course, if data are available on more than one past program, all data will be included in the estimate by providing a general relationship on those characteristics (both similar and different) of all systems concerned (Seldon:15-16).

Analogy estimates are usually conducted very early in the development of a future system to try to gauge the approximate order of magnitude of the expected total cost.

"By starting the LCC analysis at the conceptual phase, it is possible to ask whether it would be wiser to produce a new system or to modify an older existing one" (Seldon:15).

Table 1 contains an example of how analogy estimates are

conducted by comparing a new program for airborne electronic equipment against an already existing system (taken from Seldon's book on Life Cycle Costing: A Becter Method of Government Procurement).

If conducted early in the conceptual phase, the method of estimating by analogy provides management with a quick and easy way to determine if the cost of a new project is prohibitive or not. This method allows periodic updates to be made as they occur, with relatively minor effort.

"Surprisingly, such estimates are usually accurate if all the significant changes between programs are understood and accounted for" (Seldon:25).

Parametric Methodology

"Parametric cost analysis involves the development and utilization of estimating relationships between historical costs and physical and/or performance characteristics of a system" (AFSCM:5-4; COEA:15; Sumner:7). The system characteristics (such as aircraft speed or the number of maintenance personnel required to support a missile's guidance shop) are commonly referred to as parameters whereas, "the historical costs reflect the impact of system growth, engineering changes, program stretchouts, and any other cost, schedule, or performance difficulties encountered in comparable programs" (AFSCM:5-4). If the characteristics of a current or previous system can be

Table 1

COST ESTIMATE BY ANALOGY
(in millions of \$)

| Cost Element | Base Program | New Program |
|--|--------------|-------------|
| Systems engineering and program management | 2.0 | 2.2 (a) |
| Design | 8.0 | 11.2 (b) |
| Prototype fabrication and material | 1.5 | 1.1 (c) |
| Flight and laboratory test | 3.0 | 1.5 (d) |
| Total | 14.5 | 16.0 |

Notes:

- (a) Systems engineering and program management for the New Program are similar to those of the Base Program; the 10% increase in the New Program is due to larger task of design monitoring.
- (b) In the New Program, the additional design task of the moving target indicator adds 20%, and higher performance requirements will require another 20%, for a total of 140% of the cost of the Base Program.
- (c) The New Program requires only two prototypes versus three for the Base Program; tooling and other fixed costs were about \$300,000 for the Base Program, with each prototype at \$400,000.
- (d) The New Program requires only one aircraft model qualification; flight test personnel estimate the cost at one-half that of the Base Program.

(Seldon:24)

quantified by some statistical means (linear regression for example), a parametric relationship or cost estimating relationship (CER) can be developed. The purpose of a CER

is to attempt to predict the future based upon information received from past occurrences (MECA:79). A CER accomplishes this by "transforming the problem from one of estimating dollars to one of estimating a more familiar and more accessible variable" (Seldon:25). A major concern with using CER's as a forecasting tool is the amount of confidence that can be placed in estimates derived from the CER.

The DoD <u>Life Cycle Costing Guide For System Acquisitions</u>
(taken from Sumner's thesis) lists several advantages
associated with using CER's to estimate costs. The
advantages are as follows:

- Cost estimates are based on general system characteristics, no detailed information is necessary;
- 2. Model is very fast and easy to use;
- 3. Model is resistant to user bias;
- 4. Since parametric statistics are used in generating the forecasts, confidence intervals (CI's) can be placed on the forecasts. (Sumner:8)

The concern regarding how much confidence can be placed in CER estimates is addressed by the fourth advantage.

Figure 1 shows an example of a parametric CER model taken from Sumner's thesis. Notice the costs are calculated from general characteristics and some error is associated with each equation.

Engineering or bottom up methodology

The engineering method of estimating the total cost of a system is commonly referred to as the bottom up method. To conduct an engineering estimate, a clear description of the task to be completed must be understood by every level involved in the project. The levels involved then estimate the cost of doing the particular task assigned to it by using specific hardware-to-cost relationships (Seldon:32; Sumner:8-9). The sum of these estimates represent the total cost of the project, hence the term 'bottom up'. "Obviously this takes more information, and indeed the DoD does not recommend this as a method for preliminary work since the level of detail needed is usually obtained after many

```
COST REPRESENTATION FOR ONE C-130 USING
      THE PARAMETRIC METHODOLOGY
 CER's
 Airframe = 200,000 + 75 * X1 + e
          = 2,000 + 63 * X2 + e
 Engines
  Electronic = 530 + 200 * X3 + e
 Manpower = 300,000 + 400,000 * X4 + e
 Operating = 500,000 + 12,000 * X5 + e
  where
      X1 = airframe weight
      X2 = thrust
      X3 = number of radios
       X4 = number of crewmembers
       X5 = yearly flying hours
       e = error, iid N(0,MSE)
```

Figure 1 Parametric CER cost model example (Sumner:9)

crucial decisions (based on cost) have been made" (Sumner:9).

The engineering method is similar to the parametric method because the system is broken down into cost components and CER's may be used to determine the cost of each component (Sumner:8). One main advantage of the engineering method is the costs tend to be very accurate due to the detail provided by each level (Seldon:34; Sumner:9). Random Number Generation

Overview

The most common method of creating random numbers is the Monte Carlo method. The term Monte Carlo comes from the city located in Monaco famous for its casino. The roulette wheel, a popular game of chance at most casinos, is one of the simplest mechanical devices for the generation of random numbers, hence the name, Monte Carlo. "The Monte Carlo method is a numerical method of solving mathematical problems by means of random sampling" (Sobol:8).

The Monte Carlo method is comprised of a unique feature.

In I. M. Sobol's book, The Monte Carlo Method, he states;

This feature is the simple structure of the computation algorithm. As a rule, a program is prepared to perform only one random trial. This trial is repeated N times, each trial being independent of all others, and the results of all trials are averaged. Thus the Monte Carlo method is sometimes called the 'method of statistical trials'. (Sobol:10)

Sobol continues his discussion of the Monte Carlo method by stating that Monte Carlo is not a good method in solving problems that require a high degree of accuracy. His reason for this is due to the error of the calculations being proportional to the square root of D/N, where D is a constant and N is the number of trials run. Sobol points out that to reduce the error by a factor of 10, 100 additional runs would have to be conducted, which may not be feasible due to time and cost constraints (Sobol:10).

The literature states there are three methods of obtaining random numbers: 1. tables of random numbers, 2. random number generators, and 3. the method of pseudo random numbers (Pritsker.716-717; Sobol:24). A random number table is just that, a list of random numbers. The list of numbers is derived by running an experiment designed to generate a random number, writing it down, and then repeating the experiment. This list is then read into the computer to be used as data for the problem at hand (Pritsker:716). The problem with this method is the amount of memory taken by the list of random numbers, and the additional time it would take to retrieve a number from the computer's memory (Pritsker:716; Sobol:26).

An example of a random number generator would be "to employ a physical device such as a vacuum tube which generates random noise" (Pritsker:716). This would operate

by counting the number of times the noise generated in the vacuum tube exceeded a predetermined threshold over a specified period of time. If the number counted was even, a one would be assigned, whereas if the number counted was odd, a zero would be recorded (Sobol:26). A register in the computer' memory would be designated to receive this collection of zeros and ones to provide a binary result for use when a random number is needed. The problem with this method is the results would not be reproducible, therefore model verification and controlled experimentation would be virtually impossible (Pritsker:716; Sobol:27).

The third, and most widely accepted method of generating random numbers is the method of pseudo-random number. Pseudo-random numbers are calculated by means of some formula that simulates the values of a random variable. Pritsker states that the preferred method of generating pseudo random numbers "is to employ a recursive equation which generates the (i + 1)th random number from previous random numbers. Since the sequence of numbers is produced deterministically by an equation, they are not truly random" (Pritsker:717).

Pritsker then lists six properties that are desireable in a pseudo random number generator, which are as follows:

- 1. The numbers should be uniformly distributed in the interval (0,1).
- 2. The numbers should be independent and, hence, no

correlation should exist in a sequence of random numbers.

3. Many numbers should be generated before the same number is obtained. This is referred to as the period or cycle length of the generator.

4. A random number sequence should be reproducible. This implies that different starting values or seeds should be permitted to allow different sequences or stream to be generated.

5. The generator should be fast, as many numbers may be required in a simulation.

6. A low storage requirement is preferred.

General Sampling Techniques

There are many different techniques to generate random samples. "Pritsker surveyed over 300 sources, which he compiled into the following fundamental approaches for random sample generation" (Pritsker:707):

- 1. Inverse Transformation
- 2. Composition
- 3. Acceptance/Rejection

(All three of these methods are commonly found in the literature.) "The uniform samples derived from these three approaches provide the basic source of randomness in simulation experiments" (Pritsker:707).

Inverse Transformation The inverse transformation method is the simplest and most fundamental technique for generating random samples (Pritsker:708). This method is performed by setting a random number, r, equal to the cumulative density function (cdf), F(x), and then solving for x. An example of this technique using the exponential

cdf, is as follows (where 1/lambda is the mean of the exponential distribution):

$$F(x) = 1 - e$$

Setting F(x) equal to r and then solving for x yields,

$$\dot{x} = -(1/lambda) * ln(1 - r)$$

Hence, if r is uniformly distributed in the range 0 to 1, then x given by the above equation is exponentially distributed with a mean value of 1/lambda. (Pritsker:708)

The problem with this technique is that the cdf in question may not be invertible (Pritsker:709). Therefore this method is not applicable for some commonly used distributions (like the beta distribution).

Composition "The composition method assumes the density function can be written as a weighted sum of component distribution functions with the sum of the weights totaling one" (Pritsker:710). A sample from one of the component distributions must first be taken. This procedure is repeated until a sample from each of the component distributions has been gotten. These samples are then summed in accordance with their respective weighting factors to create one random variable.

<u>Acceptance/Rejection</u> "The acceptance/rejection approach to generating random samples involves generating samples from a distribution and then rejecting some of the samples

in a way that the remaining samples have the desired distribution" (Pritsker:709). The process begins with the generation of two random numbers. "One random number is used to calculate a proposed random sample, x" (Pritsker:709). Let f(x) be the density function from which random deviates are required — this is where the sample value is inserted (Pritsker:709; Tadikamalla:925). "The key is to find a different function, t(x), whose value returned for a given zero-one number is always larger than the function f(x) at the same point" (Sumner:15). The majorizing function, t(x), must be easy to sample from. The second random number is drawn from a uniform distribution along the (0,1) interval (known as a uniform variate).

If the uniform variate is less than the ratio of the majorizing function value over the pdf value (ie, if U < t(x)/f(x)), then x is accepted as a random variate of the function, f(x) (Tadikamalla:926). Otherwise, x is rejected and the process must be repeated by selecting two new random numbers. As the majorizing function gets closer to the desired function, less values of x are rejected. Therefore the goal of this method is to find a t(x) function as close to the pdf as possible to minimize the amount of work required to generate the desired random numbers.

Summary

Life cycle costing is usually conducted in one or more of

three different models. Estimating by analogy is generally considered the easiest of the three because it requires the least amount of detail. Parametric modeling involves more work than an analogy estimate due to the addition of performance and/or physical characteristics into the CER's. Engineering or bottom up estimates require a great deal of detail and are generally not recommended by the DoD. The key to good LCC estimates is to start them as early in the program's conceptual phase as possible. This allows management to receive a quick and easy overview of what is to be expected while also allowing changes to be made in a simplistic fashion.

The generation of random numbers for work on a digital computer is conducted in one of three ways: by random number tables, by random number generators, or by pseudo random number generation. The preferred method is pseudo random number generation because the results can be replicated and this is the fastest of the three methodologies.

The three most common sampling techniques to produce random samples are the inverse transformation method, the composition method, and the acceptance/rejection method.

These methods do not have to be used independently. In most cases, they are combined to ensure the desired sample is achieved.

III. Methodology

<u>Overview</u>

The purpose of this chapter is to acquaint the reader with the general methods used to meet the objective and some of the subobjectives stated in the first chapter (the subobjectives not covered in this chapter will be addressed in Chapter IV). Additionally, the reader will also be acquainted with the two distributions made available in the program LCC.FOR (the Beta and Triangular distributions), and the methodology used to validate and verify the program.

Cost Estimating Relationships

As stated in the literature review, there are three types of LCC models -- of which the parametric relationship or CER was selected to be used by the program LCC.FOR. The CER was chosen because it allows the user to predict the future based upon information received from past occurrences (MECA:79). (An illustration of a CER was shown in Figure 1.)

For a CER to be effective, the variables used to estimate the cost of a future weapon system must have characteristics similar to those of some existing or previously existing system. For example, the future cost of the booster stages to be used in the small intercontinental ballistic missile

(ICBM) may be based upon the costs associated with the boosters used on the Minuteman III or Peacekeeper ICBM weapon system. Because of the close similarities in booster technology, the characteristics demonstrated by existing rocket stages can be used to forecast the cost of future boosters.

A counter example where using an older system may not be practical is the reentry vehicles used on the Minuteman III ICBM versus those used on the Peacekeeper weapon system.

The reentry vehicles used on the Minuteman III are the MK-12 and the MK-12A, where the MK-21 is the reentry vehicle used on the Peacekeeper missile. The technological differences between the MK-12/MK-12A and the MK-21 make cost comparisons between the two inadvisable. The MK-12/MK-12A is comprised of vacuum tube electronics -- the MK-21 is entirely solid state. The MK-12/MK-12A conducts a single radar update to determine its location above the earth when reentering the earth's atmosphere -- the MK-21 makes four. Because of these and other significant differences, the MK-12/MK-12A would not represent an acceptable forecasting model to determine the cost of the MK-21.

A CER consists of two types of terms, explanatory variables and beta parameter estimates. The explanatory variables are the Xi terms where the parameter estimates are represented by bi or (beta)i.

In the program LCC.FOR, the explanatory variables are referred to as cost drivers. A person using the program LCC.FOR can assign each Xi to either a constant or to a range of values based upon some form of either the beta or triangular distribution. This is done because sometimes the value of an explanatory variable is known for certain, while at other times the exact value of an explanatory variable is only known to exist within a range of numbers. For example, suppose a CER consists of two cost drivers, X1 and X2. The value of X1 is regarded as a constant equal to 100 units, but the value of X2 can take on any value between 100 and 250 units. The program LCC.FOR needs to know how to assign a value to X2. This is where the beta and triangular distributions come into play.

Beta and Triangular Distributions

Continuing with the example above, an analyst is not likely to know what value to assign the cost driver X2. The expert who builds component X2 is not likely to know the distribution X2 would be best represented by. Together, the analyst can ask the expert a series of questions to determine an educated guess as to the actual value of X2.

The questions needed to be asked by the analyst are:

- 1. What is the minimum value X2 can attain?
- What is the maximum value X2 can attain?
- 3. How is X2 likely to be distributed?

An expert would be expected to know the approximate minimum and maximum values in answering the first two question. But the response to question number three will probably be a blank stare. However, the clever analyst can rephrase question number three to get the needed information — aided by either the beta or triangular distributions.

Beta Distribution The beta distribution was incorporated into the computer program LCC.FOR because it allows a user to generate a rough model with little or no data.

Additionally, "since the beta distribution is defined over a finite interval, it is extremely useful in describing situations which have a finite range" (Pritsker:705). The finite range is explained by the minimum and maximum values provided by the expert. Figure 2 displays nine 'types' of beta distributions (taken from Sumner's thesis). The Beta distribution was reduced to nine pdf's because they represent the input options in the program LCC.FOR. By showing these nine pdf's to the expert, an analyst would be able to get an accurate assessment of how X2 is actually represented.

As shown in Figure 2, the nine beta pdf's give a general account of how a component could be best described. Beta distributions of 'type' 1, 4, and 7 are all skewed left. This means a sample from one of these pdf's is more likely to be closer to the high estimate than to the low estimate.




Figure 2 Nine Beta Distributions

The difference between these three 'types' is the amount of variability contained in each of them. For the analyst trying to explain these nine beta distributions to the expert, the analyst could ask the expert if he would expect the actual value of the cost driver to be closer to the low or high estimate he provided earlier. If the expert feels strongly that the actual cost driver would be more likely to be nearer the high estimate than the low, a beta

distribution of 'type' 7 would be assigned to it. If the diagram of the nine beta pdf's is not available, or if the expert is not comprehending the information being explained to him -- the triangular distribution becomes a viable alternative.

Triangular Distribution The triangular distribution operates much like the beta except instead of requiring a 'typa', the triangular pdf needs a mode or best guess estimate. The triangular distribution was also incorporated into the computer program because it has the same advantages as those mentioned for the beta distribution — it also allows a user to generate a rough model in the absence of data. One additional advantage of the triangular distribution is it is more intuitive to those without a background in statistics. No diagrams of nine distributions is required in trying to get information from a non-statistician regarding how a cost driver is likely to be distributed. The only information needed from the expert in this case is:

- 1. What is the minimum value X2 can attain?
- 2. What is the maximum value X2 can attain?
- 3. What is the mode or best guess of the value X2 is likely to be?

This eliminates any possible confusion that may arise in trying to explain the concept of 'variance' to a person not

familiar with statistics. However, the estimation of the variance is the main drawback to the use of the triangular distribution. With only the minimum, maximum, and mode values provided, estimation of the variance produces meaningless results.

Software Verification and Validation

"The software verification and validation processes are concerned with evaluating the performance of a model" (Pritsker:12). In this case, the model is the program LCC.FOR. "Verification means the computer program functions as intended, where validation checks to see if the program is a reasonable representation of the system it was designed to emulate" (Pritsker: 12-13). The verification and validation stages were conducted through the use of a test run (provided by Dr Cain and Capt Gibson) consisting of eight cost elements. The algorithms contained in the program's code were compared against the same calculations made by hand. This was done to verify the program LCC.FOR was performing as expected -- both at the nuts and bolts level and the system as a whole. The validation process involved taking the expected value of each of the eight cost elements as they were distributed over time (refer to Table 2 in Chapter IV). The values of the eight cost elements were then placed in the program LCC.FOR to validate that the program yields an accurate assessment of calculating life

cycle cost estimates. It is important to understand that the validation that took place validated a model -- validation of the real world may or may not have been shown. The point here is each cost element is an approximation of the value of some entity -- the entities themselves may not have been an accurate assessment of the real world. However, the program did validate the models presented.

IV. Implementation

Overview

This chapter describes how the subobjectives mentioned in Chapter I were implemented. Specifically, the subobjectives mentioned in this chapter are: 1. how the data input procedures in the program LCC.FOR were modified, 2. detailed results of the varification and validation procedures, 3. instructions regarding how the program LCC.FOR could be modified to meet the individual needs of a user, and 4. the outcomes of the tests conducted to determine if only 250 random samples per cost element and cost driver needed to be obtained versus the current process of getting 750 random variables.

Data Input Modification

The program originally designed to estimate life cycle costs consisted of an impersonal, unforgiving, and tedious method or entering data. The 'old' process was made up of executable code (LCC.EXE) and one external file containing the data (INPUTLCC.DAT). The data file required the user to place the values to be entered in precise positions within the file. No interaction between the main program and user ever took place. If data was improperly aligned, a run time error would occur. This run time error was difficult to

debug because of the large amount of information contained in the data file. Another hinderance in debugging was that there were no messages or labels explaining what the data within the file represented. If data was incorrectly entered, or if a change to one or more values was desired, the user had to physically enter the file INPUTLCC.DAT to make the necessary changes.

The solution to making the 'old' program more personal, more forgiving, and "user friendly" was accomplished as follows: 1. provide the user with prompts from the main program asking for each data point, 2. incorporate checks on the data to ensure the inputs were within an acceptable range, 3. provide the user with an echo check, meaning allow the user to see what she had just entered (so she could be certain the data set contained the intended values), and 4. ask the user if any changes to the data set would be necessary (and the means to correct them), while at the same time keeping the storage locations of the data invisible to the user.

Step one involved asking the user questions regarding each data point to be entered. The user's responses would then be sent to one of two files external to the main program depending on the form of the model being entered (the form of the model refers to either a constant, beta or triangular random variable, or a CER cost element). All

information was stored in the file INPUTLCC.DAT except for some data relating to CER's. Information about the estimated variance of the CER, the covariability of the cost drivers incorporated within the CER, the slope parameters, and the description of how each cost driver was distributed was stored in the file MOREINPT.DAT. This separate file was necessary to simplify data transfers and to eliminate the extra computer code necessary to account for the entering and editing of the data.

The three types of models handled by this program are:

- 1. constants,
- random variables from either a beta or triangular distribution,
- 3. random variables generated by a CER.

The level of complexity increases from constant data to CER information. This means the amount of information required for a CER is greater than for a beta or triangular random variable, which in turn requires more information than a constant cost element. All of the information needed to evaluate the first two models is contained in the file INPUTLCC.DAT, as is most of the CER information. The problem with placing all the CER data into the INPUTLCC.DAT file is: 1) no restriction is placed on the user regarding the order of the models to be input (meaning a constant cost element may be entered before a CER and visa-versa), and 2)

additional bookkeeping procedures would have to be incorporated into the program to maintain the proper placement of data being entered/edited.

The easiest way to approach this was to use the information already provided by the main program.

Methodologies already existed within the main program to keep track of data storage. The only change necessary was to modify where the data was being sent. This meant changing file numbers, opposed to developing numerical algorithms and pointers to keep track of data locations.

The second part of the solution involved checking the user's inputs to ensure they were within an acceptable range. For example, many queries presented by the program are in the form of YES/NO questions requiring either a '1' or '2' as a response. If the user entered a value less than '1' or greater than '2', the computer would catch this mistake and ask the user to reenter their response, thus preventing the program from encountering a run time error.

The echo checks in the program occur in one of two places. One echo check takes place immediately after the CER data to be sent to the file MOREINPT.DAT has been entered. The second check occurs after all of the data has been input. The location of the first echo check coincides with why the second data file exists -- for ease and expedition. Also, the availability for corrections to be

made to these inputs only occurs here because this type of data is generally not updated once correctly entered. The second echo check is made available to the user when the program is rerun (refer to the User's Manual located in Appendix A for more information).

The fourth solution ties in closely with the third. Immediately following each echo check, the program asks the user if any changes need to be made. If no corrections are required, the program either continues asking for the remainder of the data set to be entered or begins calculating the LCC of the system. If changes are necessary, the program will ask the user how many changes need to be made. A positive integer response is then followed with queries (equal to the number of changes required), for the index number along the left hand column associated with the value to be updated. For example, assume the user has just entered the estimated variance, variance-covariance matrix, slope parameters, and cost driver cards of a CER consisting of three slope parameters (refer to the User's Manual located in Appendix A for details on how and when these variables are entered). echo check provided upon completion of entering these values is shown in Table 2. The program then asks:

Do you want to edit any of these?
Enter:
1 for YES
2 for NO

If a '2' is entered, the program either continues the data acceptance process or begins calculating the LCC of the system. If a '1' is submitted, the program responds with,

How many values would you like to edit? (Enter 0 to exit)

If the user did not want to make any corrections but mistakenly entered a '1' instead of a '2', she can still exit this procedure by entering a '0'. If however, one correction needs to be administered, the user would enter a '1'. The program then asks the user:

Enter the # of the value to be
changed (from the left hand column)

Notice the number on the far left of each value entered (see Table 2). This number is what the program is asking the user to enter to represent the value to be changed. Continuing with this example, say the element varcov (2,1) needs to be changed to 0.55. The user would respond by entering the number in the left hand column associated with varcov (2,1) -- in this case a '5'. The program would then state:

Enter the NEW VARCOV(2,1):

This is where the user would enter the new value for the variance-covariance element (2,1) (by typing .55 or 0.55

then pressing RETURN).

Software Verification and Validation

<u>Verification</u> The verification process was conducted by evaluating whether the following aspects of the program LCC.FOR performed as intended: 1. the error check subroutine ANS, 2. the editing procedures located at both echo checks, and 3. the performance of the subroutines designed to calculate the triangular distribution.

The subroutine ANS was tested while executing the program LCC.FOR. Queries such as, "Enter: 1 for YES, 2 for NO" were responded with numeric values outside of the expected range of '1' to '2'. In every instance the program returned with the statement, "Please enter a number from 1 to 2". Also, the range specified in this second query was appropriate to the data required to be entered.

The editing procedure following the two echo checks was initiated per the instructions provided in the User's Manual (located in Appendix A). Verification that updates incorporated into the database were properly executed were found in two locations. First, if the update made was significant, a noticeable change in the values displayed in the output analysis (refer to Step 24 of the User's Manual) became evident. The second and usually more apparent location occurred when the program was rerun. Selecting the option to review the database verified the new value had

ECHO CHECK EXAMPLE OF CER DATA CONSISTING OF 3 SLOPE PARAMETERS (NO INTERCEPT TERM)

TABLE 2

```
1. variance (s-squared) = 0.99
2. varcov(1,1) =
                  0.1
3. varcov(1,2) =
                  0.2
4. varcov(1,3) =
                  0.3
5. varcov(2,1) =
                  0.4
6. varcov(2,2) =
                  0.5
7. varcov(2,3) =
                  0.6
8. varcov(3,1) =
                  0.7
9. varcov(3,2) = 0.8
10. varcov(3,3) = 0.9
Press RETURN to continue . . .
11. slope param 1 = 1.1
12. slope param 2 = 2.2
13. slope param 3 = 3.3
Cost Driver for Element # 1
14. LOW value = 1
15. HIGH value = 1
16. Beta TYPE = 1
Cost Driver for Element # 2
17. LOW value = 25
18. HIGH value = 45
19. Beta TYPE = 7
Cost Driver for Element # 3
20. LOW value = 50
21. HIGH value = 50
22. Beta TYPE = 1
```

been accepted by the presence of the new value in the listing (like the one shown in Table 2).

The subroutines TRIAG and TRIAG1 were designed to generate random variables from the triangular distribution.

Each subroutine receives the low, high, and mode values necessary to calculate the triangular distribution from the calling portion of the program. First, the subroutine generates random numbers from the (0,1) uniform distribution. These random numbers are then transformed into values representative of the triangular distribution. Before the transformation can occur however, the "break" point must be determined. The "break" point represents the mode value of the triangular distribution. This value must be obtained because different equations are used depending on whether the random number generated is less or greater than the "break" point.

Proper execution of this subroutine was verified by first comparing the "break" point calculated by the program against a hand calculation of the same value. Once it was established these values matched, the next step was to print out the value of the random number generated and ensure the proper equation was used to produce the triangular distribution estimate. In other words, if the random number generated was greater than the "break" point, the equation designed to calculate this set of circumstances must be selected. Print statements were inserted into the program signifying if the greater than or less than path had been chosen. The subroutine was verified to be functioning properly because each time the random number was

greater/less than the "break" point, the appropriate message was issued.

Validation A test case involving the life cycle cost of a weapon system consisting of eight components was used in attempting to validate the accuracy of the overall program LCC.EXE. The eight components were comprised of two constants, three random variables from the beta distribution, and three random variables generated by CER's. The make-up of the eight components and their hand generated expected life cycle costs are shown in Table 3.

The eight cost elements presented in Table 3 were calculated against a discount rate (annual percentage rate or interest) of 10%. Additionally, each cost element has an individual payment schedule associated with it. The discount rate converts each payment schedule into a present value -- how much it would cost today to pay for the cost element if the payment was a lump sum.

The expected life cycle costs of the two constants were calculated by simply spreading the cost associated with each cost element over their respective payment schedules. The algorithm used in assigning a dollar value to a particular year within each payment schedule was taken from the computer code generated by Dr Cain. This algorithm is located in the subroutine TRAP contained in the program LCC.FOR (refer to Appendix C).

The expected life cycle costs of the cost elements generated by beta random variables were attained in the following manner: 1. refer to the subroutine BETA (located in LCC.FOR) and go to the section of the IF-THEN loop corresponding to the beta 'type' applicable to each cost element, 2. set the PIN and QIN values associated with the beta 'type' in question equal to alpha and beta, respectively, and 3. calculate the expected value using the equation (taken from class notes provided by Dr Cain);

For example, the expected life cycle cost of cost element #4 (refer to Table 3) was generated as follows:

EV (ce #4) =
$$900K + (2500K - 900K)*(5.5 + 1)/(5.5 + 2.5 + 2)$$

= $900K + 1600K * 0.65$

EV (ce
$$\#4$$
) = 1,940,000.00

Each expected value generated for cost elements 3, 4, and 5 was then subjected to the cost per year algorithm mentioned in the discussion regarding the constant cost elements (for details, refer to the subroutine TkAP contained in the program LCC.FOR).

The expected life cycle costs of the CER's was conducted using the same tools shown in the constant and beta random variable sections, but these tools were applied to different

aspects of the CER's. In each CER shown in Table 3, at least one explanatory variable was not known for certain. This meant the expected value of those explanatory variables had to first be determined. For example, the explanatory variable X2 located in the eighth cost element was distributed by a 'type' 4 beta distribution over a range of 2500 to 6000 units. The algorithm mentioned above was used to calculate the expected value of X2 (see below).

EV (X2) =
$$2500 + (6000 - 2500)*(4 + 1)/(4 + 2 + 2)$$

= 4687.5

Cost elements 6 and 7 represent learning curves (meaning the average cost of each unit decreases as the number of units purchased increases). After determining the expected value of each explanatory variable and taking the inverse natural logarithm of the two equations, this result equalled the expected average cost of purchasing one unit of each respective cost element (AC). Both cost element 6 and cost element 7 required a total buy of 200 units. Thus, the average cost of cost elements 6 and 7 had to be multiplied by 200 to obtain their respective expected life cycle cost.

The same data shown in Table 3 was then put into the computer program LCC.FOR. A total of thirty runs of this data set were generated. Thirty was selected to ensure a reasonable estimate could be established, and because thirty is generally accepted as a significant sample size.

TABLE 3

HAND GENERATED EXPECTED LIFE CYCLE COST OF A WEAPON SYSTEM CONSISTING OF EIGHT COMPONENTS

| Cost | | Dollar | Payment | Year | Expected |
|---------|-------|----------------------------|---------|----------|---------------|
| Element | Type | Value | Plan | Realized | LCC (c) |
| 1 | 1 (a) | 150000 | 2 (b) | 2 (b) | 105013.32 |
| 2 | 1 | 800000 | 5 | 1 | 518393.50 |
| 3 | 2 | B:100000 to 300000:2 (d) | 9 | 1 | 112679.88 |
| 4 | 2 | B:90000:2 (d) 2500000:7 | 22 | 5 | 439264.37 |
| 5 | 2 | B:2500000 to | 24 | 6 | 885432.91 |
| 6 | 3 | (e) | 7 | 4 | 470850.93 |
| 7 | 3 | (f) | 17 | 5 | 1211617180.00 |
| 8 | 3 | (g) | 19 | 0 | 4646076.99 |

Notes:

- (a) The coding for Type is:
 - 1 = constant
 - 2 = random variable (beta or triangular pdf)
 - 3 = random variable generated by a CER
- (b) Component's life cycle (in years).
- (c) The expected cost of the respective component.
- (d) For components of Type 2, this symbology represents: B or T (for either the Beta or Triangular pdf): the LOW value to the HIGH value: the type of Beta distribution or the MODE of the Triangular distribution.
- (e) This cost element is generated by the CER (requiring a total buy of 200 units):

ln(AC) = 9.239961 - .321775*ln(X1) + .189285*ln(X2)where, AC = average cost per unit,

Expected value of X1 = 95, X2 = 50

- (f) This cost element is generated by the CER (requiring a total buy of 200 units):
- ln(AC) = 16.81124283 .32*ln(X1) + .15*ln(X2) + .212*ln(X3)where, AC = average cost per unit,

Expected value of X1 = 95, X2 = 101, X3 = 68.33

- (g) This cost element is generated by the CER:
- LC = 10000837 + 201.0509491*X1 + 149.3534241*X2

where, LCC = life cycle cost

Expected value of X1 = 3000, X2 = 4687.5

Each run was independent of the others because the seeds used during each run were changed (the seeds chosen in each run were based on the computer's clock).

The results of the hand and computer generated expected life cycle costs of a weapon system consisting of eight components are:

HAND CALCULATION = \$1,218,794,892.00 COMPUTER CALCULATION = 968,354,333.33

Each computer run generated 750 estimates of the given weapon system's life cycle cost. The output provided by the computer runs was listed in percentile increments. Since the hand calculations were based upon the expected value of the data, the 50th percentile was taken from the thirty computer generated calculations.

The variance of the hand calculation was not obtained, however the variance of the thirty computer runs was.

Assuming the data from the thirty runs was normally distributed, a confidence interval was placed around the computer calculation. Using an alpha value of 0.1, the t-value equals 1.699 (taken from a standard t-table where alpha = 0.05 with 29 degrees of freedom). The 90% confidence interval is presented below.

968354333.33 +/- t(1 - alpha/2)*(stdev/(square root of N) 968354333.33 +/- 1.699*(5432038.228/(square root of 30) 968,173,265.4 < Computer calculation < 986,535,401.2 The confidence interval placed around the computer calculation does not contain the hand generated value. This infers the hand generated calculation is not equal to the computer generated calculation -- hence the program LCC.FOR may not be doing what it was intended to do. An error in selecting the 50% may be the reason for the discrepancy -- the hand calculation was best approximated by the 95% in the output analysis of each computer run.

Another possibility for the difference is the manner in which the computer calculates the CER estimates. The program LCC.FOR uses the normal distribution to evaluate the expression:

$$y = bo + b1*X1 + b2*X2 +/- N(0,1)*(s-sqrd + X'(varcov)X)$$

where N(0,1) represents the normal distribution with a mean of zero and variance of one. The actual value that should have been used is the t distribution. The normal distribution was used because it is much simpler to generate—one line of code completes the task. The use of the normal opposed to the t is a valid technique if the degrees of freedom are 30 or more. If the degrees of freedom are small (as in the example shown in Table 3), use of the normal distribution—an grossly underestimate predictions.

This may have been the case with the computer calculation provided earlier. Notice it is significantly less than the

hand generated calculation -- possibly due to the use of the normal distribution instead of the t distribution.

Random Variable Sampling Reduction

The number of samples generated by the program LCC.FOR is currently 750. A test was conducted to determine if this number could be reduced without losing information. If no information was lost then the benefit of less samples being taken is in the compilation time saved by the computer. The actual amount of calculations saved is not simply, 750 - 250 = 500. In most cases, the number of samples taken exceeds 5000. Therefore, if the 750 could be reduced to 250, the amount of work not having to be accomplished by the computer would be substantial.

The data used in this experiment was the one mentioned earlier containing eight cost elements (refer back to Table 3). Since two of the cost elements represent learning curves, Dr Cain suggested running this experiment at a variety of purchase values. This was accommodated by running tests where the number purchased by the learning curves were set at 95, 125, 150, 175, and 200 units. Each purchase value was run 30 times at 750 samples, 30 times at 500 samples, and 30 times at 250 samples, for a total number of runs equalling 450. Each run was independent from all the others because the seeds used were changed. The output generated after each run was presented in percentile form —

meaning the maximum value was listed, then the value representing 99 percent of the LCC estimates, then 95%, etc, down to the minimum value attained for that particular run. Dr Cain suggested testing the 95th percentile -- which was done along with the minimum and maximum values.

The test was broken into three sections; testing to determine if the data was normally distributed, comparing the mean value of the thirty runs, and comparing the variance of the thirty runs.

Normality Test The Wilk-Shapiro test was conducted on each set of thirty data points to determine if they were normally distributed. The assumptions made for these tests were: 1. the data samples were acquired randomly and 2. the data sets are independent from each other. The hypothesis for each test was:

Ho: data set 1/data set 2 is a normal distribution function with unspecified mean and varianceHa: data set 1/data set 2 is nonnormal

The decision rule used for these tests was: Fail to accept Ho if the Wilk-Shapiro statistic was less than the 0.05 quantile.

Results: Every test for normality passed the decision rule except for the following:

| NUMBER SAMPLES | NUMBER PURCHASED | MIN, MAX OR 95% | WS <u>CALCULATED</u> | WS TABULAR |
|-------------------|---------------------|--------------------|-------------------------|---------------|
| 500 | 200 | MAX | 0.9034 | 0.927 |
| 250 | 150 | 95% | 0.9133 | 0.927 |
| 750 | 125 | 95% | 0.9023 | 0.927 |

Although these three tests did not meet the WS statistic, their result was close enough to be waived.

Comparison of Means The means of each run conducted at 250 and 500 samples was compared against the corresponding run done at 750 samples. The hypothesis test used for these tests was:

Ho: mean (data set 750) = mean (data set 250) or mean (data set 500)

Ha: mean (data set 750) <> mean (data set 250) or mean (data set 500)

The decision rule used was: Fail to accept Ho if the absolute value of the calculated t-statistic was greater than the t-statistic obtained from a table. The tabular t value was obtained at alpha = 0.01 with 58 degrees of freedom.

Results: Every test passed the decision rule. In fact, no test failed at an alpha = 0.1 and only one of the 30 tests failed at an alpha level of 0.2.

<u>Comparison of Variances</u> The hypothesis used in evaluating these tests was:

Ho: var (data set 750) = var (data set 250) or var (data set 500) Ha: var (data set 750) <> var (data set 250) or var (data set 500)

The decision rule used to determine which hypothesis should be selected was: Using the F-distribution, if the ratio of the sample variances falls between the range of F(alpha/2,nl-1,n2-1) and F(1-alpha/2,nl-1,n2-1), for alpha = 0.01 and nl = n2 = 30, fail to reject Ho.

Results: all of the tests passed the decision rule except:

- 1. 250 vs 750 samples with 175 components purchased at the 95% level -- the lower bound was exceeded by 0.0274.
- 2. 250 vs 750 samples with 150 components purchased at the 95% level -- the lower bound was exceeded by 0.2102.
- 3. 250 vs 750 samples with 95 components purchased at the 95% level -- the lower bound was exceeded by 0.1100.

Based upon the results of these tests, it was concluded a sample size of 250 random samples yields similar results as a sample size of 750 (ie, little or no information is lost by decreasing the number of random samples from 750 to 250). Program Modification

The program LCC.FOR is currently configured with the following format:

- 750 LCC samples are acquired,
- 2. The maximum number of cost elements that can be entered is 20.

If these parameters are not sufficient, changes can be made by making the following changes in the LCC.FOR computer code.

To modify the number of LCC samples taken, the following changes must be made:

| LOCATION | LINE_# | VARIABLE NEEDING ADJUSTMENT |
|-------------------|--------|--------------------------------|
| Main Program | 7 | A(*,20), LC(*) |
| Main Program | 8 | XCER(*,20) |
| Main Program | 12 | NRV/*/ |
| Subroutine TRIAG | 19 | NR = * |
| Subroutine TRIAG1 | 5 | NR = * |
| Subroutine BETA | 6 | NR = * |
| Subroutine CER | 7 | NRR = * |
| Subroutine BETA1 | 5 | NR = * |

The line # refers to the line number of the respective routine given under the location heading. Replace the value located where the * is with the number of runs desired.

CAUTION: If the number of runs is to be reduced, reduction has only been verified down to 250. Any value inserted less than 250 may not yield statistically acceptable results.

If the number of cost elements needs modification, the following changes must be made:

| LOCATION | LINE_# | VARIABLE NEEDING <u>ADJUSTMENT</u> | |
|--|--------------|--|--|
| Main Program Subroutine TRAP Subroutine TRAP | 7 7 11 | A(750,*), CE(*,20) CE(*,20) MCON(*,100), MRAND(*,100) | |

The line # refers to the line number of the respective routine given under the location heading. Replace the value located where the * is with the number of cost elements desired.

V. CONCLUSIONS AND RECOMMENDATIONS

GOAL REALIZATION

The purpose of this effort was to enhance Dr Cain's computer simulation for the forecasting of life cycle costs. This was attained. The program LCC.FOR is easy to use and provides quick, accurate estimates of weapon system costs. The addition of the triangular distribution allows those without a solid understanding of distributions, variance in data, and statistics in general the opportunity to comprehend their inputs.

RECOMMENDATIONS FOR FUTURE RESEARCH

Random Variable Sampling Reduction The minimum number of random samples generated by the program LCC.FOR while maintaining statistical integrity is 250. This number can be reduced -- but how far? A reduction is still possible due to the strength shown in the tests done in comparing the means and variances.

A test that could be conducted concerning this topic would be to determine the optimal number of random samples to be acquired for a given set of cost elements. The first item to be checked would be to find the "actual" value of a predetermined quantile. For example, run the same data as entered in Table 3, but let the number of random samples be increased to some large value, say 10,000. This will allow the output to "zero in" on the actual values for the given

data set. •

Once the "actual" values are known, a confidence interval could be placed around them. The test would be to reduce the number of random samples taken until the established confidence interval is violated. When the confidence interval is violated, it would be known with certainty that at least that many random samples would have to be taken to ensure statistical integrity is maintained. The procedure would be repeated with various amounts of cost elements to establish the minimum number of random samples to be acquired for each.

Validation Check The analysis regarding the hand and computer generated expected life cycle costs revealed a discrepancy. Was this caused by user error (where the user is this author), using the normal distribution instead of the t distribution, or is there a flaw somewhere in the software? The answer to this is important so that future projects using this program will be as accurate as possible.

APPENDIX 1: USER'S MANUAL

Step 1: Log into the CSC.

Step 2: Copy LCC. EXE and ANAL. SAS from Dr Cain's userid.

Step 3: Create the files INPUTLCC.DAT, MOREINPT.DAT, and LCCOST.DAT. This is done by typing (at the \$ prompt):

\$ CREATE LCCOST.DAT <RETURN>

The system will not respond with any prompt. Pressing <Control 'Z'> at this time creates the file LCCOST.DAT;1 in the user's directory. Repeat this process for the other two files (INPUTLCC.DAT and MOREINPT.DAT).

Step 4: Type (at the \$ prompt) 'RUN LCC.EXE <RETURN>'.
This executes the file LCC which is designed to calculate
the life cycle cost of a weapons system.

<u>Step 5:</u> At this point, a series of questions will be asked by the program LCC requesting the user to provide <u>numerical</u> responses.

WARNING: ALL RESPONSES TO QUERIES FROM THE PROGRAM LCC MUST BE IN NUMERICAL FORM -- EVEN TO ANSWER 'YES/NO' QUESTIONS.

For example, once a data set has been entered and the user wants to make a change to the data on the next run, the program will ask the user:

Do you wish to edit the data? Enter:

1 FOR YES

2 for NO

If a 'Y' or 'N' is entered (or any combination of letters), the program will encounter a run time error. The program will stop functioning at this point because only a numeric response is expected. However, if a letter response is entered and the program to aborts, go back to Step 4.

The user should not be concerned with entering a number outside of the specified range (a 1 or 2 in this example). If the range of possible values is exceeded, the computer will repeat its question until an appropriate value is entered. Continuing with this example, if a '3' were entered, the program would respond with:

Please enter a number from 1 to 2

This process would continue until a '1' or '2' was entered by the user.

Step 6: The first question asked by the program is:

Do you wish to access:

1. the last data set entered, or

2. begin a new data set?

Enter a 1 or 2

If the user has never executed this program before, no 'last data set' exists, therefore option 'l' is not feasible (yet). In this case the user would enter a '2' and press <RETURN> and proceed to Step 7.

For information regarding what to do if the last data set needs to be edited, go to Step 20.

Step 7: This step and those immediately following mean the user is going to enter a new data set. The first question asked in entering the new data set is:

Enter the number of cost elements:

The user should respond with an integer value from 1 to 20 (the program can only handle a maximum of 20 cost elements as presently configured -- refer to page xx of Capt Gibson's thesis "An Interactive Life Cycle Cost Forecasting Tool", if configuration changes need to be conducted). This value represents the number of cost elements that make up the weapon system.

- <u>Step 8:</u> The program then asks the user to enter the life expectancy of the weapon system (in years). This is an integer value representing 1 to 100 years.
- Step 9: The discount rate the weapon system is to be evaluated against is the third query in this section. If the discount rate is 9.5%, enter either 0.095 or .095 (the zero preceding the decimal point may be omitted).
- <u>Step 10:</u> Step 10 is an iterative process. The number of times it is repeated is equal to the number of cost elements to be entered. The program wants to know what 'type' each cost element is. A cost element can be one of three 'types':

- a constant or "fixed value" which is assumed to be certain,
- a random variable modeled by either a Beta or Triangular probability density function (pdf), or
- 3. a random variable generated by a cost estimating relationship (CER).

If the cost element is a constant, enter a '1' (go to Step 11 for further directions).

If the cost element is a random variable to be modeled by either a Beta or Triangular pdf, enter a '2' (go to Step 12).

If the cost element is a random variable generated by a CER, enter a '3' and proceed to Step 13.

<u>Step 11:</u> Enter the constant cost of the element. For example, if the cost is \$25,000, enter 25000. (Go to Step 14.)

Step 12: The first question asked is if this cost element is to be modeled by a Beta or Triangular pdf. If a Beta pdf is desired, enter a '1' and proceed to Step 12a. If the Triangular pdf is desired, enter a '2' and proceed to Step 12b. (Detailed information regarding the Beta and Triangular distributions along with why they were chosen for this program is located on pages 21 to 25 of Capt Gibson's thesis.)

Step 12a: The next three queries regard the LOW value of the Beta distribution, the HIGH value, and the TYPE of Beta distribution to be modeled. For example, if the LOW, HIGH, and TYPE are:

LOW = \$10,000HIGH = \$30,000

TYPE = 4 (medium variance with higher probability of values occurring closer to the HIGH end (\$30,000) -- refer to Figure 2 in Capt Gibson's thesis for a description of the nine TYPE's of Beta distributions)

The responses to the computer's queries would be:

10000 (for LOW)
30000 (for HIGH)
4 (for TYPE -- this must be an integer from 1 to 9)

When these three values have been entered, proceed to Step

Step 12b: The next three queries regard the LOW value of the Triangular distribution, the HIGH value, and the MODE or best guess of the Triangular distribution to be modeled. For example, if the LOW, HIGH, and MODE are:

LOW = \$10,000HIGH = \$30,000 MODE (best guess) = \$25,000

The responses to the computer's three queries would be:

10000 (for LOW) 30000 (for HIGH) 25000 (for MODE or best guess)

When these three values have been entered, proceed to Step 14.

<u>Step 13:</u> Because this cost element is a random variable to be generated by a CER, the number of cost drivers (slope parameters) needs to be entered. For example, if the CER to be evaluated is represented by the expression:

Y = a0 + a1*X1 + a2*X2 + a3*X3,

the number of cost drivers is 3, hence a 3 would be entered (notice the intercept term is not included). Go to Step 13a.

<u>Step 13a:</u> This is where the information regarding the existence of an intercept term asked for. If an intercept term exists in the CER, enter a '1', otherwise enter a '0' (go to Step 13b).

Step 13b: At times the CER in question will not be in a form easily manipulated unless the natural logarithm of both sides is taken. To prevent the user from having to compute these values and have to keep track of which terms need to be transformed, the program performs this task for the user. If a logarithmic transformation is required, the user would respond to the program's query with a '1' -- if no transformation is necessary, enter a '0' (go to Step 13c).

<u>Step 13c:</u> The purchase of a weapon system sometimes involves the buying of more than one particular component making up the weapon system. For example, a Boeing B-52 aircraft requires eight engines. To account for this in the software, the program LCC asks the user if the final cost

estimate of the CER needs to be multiplied by a scalar. If a scalar multiple is required, the user would respond to the program's query by entering a '1' and then going on to Step 13d. If no scalar multiple is required, a '0' should be entered (go to Step 14).

Step 13d: The next three queries represent how many components of the CER need to be purchased. If the value of the scalar multiple is certain, set both the LOW and HIGH values equal to each other. The program will then ask the user how the LOW and HIGH values are to be distributed based upon one of nine forms of the Beta distribution. If the LOW and HIGH values are equal, this information is not used, therefore the user should enter a '1' to the query regarding the TYPE of Beta distribution to be modeled. However, the exact amount of items to be purchased is not always known. In many instances, especially when a weapon system is still in the developmental stage, only a range of the number of components required is known -- hopefully based upon some distribution. This is why the program asks for a LOW value, HIGH value, and TYPE of Beta distribution. For example, if the LOW, HIGH, and TYPE are:

> LOW = \$10,000HIGH = \$30,000

TYPE = 4 (medium variance with higher probability of values occurring closer to the HIGH end (\$30,000))

The responses to the computer's queries would be:

10000 (for LOW)
30000 (for HIGH)
4 (for TYPE -- this must be an integer from 1 to 9)

When these three values have been entered, proceed to Step 14.

Step 14: This section of the program relates to the time phasing of each cost element. Time phasing refers to how the cost of each cost element is to be distributed over time. When the Department of Defense purchases a weapon system, the total cost of the system is not usually paid for in full as soon as the contracts detailing how many will be bought is signed by all involved. In most cases, the cost of the weapon system is spread out over the life of the weapon. For example, if the cost element is a constant with a cost of \$50,000, a portion of this cost may occur in increments at first, say over three years (the component's

PHASE-IN period). The next five years of payments could be set at a constant amount (the component's CONSTANT cost per year), while the remaining payments decrease at a steady rate for two years (the component's PHASE-OUT period). program transforms this information into a trapezoid. only a PHASE-IN or PHASE-OUT period exists, the shape of the trapezoid becomes a triangle. If only a CONSTANT period exists, the shape of the trapezoid is a rectangle. point is the program takes all of this into account so the user does not have to. The final piece of information required in this section is -- when do the payments for this particular component begin? The program transforms the initial cost provided by the user into annual costs based upon the discount rate, phase-in, phase-out, and constant cost per year values. Using the data mentioned above, the inputs to the program would be:

PHASE-IN: 3
CONSTANT: 5
PHASE-OUT: 2
YEAR WHEN PAYMENTS BEGIN: 8

The user must make sure the total of these four values does not exceed the life cycle of the system specified earlier in Step 8 (if the user makes an error here, the computer will catch it and ask the user to check her numbers and to try again).

NOTE: If the first realization of the cost element occurs immediately, enter a '0'. In other words, if the payments for this particular cost element are to start immediately, enter a '0'.

<u>CAUTION:</u> The four time phasing values cannot all be zero. If all four time phasing values are zero, the computer will ask the user to try again.

If this cost element is a random variable estimated by a CER (a '3' was entered at Step 10), proceed to Step 15. If this cost element was either a constant or a random variable modeled by the Beta or Triangular distribution, and more cost elements need to be entered, go back to Step 10. If neither of these two criteria apply, then the user has completed all inputs. This means the program will ask no further questions and the estimated life cycle cost of the weapon system is being executed (refer to Step 24 for output analysis). If changes to the data need to be made, type 'RUN LCC.EXE' when the '\$' prompt appears and follow the instructions provided.

Step 15: Every CER has a certain variability associated with it, along with an inherent variance/covariance between the cost drivers included within the CER. Step 15 asks the user to enter the value of the estimated variance (s-squared) of the CER estimate.

<u>CAUTION:</u> If the variance is very small (less than le-5) or very large (greater than le5), be sure to enter the variance in the form shown below. For example, if the variance is;

0.00000567, at the prompt enter, 5.67e-6, or 2340000000, at the prompt enter, 2.34e9

This will prevent the program from encountering a run time error (go to Step 16).

Step 16: This step is an iterative process dependent on the number of slope parameters plus the intercept term (if applicable). This is where the variance-covariance matrix of the cost drivers is entered. The variance of the intercept term occupies the position (1,1) if it is present. The data for the matrix is requested in row format. This means element (1,1) is asked for first, followed by element (1,2), then element (1,3), until all covariances in the first row have been entered. This process is repeated until all n-squared elements have been entered (where n equals the number of cost drivers plus the intercept (if applicable)). The caution mentioned in Step 15 regarding the input of very small or very large values applies to these entries as well. Proceed to Step 17.

Step 17: This is where the values for the slope parameters are entered. If an intercept term is present, the program will be aware of this and ask for the user to enter it first, followed by the remaining slope parameters.

As mentioned in Step 15, if the value of the intercept or slope parameters is very small or very large, the user must enter the value in accordance with the example shown in Step 15. Proceed to Step 18.

<u>Step 18:</u> Each cost driver is characterized by three queries. Therefore, this step is an iterative process where there inputs are required for each cost driver. Before each cost driver's data can be entered however, the user is asked:

Do you want cost driver # 1 to be modeled by a Beta or Triangular pdf? Enter: 1 for YES 2 for NO

If the Beta distribution is selected, go to Step 18a. Go to Step 18b for input instructions regarding the Triangular distribution.

Step 18a. The three queries presented in this step refer to the LOW value of the Beta pdf, the HIGH value of the Beta pdf, and the TYPE of Beta pdf to be modeled. If this cost driver is associated with an intercept term, the program will print the message,

Enter the INTERCEPT values NOW

prior to asking for the LOW value of the Beta pdf. This is important because if as intercept is present, the value to be entered for all three queries is '1.0'. For example, assume an intercept term does exist in the model described below:

AC = bo*X1 * X2

where,

AC = average cost per unit
X1 & X2 = cost drivers
bo = intercept term
b1 & b2 = slope parameters

This equation can be rewritten as,

ln(AC) = ln(bo)*X0 + b1*ln(X1) + b2*ln(X2)

This should help clarify why the values of the intercept term in response to the cost driver queries must all be equal to '1.0' -- the X0 term can only take on a value of '1.0'.

<u>CAUTION:</u> The cost drivers representing the X0 term <u>must</u> always equal '1.0', and they can <u>never</u> be altered (without completely reestimating the CER). If an intercept term is present, the program LCC.FOR regards X0 as cost driver #1 even though it is not a cost driver. X1 is treated as cost driver #2 (<u>internally</u> by the program) and X2 is cost driver #3.

Therefore, the three responses for an intercept term would be:

LOW = 1.0 HIGH = 1.0 TYPE = 1.0

If the cost driver in question does not refer to an intercept term, insert the actual LOW, HIGH, and TYPE values. If the value of the cost driver is certain, enter the same number for both the LOW and HIGH queries then enter a '1' for the query regarding the TYPE of Beta distribution to be modeled (the value for the TYPE is unimportant in this instance because the LOW and HIGH terms are equal). value of the cost driver is not certain, enter the appropriate IOW and HIGH values along with the TYPE of Beta distribution to be modeled. Continuing the example above, if X1 is assumed to be a constant equal to 100, then the responses to the LOW and HIGH queries would both be 100 (because the value of X1 is certain.) The TYPE of Beta distribution is irrelevant since the LOW and HIGH values are the same, but an integer from 1 to 9 must be entered. Suppose X2 can take on a value between 100 and 250 characterized by a Beta distribution of TYPE 8 (symmetrically distributed with low variability). The responses for this cost driver would be:

> LOW = 100 HIGH = 250 TYPE = 8

NOTE: If the natural logarithm of the LOW and HIGH values is required (ie, if a '1' was entered in Step 13b), be sure both the LOW and HIGH values entered by the user are greater than zero. Go to Step 19.

<u>Step 18b:</u> The three queries presented in this step refer to the LOW value of the Triangular pdf, the HIGH value of the Triangular pdf, and the MODE or best guess of the Triangular pdf to be modeled. If this cost driver represents the intercept of the CER in question, the program will print the message,

Enter the INTERCEPT values NOW

prior to asking for the LOW value of the Triangular distribution. This is important because if as intercept is present, the value to be entered for all three queries is '1.0'. For example, assume an intercept term does exist in the model described below:

$$b1 b2$$

$$AC = bo*X1 * X2$$

where,

AC = average cost per unit
X1 & X2 = cost drivers
bo = intercept term
b1 & b2 = slope parameters

This equation can be rewritten as,

ln(AC) = ln(bo)*X0 + b1*ln(X1) + b2*ln(X2)

This should help clarify why the values of the intercept term in response to the cost driver queries must all be equal to '1.0' -- the XO term can only take on a value of '1.0'.

Therefore, the three responses for an intercept term would be:

LOW = 1.0 HIGH = 1.0 MODE = 1.0

If the cost driver in question does not refer to an intercept term, insert the actual LOW, HIGH, and MODE values. If the value of the cost driver is certain, enter the same number for the LOW, HIGH, and MODE queries. If the value of the cost driver is not certain, enter the appropriate LOW, HIGH, and MODE values. Continuing the example above, if X1 is assumed to be a constant equal to 100, then the responses to the LOW, HIGH, and MODE queries would all be 100 (because the value of X1 is certain.) Suppose X2 can take on a value between 100 and 250 with a best guess of X2 being 150. The responses for this cost driver would be:

LOW = 100HIGH = 250 MODE (best guess) = 150

NOTE: If the natural logarithm of the LOW, HIGH, and MODE values is required (ie, if a '1' was entered in Step 13b), be sure the LOW, HIGH, and MODE values entered are greater than zero. Go to Step 19.

<u>Step 19:</u> Due to a limitation of the program, editing of the estimated variance (s-squared), variance/covariance matrix, and slope parameters is only possible upon the completion of

each cost element being entered. When the last cost driver card has been submitted for a particular cost element, the program prints the message;

The escimated variance (s-squared), covariance matrix, slope parameters, and cost driver cards have just been entered -- Do you wish to review or edit any of these?

Enter:
1 for YES
2 for NO

If no review is desired, the user enters a '2' and the program advances to the next cost element. If this was the last cost driver of the last cost element, no further requests for data will be made by the program -- proceed to Step 24 for a brief explanation of the output analysis.

If the user wishes to review or edit the data from Step 15 on and enters a '1', the program issues a notice then lists the estimated variance (s-squared), and the elements comprising the covariance matrix. If a change is necessary on one or more of these values, write down the number in the left hand column next to the value needing to be modified. The user is instructed to write down the number in the left hand column corresponding to the incorrect parameter because of the large number of parameters that may exist - this will eliminate the user from forgetting which element needed to be changed. For example, if the CER entered contained four cost drivers and an intercept term, a total of 46 elements eligible to be edited would appear on the screen (1 variance estimate, 25 covariance elements, 5 slope parameters, and 15 cost driver cards).

Once the last element of the covariance matrix has been presented, the program issues the message,

Press RETURN to continue . . .

After reviewing these values and documenting any changes needed to be made, the user would press <RETURN>. This invokes the program to display the slope parameters and cost driver values currently entered in the database. Immediately following the last cost driver value, the program asks the user:

Do you want to edit any of these?

Enter:
1 for YES
2 for NO

If no changes are required the user would enter a '2', meaning the program will advance to the next cost element (if one exists). (Go to either A listed above or to Step XX for output analysis.) If changes ARE required, continue on to Step 19a below.

Step 19a: The program will then ask the user how many changes need to be made. If the user realizes that NO changes are necessary, she would enter a '0'. This will cause the program to act as if a '2' were entered in Step 19. If changes are required, the user would enter an integer value equal to the number of changes desired. For example, if an element in the covariance matrix and one of the cost driver values needed to be changed, the user would enter a '2' in response to the question;

How many values would you like to edit?

The user would then proceed to Step 19b.

Step 19b: The program then asks the user to enter the number of the value to be changed, and follows this query with the statement, "Enter the new value". Continuing with the example shown in Step 19a, the user would enter the following values:

Enter the # of the value to be changed: x Enter the NEW value: the NEW phase-in value goes here

Enter the # of the value to be changed: y
Enter the NEW value: the NEW phase-out value goes here

The values x and y represent the numbers in the left hand column corresponding to the OLD covariance element and cost driver values, respectively. The order in which these two changes are made is NOT important. The key for the user is she must keep track of the numbers in the left hand column that correspond with the desired updates to be made.

<u>Step 20:</u> This step means the user has selected to either review and possibly edit the last data set entered or just conduct an additional run of the last data set entered. In either case, the first question posed to the user is:

Do you wish to edit the data?

Enter:
1 for YES
2 for NO

If the user selects to not edit the data, the program will proceed to execute the estimated life cycle cost of the weapon system using the same data provided by the last set (refer to Step 24 for output analysis).

If a review or editing of the data is desired, the user would enter a '1' to the question stated above (go to Step 21).

NOTE: The following steps only allow the user to review and edit the previous data set. Cost elements may NOT be added or deleted. If the addition or deletion of a cost element is desired, the user must reenter an entire new data set. This is accomplished by entering a '2' at Step 6.

<u>Step 21:</u> This step asks the user if a change to the expected life of the system needs to be modified. Before asking if a change is necessary, the program first provides a statement stating what the expected life of the system was for the previous data set. If a change is needs to be made, the program will ask the user to enter the new life cycle of the system (go to Step 22).

<u>CAUTION:</u> A change to the life cycle of the system, especially if the number of years is reduced may affect other portions of the data entered -- specifically, the total time of the phase-in, constant, and phase-out should be checked to ensure the new life cycle is not exceeded.

<u>Step 22:</u> This step is similar to Step 21 except in this step the discount rate for the system is presented for possible change. If a modification is desired, be sure to enter the new discount rate as described in Step 9 (go to Step 23).

Step 23: This step is an iterative process dependent upon the number of cost elements entered in the previous data set. The program asks the user if she wants to review each cost element. The cost elements are shown in the same order they were input in the last data set. If the user does not wish to review/edit a particular cost element, a '2' should be entered. This will cause the program to advance to the next cost element. This process is repeated until all of the cost elements have been offered for review/editing.

Once all of the cost elements have been presented for review/editing, the program will begin executing the estimated life cycle cost of the weapon system. If changes have been made, these changes will be incorporated in the program's life cycle cost estimate (go to Step 24 for output analysis).

If review/editing of a cost element is desired, the user would enter a '1' for that particular cost element. The process the program undergoes for this selection is as follows:

- A. The 'type' of the cost element is stated (constant, random variable estimated by a Beta or Triangular pdf, or random variable estimated by a CER).
 - B. Data pertinent to the cost element is listed.
- C. The program asks if any changes to this particular cost element is desired. If NO changes are required the user would enter a '2', meaning the program will advance to the next cost element (if one exists). (Go to either A listed above or to Step 24 for output analysis.) If changes ARE required, continue on to step D below.
- D. The program will then ask the user how many changes need to be made. If the user realizes that NO changes are necessary, she would enter a '0'. This will cause the program to act as if a '2' were entered in step C. If changes are required, the user would enter an integer value equal to the number of changes desired. For example, if the phase-in and phase-out values needed to be changed for a constant cost element, the user would enter a '2' in response to the question;

How many values would you like to edit?

E. The program then asks the user to enter the number of the value to be changed, and follows this query with the statement, "Enter the new value". Continuing with the example shown in part D, the user would enter the following responses:

Enter the # of the value to be changed: 2
Enter the NEW value: the NEW phase-in value goes here

Enter the # of the value to be changed: 4
Enter the NEW value: the NEW phase-out value goes here

The values 2 and 4 represent the numbers in the left hand column corresponding to the OLD phase-in and phase-out values, respectively. The order in which these two changes are made is NOT important. The key for the user is she must

keep track of the numbers in the left hand column that correspond with the desired updates to be made.

This example refers only to a constant cost element. The entries for the other two possible 'types' of cost elements are similar, but a little more complicated because they contain more options.

NOTE: The 'type' of cost element cannot be changed. If the 'type' of cost element requires editing, the entire data set must be reentered.


<u>Step 24:</u> This section and those that follow provide a brief explanation in how to obtain an analysis of the data entered into the program LCC.FOR. When the program LCC.EXE has finished running and the '\$' prompt returns to the screen, type:


\$ SAS ANAL


This causes the SAS program ANAL.SAS to be executed. This program will automatically access the file 'LCCOST.DAT' which contains the results calculated by the program LCC.EXE. When the '\$' prompt returns, the results from this SAS run will be contained in the file ANAL.LIS.


ANAL.LIS contains all of the statistical values necessary to complete an analysis of the estimated life cycle cost of the data provided by the user.


APPENDIX B: FLOWCHART














APPENDIX C: FORTRAN SOURCE CODE

Overview

The subroutines ANS, CLRSCR, TRIAG, TRIAG1, and CHECK were written by Captain Gibson. All other subroutines, including the main program were designed by Dr Cain, though portions of Dr Cain's code was modified by Captain Gibson (specifically, sections of the main program and the subroutine CER were modified by Captain Gibson).

| 0001 | | |
|------|---|---|
| 0002 | С | PROGRAM LCC.FOR WHICH CALCULATES THE LIFE CYCLE COST OF A |
| 0003 | С | WEAPONS SYSTEM. NOTE: THE IMSL SUBROUTINES MUST BE ATTACHED |
| 0004 | С | TO THE OBJECT DECK TO GET AN EXECUTABLE FILE. |
| 0005 | | PROGRAM LCC |
| 0006 | | LOGICAL found, lastset, ceredit, got |
| 0007 | | DIMENSION A(750,20), COST(100), CE(20,20), |
| • | | STORE(100), LC(750) |
| 0008 | | 1,BET(20), XSTAR(60), XCER(750,20), bort(20), |
| | | super(20,505) |
| 0009 | | REAL*8 LC |
| 0010 | | COMMON /AA/ Z(20) |
| 0011 | | COMMON /AB/ COSTC(100), COSTR(100) |
| 0012 | | DATA NRV/750/ |
| 0013 | | |
| 0014 | С | TO CHANGE TO A DIFFERENT NUMBER OF LCC SAMPLES |
| | • | CHANGE THE |
| 0015 | С | FOLLOWING STATEMENTS IN THE PROGRAM: |
| 0016 | С | IN THE DATA STATEMENT BELOW CHANGE NRV NUMBER, IN |
| | | SUBPROGRAMS |
| 0017 | С | BETA, CER, AND BETA1 CHANGE THE PARAMETER CARD AT |
| | | THE BEGINNING |
| 0018 | С | OF EACH PROGRAM. ALSO CHANGE THE VALUES OF MATRIX A |
| | | AND |
| 0019 | С | MATRIX XCER AND THE VALUES OF VECTOR LC IN THE |
| | | ABOVE DIMENSION |
| 0020 | С | STATEMENT. |
| 0021 | С | A(NRV, 20) HOLDS THE NRV SAMPLES OF EACH OF 20 COST |
| | | ELEMENTS. |
| 0022 | С | TO HANDLE MORE THAN 20 COST ELEMENTS A (NRV, 20) MUST |
| | | BE |
| 0023 | С | EXPANDED AS MUST THE ROW DESIGNATOR OF CE(*,20). |
| 0024 | С | Z(20) IS THE ARRAY CONTAINING THE COST ELEMENT |
| | | CARD. |
| 0025 | C | NOT ALL OF THE VALUES ARE CURRENTLY USED. |

```
C
              CE(*,20): THE * ROWS REFERS TO THE NUMBER OF COST
0026
              ELEMENTS
              PRESENT, THE 20 COLUMNS TO Z(20). IF YOU WANT 30
0027
        C
              COST
0028
        С
              ELEMENTS THEN YOU MUST MAKE THE FOLLOWING CHANGES:
0029
        C
              A(NRV,30), CE(30,20). IN SUBROUTINE TRAP CE(*,20)
              MUST BE CHANGED
0030
              TO CONFORM EXACTLY TO CE(*,20) IN THE MAIN PROGRAM
        C
              AND MCON(*,100)
0031
        C
              AND MRAND(*,100) MUST ALSO BE CHANGED (WHERE * IS
              DESIRED NUMBER
0032
        C,
              OF COST ELEMENTS).
0033
0034
        С
              The files INPUTLCC.DAT and MOREINPT.DAT contain the
              data saved
0035
        С
               from the previous data set entered. LCCOST.DAT
              contains the
0036
        C
              output of the 750 lcc samples attained by this
              program.
0037
0038
              OPEN(01, FILE='INPUTLCC.DAT', STATUS='OLD')
              OPEN(02, FILE='MOREINPT.DAT', STATUS='OLD')
0039
0040
              OPEN(05, FILE='LCCOST.DAT', STATUS='OLD')
0041
              REWIND 01
0042
              REWIND 02
0043
              REWIND 05
0044
              CALL CLRSCR
0045
              numcer = 0
0046
              ceredit = .false.
0047
              do 9 i = 1,27
0048
               do 9 j = 1,505
0049
                  super(i,j) = 0.0
0050
              continue
0051
0052
        С
               This section begins a long series of user prompts
               regarding
0053
               either the last data set entered, or the new set to
        С
               be entered.
0054
0055
               print*
              print*, 'Do you wish to access:'
0056
               print*,'1. the last data set entered, or'
0057
               print*,'2. begin a new data set?'
0058
0059
               print*, 'Enter a 1 or 2'
0060
               read*, oldnew
               asked = oldnew
0061
0062
               min = 1
0063
               max = 2
0064
               found = .TRUE.
               CALL ANS (min, max, asked, found)
0065
0066
               oldnew = asked
0067
               lastset = .FALSE.
```

```
0068
              Lastset is initially set to False meaning the user
0069
        C
              will input a
0070
                              If the user wants to review the last
              new data set.
        C
              data set
0071
              entered, lastset will be set to True (see line 86).
        C
0072
        C
              purpose of this is to ensure that if changes are
              made to the
0073
              last data set, the changes will be saved at the
        C
              appropriate time
0074
              and no duplicate information is saved.
0075
0076
              CALL CLRSCR
0077
              IF (oldnew .EQ. 1) THEN
0078
0079
             . . . retrieve the last data set entered from the
                  file
                  INPUTLCC. DAT
        C
0080
        C
                  and put the data in the array CE(I,J) after
                  getting the
0081
        C
                  number of cost components in the system, life
                  cycle of the
0082
                  system (in years), and the discount rate.
        C
0083
0084
                  read(01,59)NCOST, NYEARS, DISCOUNT
                  FORMAT(I3,1X,I3,1X,F4.3)
0085
         59
0086
                  DO 22 I=1, NCOST
                  DO 23 J=1,20
0087
8800
                     READ(01,58)CE(I,J)
0089
           58
                     FORMAT (F18.4)
0090
           23
                  continue
0091
           22
                  continue
                  do 164 i = 1, ncost
0092
0093
                     if (ce(i,1) .eq. 3.0) then
                        numcer = numcer + 1
0094
                        n = ifix(ce(i,10) + ce(i,11))
0095
                        do 160 iii = 1, (n*n + 5*n + 1)
0096
                           if (iii .le. (n*n + n + 1)) then
0097
0098
                              read(02,162) super(numcer,iii)
0099
          162
                               format(f31.16)
0100
                  else if (iii .gt. (n*n+n+1) .and. iii .le.
                 (n*n+4*n+1)) then
0101
                              read(02,161) super(numcer,iii)
0102
          161
                               format(f15.8)
0103
                           else
0104
                               read(02,163) super(numcer,iii)
0105
          163
                               format(f5.3)
0106
                           endif
0107
          160
                        continue
0108
                     else
0109
                     endif
```

```
164
0110
                 continue
0111
                  lastset = .TRUE.
                 numcer = 0
0112
0113
                 print*
0114
0115
                  The following user prompt may be the last one
        C
                 the user sees.
0116
                  If the user does not wish to edit the data, no
        C
                  further
0117
        C
                  questions will appear and the $ prompt will show
                 up meaning
0118
                 the program has completed its run.
        C
                                                        If data
                 viewing is
0119
        C
                  desired, the user would enter a 1 to the
                  following prompt.
0120
                 A series of questions asking if the current data
                 needs to
0121
        C
                 be modified would then appear.
0122
0123
                 print*, 'Do you wish to edit the data?'
0124
                 print*,'Enter:'
                 print*,'l for YES'
0125
0126
                 print*,'2 for No'
0127
                 read*, yorn
0128
                  asked = yorn
0129
                  CALL ANS (min, max, asked, found)
0130
                 yorn = asked
0131
                 print*
0132
                  IF (yorn .EQ. 1) THEN
                     print 721, NYEARS
0133
                     FORMAT(' The life cycle of this system
0134
          721
                     is', I4, ' years.')
                     print*,'Do you wish to change this?'
0135
0136
                     print*, 'Enter:'
                     print*,'1 for YES'
0137
0138
                    print*,'2 for NO'
0139
                    read*, yorn
0140
                     asked = yorn
0141
                     CALL ANS (min, max, asked, found)
0142
                     vorn = asked
0143
                     print*
0144
                     IF (yorn .EQ. 1) THEN
0145
                        print*, Enter the new life cycle of this
                        system: '
0146
                        print*,'(the maximum is 100 years)'
0147
                        read*, NYEARS
0148
0149
        С
                     CAUTION: A change to the life cycle of the
                     system,
0150
        С
                     especially if the number of years is reduced
0151
        С
                     affect other portions of the data entered --
```

```
0152
                     specifically, the total time of the phase in,
        C
0153
        C
                     constant, and phase out should be checked to
                     ensure
0154
                     the new life cycle is not exceeded.
0155
                  ELSE
0156
0157
                  ENDIF
0158
                  print 722, DISCOUNT
                  FORMAT(' The discount rate for this system is
0159
          722
0160
                  print*, 'Do you wish to change this?'
                  print*, 'Enter: '
0161
                  print*,'1 for YES'
0162
                  print*,'2 for NO'
0163
0164
                  read*,yorn
0165
                  asked = yorn
                  CALL ANS (min, max, asked, found)
0166
0167
                  yorn = asked
0168
                  IF (yorn .EQ. 1) THEN
0169
                     print*, 'Enter the new discount rate for this
                     system: '
0170
                     print*,'(for example, 9% would be entered as
                     0.09)'
0171
                     read*, DISCOUNT
0172
                  ELSE
0173
                  ENDIF
0174
                  print*
0175
                  DO 30 ieye = 1, NCOST
0176
                  In this section each of the cost elements become
0177
        С
                  available
0178
                  for review.
                                The sequence of the elements
                  matches how the
0179
                  data was originally entered.
        C
0180
0181
                     DO 31 j=1,20
                         Z(j) = CE(ieye, j)
0182
0183
           31
                     continue
0184
                     if (Z(1) \cdot eq. 3.0) numcer = numcer + 1
                     print 32, ieye
0185
0186
           32
                     FORMAT(' Do you wish to review cost element
                     #',I3)
                     print*,'Enter:'
0187
                     print*,'1 for YES'
0188
                     print*,'2 for NO'
0189
0190
                     read*, yorn
                     asked = yorn
0191
0192
                     min = 1
0193
                     max = 2
                     CALL ANS (min, max, asked, found)
0194
0195
                     yorn = asked
0196
                     print*
```

| 0197 0198 | | | <pre>IF (yorn .EQ. 1) THEN print 33, ieye</pre> |
|--------------|---|------|---|
| 0199 | | 33 | FORMAT(' COST ELEMENT NUMBER ',13) |
| 0200 | | | print* |
| 0201 | | | IF (Z(1) .EQ. 1) THEN |
| 0202 | | | (b(1) 12g1 1) 111111. |
| 0203 | С | | the cost element in question is a |
| 0204 | | | constant |
| 0204 | | | nrint 24 7/2\ |
| 0205 | | 34 | <pre>print 34, Z(2) FORMAT(' 1. is a CONSTANT =',F16.2)</pre> |
| 0207 | | J.4 | print*, 'Only the CONSTANT value can be |
| | | | changed here -' |
| 0208 | | | print*, 'The TYPE of CE CANNOT be |
| | | | changed unless a' |
| 0209 | | | print*, 'NEW data set is entered!' |
| 0210 | | | print 35, Z(6) |
| 0211 | | 35 | FORMAT(' 2. whose PHASE IN period is |
| 0010 | | | ',F3.1,' years') |
| 0212 | | 2.6 | print 36, Z(7) |
| 0213 | | 36 | FORMAT(' 3. This CE is constant for |
| 0014 | | | ',F4.1,' years') |
| 0214 | | 2 77 | print 37, Z(8) |
| 0215 | | 37 | FORMAT(' 4. The PHASE OUT period is |
| 0016 | | | ',F3.1,' years') |
| 0216 0217 | | 38 | print 38, Z(9) |
| 0217 | | 38 | FORMAT(' 5. This CE time period begins |
| 0218 | | | in year ',F4.1) print* |
| 0218 | | | |
| | | | <pre>print*,'Would you like to change any of these?'</pre> |
| 0220 | | | print*, 'Enter: ' |
| 0221 | | | print*,'1 for YES' |
| 0222 | | | print*,'2 for NO' |
| 0223 | | | read*, yorn |
| 0224 | | | asked = yorn |
| 0225 | | | CALL ANS(min, max, asked, found) |
| 0226 0227 | | | yorn = asked |
| 0227 | | | IF (yorn .EQ. 1) THEN |
| 0220 | | | <pre>print*,'How many values would you like to edit?'</pre> |
| 0229 | | | print*,'(Enter 0 to exit)' |
| 0230 | | | read*, numchanges |
| 0231 | | | asked = numchanges |
| 0232 | | | min = 0 |
| 0232 | | | $\max = 5$ |
| 0234 | | | CALL ANS (min, max, asked, found) |
| 0235 | | | numchanges = asked |
| 0236 | | | IF (numchanges .GT. 0) THEN |
| 0237 | | | (|
| 0238 | С | | If changes are to be made, the new values are |
| | | | read into |

```
some form of the counter, jay. The reason why
0239
        C
                   jay's value
0240
                   is inconsistent is to make sure the number of
        С
                   the area
                   needed to be changed will coincide with where
0241
        С
                   the data
0242
                   actually came from. For example, if the Phase
        C
                   Out period
0243
                   needs to be modified, the user would enter the
        C
                   number 4.
0244
                  However the number 4 does not match up with
        С
                  where the value
0245
        C
                   for Phase Out is stored in the array Z. That's
                   why in this
0246
                   case the user's input of 4 must have an
        C
                   additional 4 added
0247
        C
                   to it.
0248
0249
                               DO 39 k=1, numchanges
0250
          666
                                 print*
0251
                                 print*, 'Enter the # of the value
                                 to be'
0252
                                 print*, 'changed (ie, a 1,2,3,4,
                                 or 5)'
0253
                                 print*,'(Enter a 0 to exit)'
0254
                                 read*, jay
0255
                              IF (jay .LT. 0 .OR. jay .GT. 5) THEN
0256
                                     GO TO 666
0257
                                  ELSE IF (jay .EQ. 1) THEN
0258
                                     jay = jay + 1
0259
                                     print*
                                     print*, 'Enter the NEW value: '
0260
                                     read*, Z(jay)
0261
0262
                       ELSE if (jay .ge. 2 .and. jay .le. 5) then
0263
                                     jay = jay + 4
0264
                                     print*
0265
                   print*, 'Be sure the life cycle of this system,'
0266
                        print 80, NYEARS
0267
           80
                        FORMAT( F3.1,' is not exceeded.')
0268
                                     print*, 'Enter the NEW value: '
0269
                                     read*, Z(jay)
0270
                                  else
0271
                                 ENDIF
0272
0273
        С
                     put the new data in its proper place (below)
0274
                                  CE(ieye,jay)=Z(jay)
0275
0276
           39
                                continue
0277
                             ELSE
0278
                             ENDIF
0279
                           ELSE
0280
                           ENDIF
```

| 0281 | | ELSE IF (Z(1) .EQ. 2) THEN |
|------|-------|--|
| 0282 | | |
| 0283 | С | the cost element in question is a random variable |
| 0284 | | TR (G(00) FO 1 0) MILEN |
| 0285 | 444 | IF (Z(20) .EQ. 1.0) THEN |
| 0286 | _ | CANTON TO ALL THE STATE OF STATE AND AND ADDRESS AND A |
| 0287 | С | CAUTION: If the Low or High value for either the beta or |
| 0288 | С | triangular distributions is changed, make sure the new |
| 0289 | С | Low/High value is indeed lower/higher than the corresponding |
| 0290 | С | High/Low value since no check is provided here in the code. |
| 0291 | | |
| 0292 | | print*,'1. is a RV modeled by a beta pdf! |
| 0293 | | print*, 'THIS CANNOT BE CHANGED HERE - YOU MUST' |
| 0294 | | print*, 'ENTER A NEW DATA SET!' |
| 0295 | | print 40, Z(3) |
| 0296 | 40 | FORMAT(' 2. LOW value of the Beta distro |
| | | is ',F15.2) |
| 0297 | | print 41, Z(4) |
| 0298 | 41 | FORMAT(' 3. HIGH value of the Beta distro |
| | _ | is ',F15.2) |
| 0299 | | print 42, Z(5) |
| 0300 | 42 | FORMAT(' 4. The TYPE of Beta being |
| | | modeled is ',F3.1) |
| 0301 | | ELSE |
| 0302 | | print*,'l. is a RV modeled by a |
| | | triangular pdf ' |
| 0303 | | print*, 'THIS CANNOT BE CHANGED HERE - YOU MUST' |
| 0304 | | print*, 'ENTER A NEW DATA SET!' |
| 0305 | | print 70, Z(3) |
| 0306 | 70 | FORMAT(' 2. LOW value of the Triang |
| | | distro is',F15.2) |
| 0307 | | print 71, Z(4) |
| 0308 | 71 | FORMAT(' 3. HIGH value of the Triang distro |
| | | is',F15.2) |
| 0309 | | print*,'4. MODE or EXPECTED value of |
| | | the Triang' |
| 0310 | | print 72, Z(5) |
| 0311 | 72 | FORMAT(' distro is',F15.2) |
| 0312 | - | ENDIF |
| 0313 | | print 43, Z(6) |
| 0314 | 43 | FORMAT(' 5. The PHASE IN period is |
| | • • • | '.F4.l.' years') |
| 0315 | | ',F4.1,' years') print 44, Z(7) |
| 0316 | 44 | FORMAT(' 6. This CE is constant for |
| | • • | ',F4.1,' years') |
| 031/ | | print 45, Z(8) |
| 0318 | 45 | FORMAT(' 7. The PHASE OUT period is |
| | | ',F4.1,' years') |
| | | , _ , _ , _ , _ , |

```
0319
                           print 46, Z(9)
                           FORMAT(' 8. This CE time period begins
0320
           46
                           in year ',F4.1)
0321
                           print*
                   print*, 'Would you like to change any of these?'
0322
0323
                           print*,'Enter:'
                           print*,'1 for YES'
0324
0325
                           print*,'2 for NO'
0326
                           read*, yorn
                            asked = yorn
0327
0328
                           min = 1
0329
                           max = 2
0330
                           CALL ANS(min, max, asked, found)
0331
                           yorn = asked
                           IF (yorn .EQ. 1) THEN
0332
                              print*, 'How many values would you
0333
                              like to edit?'
                              print*,'(Enter a 0 to exit)'
0334
                              read*, numchanges
0335
0336
                              asked = numchanges
0337
                              min = 0
0338
                              max = 8
0339
                              CALL ANS(min, max, asked, found)
0340
                              numchanges = asked
0341
                              IF (numchanges .GT. 0) THEN
                                DO 47 k = 1, numchanges
0342
                                  print*
0343
0344
                  print*, 'Enter the # of the value to be changed'
0345
                                  print*,'(ie, enter a 1 - 8)'
0346
                                  read*, jay
0347
                                  IF (jay .EQ. 1) THEN
             print*, 'THIS CANNOT BE CHANGED HERE! YOU CAN ONLY'
0348
0349
           print*, 'CHANGE THIS BY ENTERING A WHOLE NEW DATA SET.'
0350
                                    print*
0351
                                    GO TO 444
0352
                                  ELSE
0353
                                    jay = jay + 1
0354
                                    print*, 'Enter the NEW value: '
                                    read*, Z(jay)
0355
0356
                                  ENDIF
0357
                                  CE(ieye,jay) = Z(jay)
0358
            47
                                continue
0359
                              ELSE
0360
                              ENDIF
0361
                            ELSE
0362
                            ENDIF
0363
                         ELSE
0364
0365
                The cost component in question is a cost
                estimating
0366
                relationship.
0367
```

| 0368 0369 | 555 | print*,'1. This CE is a RV generated by a CER' print*,' THIS CANNOT BE CHANGED HERE |
|--------------|------------|---|
| | | - a NEW data' |
| 0370 | | <pre>print*,' set must be entered to change the CE type.'</pre> |
| 0371 | | print 48, Z(10) |
| 0372 | 48 | FORMAT(' 2. The # of SLOPE parameters |
| | 40 | is '.F3.1) |
| 0373 | | <pre>print*,'3. If an INTERCEPT term exists, a 1 will'</pre> |
| 0374 | | <pre>print*,' appear, otherwise a 0 will be used to'</pre> |
| 0375 | | <pre>print*,' represent NO INTERCEPT term NOTE:'</pre> |
| 0276 | | print*,' If this is changed, you must |
| 0376 | | RE-ESTIMATE' |
| 0277 | | print*,' the ENTIRE CER!' |
| 0377 | | print 40 7/11) |
| 0378 | 4.0 | print 49, Z(11) FORMAT(' INTERCEPT?: 'F3.1) |
| 0379 | 49 | print*,'4. If CER was estimated by |
| 0380 | | |
| | | taking logs, a' |
| 0381 | | print 50, Z(12) |
| 0382 | 50 | FORMAT(' 1 will appear, a 0 if not - |
| | | LOGS?: ',F3.1) |
| 0383 | | <pre>print*,'5. If the final estimate is to be multiplied'</pre> |
| 0384 | | print*,' by a scalar, a one will |
| 050. | | appear, otherwise' |
| 0385 | | print 51, Z(13) |
| 0386 | 51 | FORMAT(' a 0 will appear - SCALAR |
| 0300 | 0.2 | MULT?: ',F3.1) |
| 0387 | | print 52, Z(14) |
| 0388 | 52 | FORMAT(' 6. The LOW value of the SCALAR |
| 0300 | 32 | is',F7.1) |
| 0389 | | print 53, Z(15) |
| 0390 | 53 | FORMAT(' 7. The HIGH value of the |
| 0390 | 33 | SCALAR is', F7.1) |
| 0201 | | print* |
| 0391 | | print*, 'Press RETURN to continue ' |
| 0392 | | read* |
| 0393 | | |
| 0394 | | if (Z(20) .eq. 1.0) then |
| 0395 | | print 54, Z(16) |
| 0396 | 54 | FORMAT(' 8. The TYPE of Beta distro is ',F3.1) |
| 0397 | | else if $(Z(20) \cdot eq. 2.0)$ then |
| 0398 | | print 8, Z(16) |
| 0399 | 8 | format(' 8. The MODE of the SCALAR |
| | | is',F15.2) |
| 0400 | | else |
| 0401 | | endif |
| 0402 | | print 55, Z(6) |
| 0403 | 55 | FORMAT(' 9. The PHASE IN period is ',F4.1) |
| 0400 | J J | |

```
0404
                           print 56, Z(7)
0405
           56
                        FORMAT(' 10. This CE is a constant for
                         ',F4.1,' years')
0406
                            print 57, Z(8)
0407
           57
                           FORMAT(' 11. The PHASE OUT period is
                           ',F4.1,' years')
0408
                           print 61, Z(9)
0409
                        FORMAT(' 12. This CE time period begins in
           61
                        year ',F4.1)
0410
                            print*,'13. Cost Driver changes?'
0411
                            print*
0412
                   print*,'Would you like to change any of these?'
0413
                           print*,'Enter:'
0414
                           print*,'l for YES'
                           print*,'2 for NO'
0415
0416
                            read*, yorn
                            asked = yorn
0417
0418
                           min = 1
0419
                           max = 2
0420
                            CALL ANS (min, max, asked, found)
0421
                            yorn = asked
0422
                            IF (yorn .EQ. 1) THEN
0423
                              print*, 'How many values would you
                              like to edit?'
0424
                              print*, '(Enter a 0 to exit):'
0425
                             read*, numchanges
0426
                              asked = numchanges
0427
                             min = 0
0428
                             max = 13
0429
                              CALL ANS (min, max, asked, found)
0430
                              numchanges = asked
0431
                              IF (numchanges .GT. 0) THEN
0432
                                DO 62 k = 1, numchanges
0433
0434
                                print*,'Enter the # of the value to
                                be changed: '
0435
                                  print*,'(ie, enter a 1 - 13)'
0436
                                  read*, jay
0437
                                  asked = jay
0438
                                  CALL ANS(min, max, asked, found)
0439
                                  jay = asked
0440
                                  IF (jay .EQ. 1) THEN
                    print*, 'THIS CANNOT BE CHANGED HERE! YOU CAN
0441
                    ONLY CHANGE'
0442
                    print*, 'THIS BY ENTERING A NEW DATA SET.'
0443
                                    print*
0444
                                    GO TO 555
0445
                                  ELSE IF (jay .GT. 1 .AND. jay
                                  .LT. 9) THEN
0446
                                    jay = jay + 8
0447
                                    print*
0448
                                    print*, 'Enter the NEW value:'
```

```
0449
                                     read*, Z(jay)
0450
                                  ELSE IF (jay .ge. 10 .and. jay
                                   .lt. 13) then
0451
                                     jay = jay - 3
0452
                                     print*
0453
                                     print*, 'Enter the NEW value:'
                                     read*, Z(jay)
0454
                                  ELSE IF (jay .eq. 13) then
0455
                                     n = ifix(\overline{Z(10)} + Z(11))
0456
                                     istart = (n*n + n + 2)
0457
0458
                                     kk = 1
0459
                                     print*
0460
                                     do 999 iii = 1,n
                                        print 27, iii
format(' Cost Driver #',i3)
0461
            27
0462
0463
                                        print*
0464
                          if (2(12) .eq. 1.0 .and. kk .gt. 1) then
0465
                             rlowout = exp(super(numcer,istart))
0466
                             highout = exp(super(numcer,istart+1))
                             print 834, kk, rlowout
0467
                             format(I3,'. LOW = ',f15.2)
0468
           834
                             print 835, kk+1, highout
0469
0470
           835
                             format(I3,'. HIGH = ',f15.2)
0471
0472
                             print 90, kk, super(numcer,istart)
0473
            90
                                        format(I3,'. LOW = ',f15.2)
0474
                             print 91, kk+1, super(numcer,istart+1)
                                        format(I3,'. HIGH = ',f15.2)
0475
            91
0476
                           endif
0477
                  if (super(numcer,(n*n+4*n+1+iii)) .eq. 1.0) then
0478
                     print 92, kk+2, super(numcer,istart+2)
            92
                                        format(I3,'. TYPE = ',f7.1)
0479
0480
                      else if (super(numcer,(n*n+4*n+1+iii)) .eq.
                      2.0) then
0481
                           if (Z(12) \cdot eq. 1.0 \cdot and. kk \cdot gt. 1) then
0482
                             rmodeout = exp(super(numcer,istart+2))
0483
                             print 836, kk+2, rmodeout
0484
           836
                             format(I3,'. MODE = ',f15.2)
0485
                           else
0486
                             print 93, kk+2, super(numcer,istart+2)
0487
            93
                             format(I3,'. MODE = ',f15.2)
0488
                                           print*
0489
                           endif
0490
                                        else
0491
                                        endif
                                        print*
0492
                                        kk = kk + 3
0493
                                        istart = istart + 3
0494
0495
           999
                                     continue
0496
                                   print*
0497
                                   print*, 'How many cost drivers
                                   need editing?'
```

```
0498
                                  print*, '(enter 0 to exit)'
0499
                                  read*, ichange
0500
                                  asked = ichange
                                  min = 0
0501
0502
                                  max = 3*n
0503
                                  CALL ANS (min, max, asked, found)
0504
                                  ichange = asked
0505
                                  if (ichange .gt. 0) then
0506
                                    ceredit = .true.
0507
                                    super(numcer, 505) = n
0508
                                    do 97 jjj = 1, ichange
0509
                                     print*
0510
                                     print*, 'Enter the # of the
                                     value to be'
0511
                                     print 98, max
           98
                                     format(' changed (ie, a 1
0512
                                      -',I3,')')
                                     read*, jaycd
0513
0514
                                     asked = jaycd
0515
                                     min = 1
0516
                                     CALL ANS (min, max, asked, found)
0517
                                     jaycd = asked
0518
                                     print*
                                     print*, 'Enter the NEW value'
0519
0520
                                     read*, XSTAR(jaycd)
0521
                              if (Z(12) .eq. 1.0) then
0522
                                 11 = 1
0523
                                 qot = .false.
0524
                                 m = 1
0525
          573
                              if (got .eq. .false.) then
0526
                     if (jaycd .gt. ((m-1)*n) .and. jaycd .lt.
                     (m*n+1)) then
0527
                         got = .true.
0528
                     else
0529
                         m = m + 1
0530
                          11 = 11 + 1
0531
                     endif
0532
                     go to 573
0533
                              else
0534
                              endif
0535
                                    if (Z(11) .eq. 0.0) then
0536
                                        ibeq = 1
0537
                                    else
0538
                                        ibeg = 4
0539
                                    endif
0540
                      if (jaycd .ge. ibeg .and. (n*n+4*n+1+11)
                       .eq. 2.0) then
0541
                          XSTAR(jaycd) = LOG(XSTAR(jaycd))
0542
                         super(numcer, (n*n+n+1+jaycd)) =
                         XSTAR (jaycd)
0543
                    else if (MOD(jaycd,3) .ne. 0) then
0544
                          XSTAR(jaycd) = LOG(XSTAR(jaycd))
```

```
0545
                         super(numcer,(n*n+n+1+jaycd)) =
                         XSTAR (jaycd)
0546
                      else
                      endif
0547
0548
                              else
0549
                                    super(numcer, (n*n+n+1+jaycd)) =
                                    XSTAR (jaycd)
0550
                              endif
           97
                                    continue
0551
0552
                                  else
                                  endif
0553
0554
                                  ELSE
                                  ENDIF
0555
0556
                                  CE(ieye,jay) = Z(jay)
           62
0557
                                continue
0558
                              ELSE
                              ENDIF
0559
0560
                            ELSE
                            ENDIF
0561
0562
                        ENDIF
0563
                     ELSE
0564
                     ENDIF
            30
0565
                  continue
0566
                  ELSE
0567
                  ENDIF
0568
               ELSE
0569
               OLDNEW equals 2, ie new data set is to be entered.
0570
        C
               In this
0571
        C
               section the user receives a series of prompts
               regarding the
0572
               status of the cost components to be entered.
        C
                                                                The
               value of
               lastset remains False for this section.
0573
        C
0574
0575
               print*
0576
               print*, 'You are entering a new data sct.
                                                            If an
               incorrect value'
0577
               print*, 'is entered, continue entering the remaining
               values.'
0578
               print*, 'Changes may be made by rerunning this
               program and then'
0579
               print*, 'selecting the option to edit the data.'
0580
               print*
               print*, 'Fnter the number of cost elements: '
0581
               read*, NCOST
0582
0583
               print*, 'Enter the life cycle of the system (in
               years): '
0584
               read*, NYEARS
0585
               print*, 'Enter the discount rate (ie, if the
               discount rate: '
               print*, 'is 9%, enter .09 or 0.09)'
0586
```

```
read*, DISCOUNT
0587
0588
               Initialization of all arrays is conducted below by
0589
        С
               setting
               them equal to zero.
0590
        С
0591
               DO 1 I=1,NRV
0592
0593
               LC(I) = 0.0
             1 CONTINUE
0594
0595
               DO 2 I=1, NCOST
               DO 2 J=1,20
0596
0597
                  CE(I,J) = 0.0
             2 CONTINUE
0598
               DO 5 J=1, NCOST
0599
               DO 5 I=1, NRV
0600
0601
                  A(I,J) = 0.0
0602
             5 CONTINUE
0603
               DO 6 J=1,100
                  COST(J) = 0.0
0604
0605
             6 CONTINUE
0606
               J=0
0607
               DO 100 II=1, NCOST
0608
0609
               Begin loop to enter the new cost elements.
0610
        C
0611
0612
               DO 7 I = 1,20
0613
                  Z(I) = 0.0
             7 CONTINUE
0614
0615
               J=J+1
0616
               CALL CLRSCR
0617
               print*
0618
               print 222,II
0619
           222 FORMAT(' What type is cost component', I3, '?')
0620
               print*,'1. a constant?'
0621
               print*,'2. a random variable modeled by either'
               print*,' a Beta or Triangular pdf?'
0622
0623
               print*,'3. a random variable generated by a CER?'
0624
0625
               print*, 'Enter a 1, 2, or 3'
0626
               read*, Z(1)
               asked = Z(1)
0627
               min = 1
0628
               max = 3
0629
               CALL ANS(min, max, asked, found)
0630
               Z(1) = asked
0631
0632
               print*
0633
               if (Z(1) \cdot EQ \cdot 1) then
0634
0635
               The question asked of the user here relate to this
        C
               cost
0636
               component being a constant. Notice the only
         С
```

```
information
7637
              needed is the cost.
0638
0639
                  print 225,II
0640
          225
                  FORMAT(' Enter the constant cost of
                  component', I3,': ')
0641
                  print*,'(If the cost is $25,000 then enter
                  25000) ¹
0642
                  read*, Z(2)
0643
               ELSE IF (Z(1) . EQ. 2) THEN
0644
0645
               These questions reflect that this cost component is
        С
               a random
0646
               variable.
        С
0647
0648
            print*, 'Do you wish this component to be modeled by:'
0649
                  print*,'
                              1. a Beta pdf, or'
                  print*,'
0650
                              2. a Triangular pdf'
                  print*, 'Enter a 1 or 2: '
0651
0652
                  read*, answer
0653
                  asked = answer
0654
                  min = 1
0655
                  max = 2
0656
                  CALL ANS (min, max, asked, found)
0657
                  answer = asked
0658
                  Z(20) = answer
0659
0660
               Z(20) is assigned here as the response to whether
        С
               this cost
0661
               component is to be modeled as either a beta or
        C
               triangular
0662
        С
               distribution.
0663
0664
                  IF (ANSWER .EQ. 1) THEN
0665
            81
                     print*
0666
                     print*, 'Enter the LOW value of the BETA
                     distribution: '
0667
                     print*,'(For example, if the LOW value of the
                     BETA'
0668
                     print*,'is $25,000, enter 25000.)'
0669
                     read*, Z(3)
0670
                     print*
                     print*, 'Enter the HIGH value of the BETA
0671
                     distribution: '
0672
                     read*, Z(4)
0673
                     IF (Z(3) \cdot GT \cdot Z(4)) THEN
0674
                        print*
0675
                        print*, 'Your LOW Beta value exceeds the
                        HIGH Beta'
0676
                        print*, 'value -- check your numbers and
                        try again.'
                        GO TO 81
0677
```

```
0678
                     ELSE
0679
                     ENDIF
0680
                     print*
0681
                     print*, 'Enter a 1-9 corresponding to the Type
                     # of the'
0682
                   print*, 'BETA distribution for this component: '
0683
                     read*, Z(5)
0684
                  ELSE
0685
           82
                     print*
0686
                     print*, 'Enter the LOW value of the TRIANG
                     distribution: '
0687
                     print*,'(For example, if the LOW value of the
                     TRIANG'
0688
                     print*, 'distro is $25,000, enter 25000.)'
0689
                     read*, Z(3)
0690
                     print*
0691
                     print*, 'Enter the HIGH value of the TRIANG
                     distribution: '
0692
                     read*, 7(4)
                     IF (7(3) . GT. Z(4)) THEN
0693
0694
                        print*
0695
                        print*, 'Your LOW value of the TRIANG
                        distro exceeds'
0696
                        print*, 'the HIGH value -- check your
                        numbers and'
0697
                        print*, 'try again.'
0698
                        GO TO 82
0699
                     ELSE
0700
                     ENDIF
0701
                     print*
0702
              print*, 'Enter the MODE or BEST GUESS of the TRIANG'
0703
                     print*,'distribution: (ie, enter a value
                     between the'
                     print*,'LOW and HIGH values)'
0704
0705
                     read*, Z(5)
0706
                     if (Z(5) .lt. Z(3) .or. Z(5) .gt. Z(4)) then
0707
                        print*
0708
                        print*, 'Your MODE value is either less
                        than the LOW'
0709
                        print*, 'value or greater than the HIGH
                        value --'
0710
                        print*, 'check your numbers and try again.'
0711
                        go to 82
0712
                     else
0713
                     endif
0714
                  ENDIF
0715
              ELSE IF (Z(1) \cdot EQ \cdot 3) THEN
0716
0717
        C
              This cost component is a cost estimating
              relationship.
0718
0719
                  print*
```

```
0720
                  print*, 'Enter the number of of cost drivers in
                  the CER.'
0721
                  print*,'(ie, the number of SLOPE parameters --
                  BUT DO: '
0722
                  print*,'NOT include the intercept term (if
                  applicable)):'
0723
                  read*, Z(10)
0724
                  print*
0725
                  print*,'Enter a 1 if an intercept term IS
                  present --'
0726
                  print*, 'enter a 0 is NO intercept term is
                  present: '
0727
                  read*, Z(11)
0728
                  asked = 2(11)
0729
                  min = 0
0730
                  max = 1
0731
                  CALL ANS (min, max, asked, found)
0732
                  Z(11) = asked
0733
                  print*
0734
                  print*, 'Enter a 1 if the CER was estimated by
                  taking'
0735
                  print*,'logs (Base e) -- enter a 0 if log
                  estimation'
0736
                  print*,'is NOT desired: '
0737
                  read*, Z(12)
0738
                  asked = Z(12)
0739
                  CALL ANS (min, max, asked, found)
0740
                  Z(12) = asked
0741
                  print*
0742
                  print*, 'Enter a 1 if the final cost estimate is
                  to be'
0743
                  print*, 'multiplied by a scalar. For example, if
                  the CER'
0744
                  print*, 'describes the cost of buying a radio,
                  but you intend'
0745
                  print*, 'to purchase 50 to 60 radios, enter a 1,'
                  print*, 'otherwise enter a 0: '
0746
0747
                  read*, Z(13)
0748
                  asked = Z(13)
                  CALL ANS(min, max, asked, found)
0749
0750
                  Z(13) = asked
0751
                  IF (Z(13) \cdot EQ \cdot 1) THEN
0752
                     print*
0753
                print*, 'Do you wish this scalar to be modeled by:'
                     print*,' 1. a Beta pdf, or'
0754
                     print*, ' 2. a Triangular pdf'
0755
                     print*, 'Enter a 1 or 2:'
0756
0757
                     read*, Z(20)
0758
                     min = 1
0759
                     max = 2
                     asked = Z(20)
0760
0761
                     CALL ANS (min, max, asked, found)
```

```
0762
                     Z(20) = asked
0763
                     print*
                     print*, 'Enter the LOW value of the scalar: '
0764
0765
                     read*, Z(14)
0766
                     print*
0767
                     print*, 'Enter the HIGH value of the scalar
                     (if the'
0768
                     print*, 'value of the scalar is certain, set
                     both the'
0769
                     print*,'LOW and HIGH values equal): '
0770
                     read*, Z(15)
0771
                     print*
0772
                     if (Z(20) .eq. 1.0) then
0773
                        print*, 'Enter the type of Beta
                        Distribution: '
0774
                        print -, '(ie, a 1 - 9)'
0775
                     else if (Z(20) \cdot eq. 2.0) then
0776
                     print*, 'Enter the MODE or BEST GUESS of the'
0777
                        print*, 'Triangular distribution:'
0778
                     else
0779
                     endif
0780
                     read*, Z(16)
0781
                  ELSE
0782
                  ENDIF
0783
              ELSE
0784
              ENDIF
0785
0786
        С
              CHECK FOR TIME PHASING OF THE COST ELEMENT.
0787
0788
               print*
0789
               print*, 'The next three values relate to the Time
               Phasing of'
0790
               print*, 'the cost element. Be sure the total length
               of your'
0791
               print*, 'PHASE-IN, CONSTANT COST, and PHASE-OUT does
               not exceed!
0792
               print 226, NYEARS
0793
          226 FORMAT(' the total LIFE CYCLE you specified earlier
               (',I3,').')
0794
           67 print*
0795
               print*, 'Enter the component phase-in period (in
               years): '
0796
               read*, 2(6)
0797
               print*
0798
             print*,'Enter # of years cost element is a constant'
0799
              print*,'cost per year: '
0800
               read*, Z(7)
0801
               print*
0802
               print*, 'Enter the component phase-out period (in
              vears): '
0803
               read*, Z(8)
0804
               print*
```

```
0805
              print*, 'Enter the time period when the element
              starts: '
              print*,'(NOTE: if the 1st realization of this
0806
              element is in'
0807
              print*, 'year zero then enter 0.)'
8080
              read*, Z(9)
0809
0810
        C
              The check below ensures all of the time phasing
              values are NOT
0811
        С
              equal to zero and that their sum does not exceed
              the life
0812
        С
              cycle of the system.
0813
              totalzs = Z(6) + Z(7) + Z(8) + Z(9)
0814
0815
              IF(Z(6) .EQ. 0.0 .AND. Z(7) .EQ. 0.0
              .AND.Z(8).EQ.O.O) THEN
0816
             print*, 'Check the Time Phasing values again, they'
0817
                  print*, 'CANNOT ALL BE ZERO!'
0818
                  GO TO 67
0819
              ELSE IF (totalzs .GT. NYEARS) THEN
0820
                  print*, 'You have exceeded the life cycle of the
                  system --'
0821
                 print*, 'please check your numbers and try
                  again.'
0822
                  GO TO 67
0823
              ENDIF
0824
0825
        C
              Assign the Z(I) values to their correct position in
              the array
              CE(I,J) for later use within the program.
0826
        С
0827
0828
              DO 16 I=1,20
                  CE(J,I)=Z(I)
0829
0830
           16 CONTINUE
0831
0832
              If cost element J is a "constant" then cost element
        С
              J in
0833
        С
              A(I,J) will be the same for all NRV values of
              A(I,J)
0834
0835
              IF(Z(1) .EQ. 1.0) THEN
                  DO 25 I=1,NRV
0836
0837
                     A(I,J)=Z(2)
0838
           25
                  CONTINUE
0839
              If cost element J is a "random variable" then
0840
              determine
              if the random variable is from either the beta or
0841
        С
              triang
0842
              distribution and make the corresponding subroutine
        C
              call.
0843
```

```
0844
              ELSE IF(Z(1) .EQ. 2.0) THEN
0845
                  IF (Z(20) .EQ. 1.0) THEN
                     CALL BETA(J,A,NRV,NCOST)
0846
0847
                  ELSE IF (Z(20) \cdot EQ \cdot 2.0) THEN
                     CALL TRIAG(J,A,NRV,NCOST)
0848
0849
                  ELSE
0850
                  ENDIF
0851
               If cost element J is a "CER" then AAA and AA are
0852
        С
               calculated
0853
        C
              before calling the subroutine CER. AAA sums the
              number of
0854
               slope parameters plus the intercept term (if
        C
               applicable).
0855
               AA is 3 times AAA for later use with the array
        C
              XSTAR.
0856
0857
               ELSE IF(Z(1) .EQ. 3.0) THEN
0858
                 AAA=Z(10) + Z(11)
                 AA=3.0 * AAA
0859
                 CALL CER (J, A, NRV, NCOST, BET, AAA, XSTAR, AA,
0860
                 XCER, LASTSET,
0861
              lnumcer, super)
0862
              ELSE
0863
               ENDIF
0864
          100 CONTINUE
0865
              ENDIF
0866
0867
               Store the just input data set into the file
        С
               INPUTLCC.DAT.
0868
0869
               REWIND 01
0870
               write(01,101) NCOST, NYEARS, DISCOUNT
0871
          101 FORMAT(I3,1X,I3,1X,F4.3)
               DO 102 I = 1,NCOST
0872
                  DO 103 J = 1,20
0873
0874
                     write (01,104) CE (I,J)
0875
          104
                     FORMAT(F18.4)
0876
          103
                  continue
0877
          102 continue
0878
0879
               If the last data set was used, the following
        C
               statements call
               all of the same subroutines as shown above.
0880
        С
               are called
               here to make sure any changes made to the data have
0881
        С
               been
0882
               saved before the changed data is used in
        C
               calculating the NRV
0883
        C
               costs of the system.
0884
0885
               IF (lastset .EQ. .TRJE.) THEN
```

```
0886
                  nc = 0
                  DO 130 iredo = 1, NCOST
0887
0888
                  Put the data from the array CE(I,J) into the
0889
        С
                  array Z(I).
0890
                  This is done NCOST times -- once for each cost
        С
                  element.
0891
0892
                     DO 131 k = 1, 20
0893
                        Z(k) = CE(iredo,k)
0894
          131
                     continue
0895
                  IF (Z(1) . EQ. 1.0) THEN
0896
                  Put the value of the constant into the array A.
0897
0898
0899
                     DO 132 i = 1, NRV
0900
                       A(i, iredo) = Z(2)
0901
          132
                     continue
0902
                  ELSE IF (Z(1) . EQ. 2.0) THEN
0903
              Cost element iredo is a random variable generated by
0904
        С
              either the
0905
              Beta or Triangular distribution, depending on the
        С
              value of Z(20). 0906
0907
                     IF (Z(20) .EQ. 1.0) THEN
0908
                        CALL BETA (iredo, A, NRV, NCOST)
0909
                     ELSE
0910
                        CALL TRIAG (iredo, A, NRV, NCOST)
0911
                     ENDIF
0912
                  ELSE
0913
                     nc = nc + 1
0914
                     numcer = nc
0915
                     AAA = Z(10) + Z(11)
                     AA = 3.0 * AAA
0916
                     CALL CER (iredo, A, NRV, NCOST, BET, AAA,
0917
                     XSTAR, AA, XCER,
              1LASTSET, numcer, super)
0918
0919
                  ENDIF
0920
           130 continue
               ELSE
0921
0922
               ENDIF
0923
               if (ceredit .eq. .true.) then
0924
                  rewind 02
0925
                  do 850 i = 1, numcer
0926
                     n = ifix(super(i,505))
0927
                     do 851 j = 1, (n*n+n+1)
0928
                         write(02,852) super(i,j)
0929
           852
                         format(f31.16)
0930
           851
                     continue
0931
                     do 853 j = (n*n+n+2), (n*n+4*n+1)
0932
                         write(02,854) super(i,j)
0933
           854
                         format(f15.8)
```

```
0934
          853
                     continue
0935
                     do 855 j = (n*n+4*n+2), (n*n+5*n+1)
                        write(02,856) super(i,i)
0936
0937
          856
                        format(f5.3)
0938
          855
                     continue
0939
          850
                  continue
0940
              else
0941
              endif
0942
0943
        С
              TO CALCULATE THE LIFE CYCLE COST OF THE SYSTEM THE
        С
0944
              ELEMENTS OF MATRIX A(NRV, 20) MUST BE DISTRIBUTED
              OVER
0945
        C
              TIME. SUBROUTINE TRAP ACCOMPLISHES THIS.
0946
        C
              JJ IS THE RANDOM VARIABLE NUMBER WE ARE CURRENTLY
0947
        С
              WORKING ON, SO JJ=1 => OBSERVATION # 1 OR IN THE
0948
        С
              CASE OF A COST ELEMENT WHICH IS A RANDOM VARIABLE
0949
0950
              JJ=1 => RANDOM SAMPLE #1.
0951
0952
              JJ = 1
0953
              CALL TRAP (A, NRV, NCOST, CE, JJ, NYEARS)
0954
0955
        С
              COSTC(100) CONTAINS THE TOTAL OF THE CONSTANT COST
        С
0956
              ELEMENTS DISTRIBUTED OVER 100 YEARS.
0957
        С
              COSTR(100) CONTAINS THE TOTAL OF THE COST ELEMENTS
0958
        С
              WHICH ARE RANDOM COST COMPONENTS MODELED AS BETA
0959
        С
              DISTRIBUTIONS.
0960
0961
        С
              TRANSFER COSTC(100) TO PROTECTED STORAGE
               [STORE (100)]
        С
               SINCE WE NEED IT REPEATEDLY.
0962
0963
0964
               DO 105 I=1, NYEARS
0965
                  STORE(I)=COSTC(I)
0966
          105 CONTINUE
0967
0968
        C
               ADD COSTC(I) TO COSTR(I) FOR EACH YEAR.
0969
0970
               DO 110 I=1, NYEARS
0971
                  COST(I) = COSTC(I) + COSTR(I)
0972
          110 CONTINUE
0973
0974
        C
               CALCULATE THE LIFE CYCLE COST FOR OBSERVATION # 1
0975
0976
               T1=0.0
0977
               X=0.0
0978
               DO 120 I=1, NYEARS
0979
                  T1 = T1 + 1.0
0980
                  X=X + (COST(I)/((1.0 + DISCOUNT)**T1))
0981
          120 CONTINUE
0982
               LC(1)=X
0983
```

```
0984
        C
              CALCULATE THE LIFE CYCLE COST FOR OBSERVATION # 2
              THRU
0985
        С
              NRV
0986
              DO 140 I1 = 2, NRV
0987
0988
                  JJ = JJ + 1
                  CALL TRAP(A, NRV, NCOST, CE, JJ, NYEARS)
0989
0990
                  DO 125 I = 1, NYEARS
                     COST(I) = STORE(I) + COSTR(I)
0991
          125
0992
                  CONTINUE
0993
        С
               CALCULATE LIFE CYCLE COST: OBSERVATIONS #2 THRU #
0994
              NRV
0995
                  T1 = 0.0
0996
                  X = 0.0
0997
                  DO 127 I = 1, NYEARS
0998
0999
                     T1 = T1 + 1.0
1000
                     X = X + (COST(I) / ((1.0 + DISCOUNT) **T1))
                  CONTINUE
1001
          127
1002
                  LC(I1) = X
1003
          140 CONTINUE
1004
1005
               Place the values calculated for the NRV LC(I)
        С
               values
1006
               into the file LCCOST.DAT.
1007
1008
               WRITE(05,151) (LC(I),I=1,NRV)
1009
          151 FORMAT(8(2X,F19.0))
1010
               STOP
1011
               END
```

PROGRAM SECTIONS

ENTRY POINTS

| Address | Type | Name | References |
|-----------|------|------|------------|
| 0-0000000 | | LCC | 5# |

VARIABLES

| Address Ty | pe Name | Referenc | ces | | |
|--------------|-----------|-------------|-------------|------|------|
| 2-0002956C R | | 859= | 860A | 916= | 917A |
| 2-00029568 R | *4 AAA | 858= 916 | 859 917A | 860A | 915= |
| 2-00029564 R | *4 ANSWER | 652= 664 | 653 | 657= | 658 |
| 2-0002950C R | *4 ASKED | 61= | 65A | 66 | 128= |

```
129A
                                                130
                                                            140=
                                                                     141A
                                                165=
                                                            166A
                                                                     167
                                    142
                                                                     224=
                                    191=
                                                194A
                                                            195
                                                                     234A
                                    225A
                                                 226
                                                            231=
                                                             330A
                                                                     331
                                                 327=
                                    235
                                                                     417=
                                     336=
                                                 339A
                                                             340
                                                             426=
                                                                     429A
                                     420A
                                                 421
                                     430
                                                 437=
                                                             438A
                                                                     439
                                                 503A
                                                             504
                                                                     514=
                                     500=
                                                 517
                                                             627=
                                                                     630A
                                     516A
                                                                     657
                                                             656A
                                                 653 =
                                     631
                                                                     738=
                                                 731A
                                                             732
                                     728=
                                                             748=
                                                                     749A
                                     739A
                                                 740
                                     750
                                                 760=
                                                             761A
                                                                     762
                                                             506=
                                                                     923
                    CEREDIT
                                                  46=
2-000294F8
              L*4
                                       6
                                      84=
                                                                     587=
                    DISCOUNT
                                                 158
                                                             171=
2-00029520
              R*4
                                                            1000
                                     870
                                                 980
                                                                     129A
2-000294F0
              L*4
                    FOUND
                                       6
                                                  64=
                                                              65A
                                     141A
                                                 166A
                                                             194A
                                                                     225A
                                                             339A
                                                                     420A
                                     234A
                                                 330A
                                                                     516A
                                     429A
                                                 438A
                                                             503A
                                                             731A
                                                                     739A
                                     630A
                                                 656A
                                     749A
                                                 761A
              L*4
                    GOT
                                                 523=
                                                             525
                                                                     527=
                                       6
     * *
              R*4
                    HIGHOUT
                                     466=
                                                 469
              I * 4
                                                  49
                                                              86=
                                                                      88
                                      47=
     * *
                    I
                                                                     592=
                                      92=
                                                  93
                                                              95(2)
                                     593
                                                 595=
                                                             597
                                                                     600=
                                     601
                                                 612=
                                                             613
                                                                     828=
                                                             837
                                                                     872=
                                     829(2)
                                                 836=
                                     874
                                                 899=
                                                             900
                                                                     925=
                                                             932
                                                                     936
                                                 928
                                     926
                                     964=
                                                 965(2)
                                                             970 = 971(3)
                                                             990 = 991(3)
                                     978=
                                                 980
                                                1000
                                                            1008(2) =
                                     998=
2-00029580
              I*4
                    Il
                                     987=
                                                1002
                                                             540
     **
              I * 4
                    IBEG
                                     536=
                                                 538=
2-00029550
              I * 4
                    ICHANGE
                                     499=
                                                 500
                                                             504 =
                                                                     505
                                     508
                    IEYE
                                                             185
                                                                      198
2-0002952C
              I * 4
                                     175=
                                                 182
                                                 357
                                                             556
                                     275
                                                             639
2-0002955C
              I * 4
                    ΙI
                                     608=
                                                 618
              I * 4
                                                  97
                                                              98
                                                                   1CO(2)
2-00029524
                    III
                                      96≠
                                                 104
                                                             460 =
                                                                      461
                                     101
                                                 480
                                     477
                                                             900
                                                 893
                                                                      908A
2-00029574
              I*4
                    IREDO
                                     887=
                                     910A
                                                 917A
               I * 4
                    ISTART
                                     457=
                                                 465
                                                             466
                                                                      472
     **
                                                             482
                                                                      486
                                     474
                                                 478
                                     494(2)=
                                                              87=
2-00029504
               I * 4
                    J
                                      48=
                                                  49
                                                                       88
                                                             596=
                                                                      597
                                     181=
                                                 182(2)
```

```
599=
                                                601
                                                            603=
                                                                    604
                                    607=
                                                615(2) =
                                                            829
                                                                    837
                                                                    873=
                                    846A
                                                848A
                                                            860A
                                    874
                                                927=
                                                            928
                                                                    931=
                                    932
                                                935=
                                                            936
2-0002953C
              T*4
                   JAY
                                    254=
                                                255(2)
                                                            257 258(2)=
                                    261
                                                262(2)
                                                            263(2) = 269
                                    275(2)
                                                            347 353(2) =
                                                346=
                                    355
                                                357(2)
                                                            436=
                                                                    437
                                    439=
                                                440
                                                            445(2)
                                    446(2) =
                                                449
                                                            450(2)
                                                            455
                                                                 556(2)
                                    451(2) =
                                                454
2-00029558
              I * 4
                                                514
                   JAYCD
                                    513=
                                                            517=
                                                                    520
                                    526(2)
                                                            541(2)
                                                540
                                    542(2)
                                                543
                                                            544(2)
                                    545(2)
                                                549(2)
2-0002957C
              I * 4
                    JJ
                                    952=
                                                953A
                                                           988(2) = 989A
              I * 4
                    JJJ
                                    508=
    \star\star
2-00029534
              I * 4
                   K
                                    249=
                                                342 =
                                                            432 =
                                                                    892=
                                    893(2)
    * *
              I * 4
                    KK
                                    458=
                                                464
                                                            467
                                                                    469
                                    472
                                                474
                                                            478
                                                                    481
                                    483
                                                486
                                                            493(2) =
2-000294F4
              L*4
                    LASTSET
                                      6
                                                 67=
                                                            111=
                                                                    860A
                                    885
                                                917A
    * *
              I * 4
                    LL
                                    522=
                                                530(2) =
                                                            540
    **
              I*4
                    M
                                    524=
                                                526(2)
                                                            529(2) =
2-00029514
              I*4
                   MAX
                                     63=
                                                 65A
                                                            129A
                                                                    141A
                                    166A
                                                193=
                                                            194A
                                                                    225A
                                    233=
                                                234A
                                                            329=
                                                                    330A
                                    338=
                                                339A
                                                            419=
                                                                    420A
                                    428=
                                                429A
                                                            438A
                                                                    502=
                                    503A
                                                511
                                                            516A
                                                                    629=
                                                655=
                                    630A
                                                            656A
                                                                    730=
                                    731A
                                                739A
                                                            749A
                                                                    759=
                                    761A
2-00029510 I*4
                   MIN
                                     62=
                                                 65A
                                                            129A
                                                                    141A
                                    166A
                                                192=
                                                            194A
                                                                    225A
                                    232=
                                                234A
                                                            328=
                                                                    330A
                                    337=
                                                339A
                                                            418=
                                                                    420A
                                    427=
                                                429A
                                                            438A
                                                                    501=
                                    503A
                                                515=
                                                            516A
                                                                    628=
                                                654=
                                                                    729=
                                    630A
                                                            656A
                                    731A
                                                739A
                                                            749A
                                                                    758=
                                    761A
     **
              T * 4
                    N
                                     95=
                                                 96(3)
                                                             97(3)
                                    100(6)
                                                456=
                                                            457(3) 400
                                    477(3)
                                                480(3)
                                                            502
                                                                    507
                                    526(2)
                                                540(3)
                                                            542(3)
                                    545(3)
                                                549(3)
                                                            926=
                                    927(3)
                                                931(6)
                                                            935(6)
2-00029570
              I * 4
                    NC
                                    886=
                                                913(2) =
                                                            914
```

| 2-00029518 | I*4 | NCOST | | 84= | 86 | 92 | 175 |
|------------|--------|----------|-------|-----------------|---------|-----------|---|
| | | | | 82= | 595 | 599 | 608 |
| | | | | 46A | 848A | 860A | 870 |
| | | | | 72 | 887 | 908A | 910A |
| | | | | 17A | 953A | 989A | J 2 01. |
| 2-000294FC | I*4 | NRV | | 12D | 592 | 600 | 836 |
| 2 00023110 | | | | 46A | 848A | 860A | 899 |
| | | | | 08A | 910A | 917A | 953A |
| | | | | 87 | 989A | 1008 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |
| 2-00029500 | I*4 | NUMCER | | 45 = | 94(2)= | | 101 |
| | | | | 04 | 112= | 184(2) | |
| | | | | 65 | 466 | 472 | 474 |
| | | | | 77 | 478 | 480 | • • • |
| | | | | 82 | 486 | 507 | 542 |
| | | | | 45 | 549 | 860A | 914= |
| | | | | 17A | 925 | 00011 | 72. |
| 2-00029530 | I*4 | NUMCHANG | | 30= | 231 | 235= | 236 |
| | | | | 49 | 335= | 336 | 340= |
| | | | | 41 | 342 | 425= | 426 |
| | | | | 30= | 431 | 432 | 420 |
| 2-0002951C | I*4 | NYEARS | | 84= | 133 | 147= | 266 |
| 2 00027020 | | | | 84= | 792 | 819 | 870 |
| | | | | 53A | 964 | 970 | 978 |
| | | | | 89A | 990 | 998 | 570 |
| 2-00029508 | R*4 | OLDNEW | | 60= | 61 | 66= | 77 |
| 2-0002954C | R*4 | RLOWOUT | | 65= | 467 | 00 | , , |
| ** | R*4 | RMODEOUT | | 82= | 483 | | |
| ** | R*4 | T1 | | 76= | 979(2)= | 980 | 996= |
| | | ** | | 99(2)= | 1000 | 700 | J J U |
| ** | R*4 | TOTALZS | | 14= | 819 | | |
| ** | R*4 | X | | 77= | 980(2)= | 982 | 997= |
| | 20 1 | | | 00(2)= | | JU2 | 551- |
| 2-00029528 | R*4 | YOR.1 | | 27= | 128 | 130= | 132 |
| 2 00023320 | * . | 1014 | | 39= | 140 | 142= | 144 |
| | | | | 64= | 165 | 167= | 168 |
| | | | | 90= | 191 | 195= | 197 |
| | | | | 23= | 224 | 226= | 227 |
| | | | | 26= | 327 | 331= | |
| | | | | 16= | 417 | 421= | |
| | | | 7 | 10- | 411 | 421- | 422 |
| ARRAYS | | | | | | | |
| Address | Туре | Name | Bytes | Dimen | sions | Referen | ces |
| 2-00001770 | R*4 | Α | 60000 | 1750 | 201 | 7 | 603- |
| 2-00001770 | T/ " # | A | 30000 | (750, | | 7 837= | 601= |
| | | | | | | | 846A |
| | | | | | | 848A | 860A |
| | | | | | | 900= | 908A |
| | | | | | | 910A | 917A |
| 2-00010B30 | R*4 | BET | 80 | (20) | | 953A | 989A |
| 2 00010050 | A(" 4 | ונעו | 00 | (20) | | 7 גלום | 860A |

917A

| 2-0001DF60 2-00010360 | R*4 R*4 | BORT CE | 80 1600 | (20) (20, 20) | 7 93 182 357= 597= 874 953A | 88= 95(2) 275= 556= 829= 893 989A |
|--------------------------|------------|------------|------------|------------------|---|---|
| 2-000101D0 | R*4 | COST | 400 | (100) | 7 971= | 604= 980 |
| 4-00000000 | R*4 | COSTC | 400 | (100) | 991 = 11 971 | 1000 965 |
| 4-00000190 | R*4 | COSTR | 400 | (100) | 11 991 | 971 |
| 2-00000000 | R*8 | LC | 6000 | (750) | 7 593= 1002= | 9 982= 1008 |
| 2-000109A0 | R*4 | STORE | 400 | (100) | 7 | 965= |
| 2-0001F720 | R*4 | SUPER | 40400 | (20, 505) | 991 7 98= 104= 466 474 478 482 507= 545= 860A 926 932 | 49= 101= 465 472 477 480 486 542= 549= 917A 928 |
| 2-00010C70 | R*4 | XCER | 60000 | (750, 20) | 7 917A | 860A |
| 2-00010B80 | R*4 | XSTAR | 240 | (60) | 7 541(2)= 544(2)= 549 917A | 520= 542 545 860A |
| 3-0000000 | R*4 | Z | 80 | (20) | 10 184 205 212 216 269= 281 295 299 307 313 317 | 182= 201 210 214 261= 275 285 297 305 310 315 319 |

| 355= 371 378 385 389 395 398 404 | 357 378 381 387 394 397 402 406 |
|---|--|
| 408 454= | 449= 456(2) |
| 464 | 430(2) |
| 521 | 535 |
| 556 | 613= |
| 626= | 627 |
| 631≕ | 633 |
| 642= | 643 |
| 658= | 669= |
| 672= 683= | 673 (2) 689= |
| 683= 692= | 689= 693(2) |
| 705= | 706(4) |
| 715 | 723= |
| 715 727= 732= | 728 |
| 732= | 737= |
| 738 | 740= |
| 747= | 748 |
| 750= | 751 |
| 757= | 760 |
| 762= 770= | 765= 772 |
| 775 | 772 780= |
| 796= | 800= |
| 803= | 800= 808= |
| 814(4) | 815(3) |
| 829 | 835 |
| 837 | 844 |
| 845 | 847 |
| 857 803- | 858(2) |
| 893= 900 | 895 902 |
| 900 | 915(2) |
| <i>.</i> . | 223(2) |

FUNCTIONS AND SUBROUTINES REFERENCED

| Type | Name | Refere | nces | | |
|------|------|--------|------|-----|-----|
| | ANS | 65 | 129 | 141 | 166 |
| | | 194 | 225 | 234 | 330 |
| | | 339 | 420 | 429 | 438 |
| | | 503 | 516 | 630 | 656 |
| | | 731 | 739 | 749 | 761 |
| | BETA | 846 | 908 | | |

| R*4 R*4 | • | 860 44 38 541 465 953 848 | 917 76 39 544 466 989 910 | 616 40 482 | |
|--|----------------------------------|--|---|------------------|---------------|
| 0001 0002 0003 | c Subi | routine ANS ma | kes sure th | e range o | f possible |
| 0004 | c ques | its to the stions posed to onse is | o the user | is met. | If the user's |
| 0005 | c outs | side of the mi | n and max v | alues, th | e loop is |
| 0006 | c an a | cinued until appropriate an able FOUND is | | en. The | logical |
| 0007 | c used | l as the flag | stating whe | ther an a | cceptable |
| 8000 | | oonse has been ained or not. | | | |
| 0009 0010 0011 0012 0013 0014 0015 0016 0017 0018 0019 0020 0021 0022 0023 | 1 IF (ELSI ENDI IF (III 10 I | <pre>found = .TRUE. IF (found .EQF print 10,min,m FORMAT(' Pleas to',I3) read*,asked GOTO 1 IF</pre> | n .OR. aske ALSE.) THEN ax | d .GT. ma | |
| ENTRY F | | | | | |
| | ress Type | Name | | Refere | nces |
| | 00000 | ANS | | 10# | |
| VARIABI | | | | n | |
| Add | ress Type | Name | References | ; | |
| | 00)00C@ R*4 | ASKED | 10 | 11(2) | 19= |

| AP-0 | 00000086 | I*4 | MAX | 10 | 11 11 | 17 17 | 10 | | |
|--|--------------------|--------------------|---|---------------|----------|-----------|-----------|--|--|
| LABEL | LABELS | | | | | | | | |
| A | ddress | Labe | 1 | | Ref | erences | | | |
| | 0000004 0000000 | 10' | | | | 11# 17 | 20 18# | | |
| 0001 0002 | С | the p | previous | is designed | | | reen of | | |
| 0003 | С | | rial. The inent to | purpose is so | only : | material | | | |
| 0004 0005 0006 0007 0008 0009 0010 | c 1 | SUBRODO 1 p: cont. | the user is in front of him/her. SUBROUTINE CLRSCR DO 1 i = 1, 23 print* continue RETURN | | | | | | |
| PROGR | AM SECTI | ONS | | | | | | | |
| ENTRY | POINTS | | | | | | | | |
| A | ddress ' | Туре | Name | | Ref | erences | | | |
| 0-0 | 0000000 | | CLRSCR | | | 6# | | | |
| VARIA | BLES | | | | | | | | |
| A | ddress | Type | Name | Attribute | s Ref | erences | | | |
| | ** | I*4 | I | | | 7= | | | |
| LABEL | S | | | | | | | | |
| A | ddress | Labe | 1 | | Ref | erences | | | |
| | ** | 1 | | | | 7 | 9# | | |
| 0001 0002 0003 | С | The samp | | Triag is desi | gned t | o get NRV | 'random | | |
| 0004 | С | | | ular distribu | tion. | The seed | for | | |

10

12= 14=

16

AP-00000010@ R*4 FOUND

```
rnset is set
0005
              to zero so that the seed is based upon the clock of
0006
              computer.
                          Random numbers are received based on the
        C
              uniform
0007
        C
              distribution within the range 0,1.
                                                    These random
              numbers are
8000
              then converted to the triangular distribution by
        C
              comparing
0009
              the random number against the variable FOFX.
        C
              represents
0010
        C
              the cumulative triangular distribution according to
              the data
              input by the user (contained in Z(3), Z(4), and
0011
        С
              Z(5)).
                       Z(3)
              corresponds to the low value of the triag distro,
0012
        C
              Z(4) the high
0013
              value, and Z(5) to the mode or best guess of the
        С
              triag
0014
        С
              distribution.
0015
0016
              SUBROUTINE TRIAG(J,A,NRV,NCOST)
0017
              DIMENSION A(NRV, NCOST)
0018
              COMMON /AA/ Z(20)
0019
              INTEGER ISEED
0020
              PARAMETER (NR=750)
0021
              REAL R(NR), FOFX, ALOW, BMID, CHIGH
0022
              EXTERNAL RNSET, RNUN
0023
              call rnset(0)
0024
0025
              The call to rnun gets nr uniformly distributed
        C
              values and
0026
        С
              puts them in the array r.
0027
0028
              call rnun(nr,r)
0029
              alow = \mathbb{Z}(3)
0030
              bmid = Z(5)
0031
              chigh = Z(4)
0032
        С
              If the LOW and HIGH values are equal then the value
              of this
              cost element is known for certain.
0033
        C
0034
              if (alow .eq. chigh) then
                  do 5 i = 1, nr
0035
0036
                     a(i,j) = alow
0037
                  continue
0038
              else
             FOFX represents the "break" point in the Triangular
0039
        С
             distribution.
0040
              If the random number generated equals fofx, assign
        С
              A(I,J) to the
              MODE, otherwise the corresponding equation is
0041
        C
              executed to
```

```
/ determine the value of A(I,J).
0042
                   fofx = ((bmid - alow)/(chigh - alow))
0043
0044
                   DO 10 i = 1, nr
                      IF (r(i) .EQ. fofx) THEN
   A(I,J) = bmid
0045
0046
                      ELSE IF (r(i) .LT. fofx) THEN
0047
0048
                       A(I,J) = (alow + SQRT(r(i)*(bmid -
                       alow)*(chigh - alow)))
0049
                      ELSE
0050
                         A(I,J) = (chigh - SQRT((chigh -
                         alow) * (chigh - bmid) *
0051
              1(1 - r(i)))
                      ENDIF
0052
                   continue
0053
            10
0054
               endif
0055
               RETURN
0056
               END
PROGRAM SECTIONS
ENTRY POINTS
                                                  References
    Address
              Type
                     Name
  0-00000000
                     TRIAG
                                                      16#
VARIABLES
    Address
              Type
                     Name
                                 References
       **
                                              29=
                                                         34
                                                                     36
               R*4
                     ALOW
                                   21
                                              48(3)
                                                         50
                                   43(2)
                                                         43
                                                                     46
       **
               R*4
                                   21
                                              30=
                     BMID
                                   48
                                              50
       **
               R*4
                     CHIGH
                                   21
                                              31=
                                                         34
                                                                     43
                                   48
                                              50(3)
       **
                R*4
                     FOFX
                                   21
                                              43=
                                                         45
                                                                     47
       * *
                                   35=
                                                         44 =
                                                                     45
                I*4
                     Ι
                                              36
                                   46
                                              47
                                                         48(2)
                                                                    50(2)
       **
                I * 4
                     ISEED
                                   19
 AP-00000004@ I*4
                                              36
                                                         46
                                                                     48
                                   16
                                   50
 AP-000000100 I*4
                     NCOST
                                   16
                                              17
 AP-0000000C@ I*4
                     NRV
                                   16
                                              17
ARRAYS
```

**

3000

Bytes Dimensions

(*, *)

(750)

References

17

48=

28A

36=

50=

45

16

21

46=

Address Type

AP-000000080 R*4

2-00000000 R*4

Name

Α

R

| 3-000 | 00000 | R*4 Z | 80 | (20) | 47 18 31 | 48 29 | 50 30 |
|--|-------------------------|---|---|---|---|----------------|----------|
| PARAMET | ER CON | STANTS | | | | | |
| Туре | Name | | Refe | rences | | | |
| I*4 | NR | | 20# 44 | 21 | 28 | 35 | |
| LABELS | | | | | | | |
| Add | lress | Label | | | Referenc | es | |
| | : * | 5 10 | | | 35 44 | 37# 53# | |
| FUNCTIO | NS AND | SUBROUTINES : | REFEREN | CED | | | |
| Type | Name | | | | Referenc | es | |
| R*4 | MTH\$S RNSET RNUN | | | | 48 22 22 | 50 23 28 | |
| 0001 0002 0003 0004 0005 0006 0007 0008 0009 0010 0011 0012 0013 0014 0015 0016 0017 0018 0019 0020 0021 | c c | else fofx = ((do 10 i = if (r(r(i | for us riagl(j d r=750) ofx,xlo et,rnun) ,r) . xhigh l,nr xlow xmode - l,nr i) .eq.) = xmo | e when a one of the whole of | cost driver gh,xmode,nr mode nigh - xlow | is a rand | |

| 0023 | r(i) = (xlow + SQRT(r(i)*(xmode - |
|------|-----------------------------------|
| | xlow)*(xhigh - xlow))) |
| 0024 | else |
| 0025 | r(i) = (xhigh - SQRT) |
| | ((xhigh-xlow)*(xhigh-xmode)* |
| 0026 | 1(1-r(i)))) |
| 0027 | endif |
| 0028 | 10 continue |
| 0029 | endif |
| 0030 | return |
| 0031 | end |

ENTRY POINTS

| Address | Туре | Name | R | eferences |
|-----------|------|--------|---|-----------|
| 0-0000000 | | TRIAG1 | | 5# |

VARIABLES

| Address | Туре | Name | Referen | ces | | |
|-------------|-------|-------|-----------|----------|--------------|-------------|
| ** | R*4 | FOFX | 8 | 18= | 20 | 22 |
| ** | I*4 | I | 14= 21 | 15 22 | 19= 23(2) | 20 25(2) |
| ** | I*4 | ISEED | 6 | | ` ' | ` ' |
| AP-00000004 | @ I*4 | J | 5 | | | |
| AP-00000014 | @ I*4 | NRV | 5 | | | |
| AP-0000000C | @ R*4 | XHIGH | 5 | 8 | 13 | 18 |
| | | | 23 | 25(3) | | |
| AP-00000008 | 0 R*4 | XLOW | 5 | 8 | 13 | 15 |
| | | | 18(2) | 23(3) | 25 | |
| AP-00000010 | 0 R*4 | XMODE | 5 | 8 | 18 | 21 |
| | | | 23 | 25 | | |

ARRAYS

| Address Type | Name | Bytes | Dimensions | Refer | rences |
|------------------|------|-------|------------|--------------------------------|---------------------------|
| AP-00000018@ R*4 | R | 3000 | (750) | 5 12A 20 22 25(2)= | 8 15= 21= 23(2)= |
| | | | | , , | |

PARAMETER CONSTANTS

Type Name References

| I*4 | NR | | 7# 19 | 8 | 12 | 14 |
|--|--------------------------|---|---|--|--------------|----------------|
| LABELS | | | | | | |
| Add | ress | Label | | | References | |
| | * | 5 | | | 14 | 16# |
| * | * | 10 | | | 19 | 28# |
| FUNCTIO | NS AND | SUBROUTINES REF | ERENCE | • | | |
| Type | Name | | | | References | |
| R*4 | MTH\$S(RNSET RNUN | QRT | | | 23 9 9 | 25 11 12 |
| 0001 0002 0003 0004 0005 0006 0007 0008 0009 0010 0011 0012 0013 0014 0015 0016 0017 0018 0019 0020 0021 0022 0023 0024 0025 0027 0028 0029 0030 | C c | SUBROUTINE BETA DIMENSION A (NRV COMMON /AA/ Z (2 INTEGER ISEED PARAMETER (NR=7 REAL PIN,QIN,R) EXTERNAL RNBET, CHECK FOR TYPE corresonds to Alpha whereas (2 IF(Z(5).EQ.1.0) PIN=2.5 QIN=1.5 ELSE IF(Z(5).EQ PIN=2.35 QIN=2.35 ELSE IF(Z(5).EQ PIN=1.5 QIN=2.5 ELSE IF(Z(5).EQ PIN=1.5 QIN=2.5 ELSE IF(Z(5).EQ PIN=3.75 QIN=3.75 QIN=3.75 QIN=3.75 ELSE IF(Z(5).EQ PIN=3.75 QIN=3.75 ELSE IF(Z(5).EQ PIN=2.0 QIN=4.0 | 7,NCOST) 20) 750) (NR) ,RNSET OF BETA QIN COTA () THEN Q.2.0) (Q.3.0) (Q.4.0) | A DISTRIE CESPONDS THEN THEN THEN THEN | | |

```
ELSE IF(Z(5).EQ.7.0) THEN
0032
0033
                  PIN=5.5
                  QIN=2.5
0034
               ELSE IF(Z(5).EQ.8.0) THEN
0035
                  PIN=5.0
0036
0037
                  QIN=5.0
               ELSE IF(Z(5).EQ.9.0) THEN
0038
0039
                  PIN=2.5
                  QIN=5.5
0040
               ELSE
0041
               ENDIF
0042
0043
               CALL RNSET(0)
0044
               CALL RNBET (NR, PIN, QIN, R)
0045
               DO 10 I=1,NR
0046
                  A(I,J)=Z(3)+((Z(4)-Z(3))*R(I))
0047
            10 CONTINUE
0048
0049
               RETURN
               END
0050
```

ENTRY POINTS

Address Type Name References
0-00000000 BETA 3#

VARIABLES

| Address | Туре | Name | Referenc | es | | |
|--------------|-------|-------|----------|-------|-----|-----|
| ** | I*4 | I | 46= | 47(2) | | |
| ** | I*4 | ISEED | 6 | | | |
| AP-00000004@ | I * 4 | J | 3 | 47 | | |
| AP-00000010@ | I*4 | NCOST | 3 | 4 | | |
| AP-0000000C@ | I * 4 | NRV | 3 | 4 | | |
| 2-00000BB8 | R*4 | PIN | 8 | 15= | 18= | 21= |
| | | | 24= | 27= | 30≂ | 33= |
| | | | 36= | 39= | 45A | |
| 2-00000BBC | R*4 | QIN | 8 | 16= | 19= | 22= |
| | | | 25= | 28= | 31= | 34= |
| | | | 37= | 40= | 45A | |
| | | | | | | |

ARRAYS

| Address Ty | pe Nam | e Bytes | Dimensions | References | |
|----------------|--------|---------|------------|------------|----|
| AP-000000080 R | *4 A | ** | (*, *) | 3 47= | 4 |
| 2-00000000 R | *4 R | 3000 | (750) | • • | 5A |

| 3-000 | 00000 | R*4 Z | | 80 | (20) | | 47 5 17 23 29 35 47(3) | 14 20 26 32 38 |
|--|----------------|--|---|---|--|-----------------------|--|----------------------------|
| PARAMET | ER CON | STANTS | | | | | | |
| Type | Name | | Refe | renc | es | | | |
| I*4 | NR | | 7# | | 8 | 45 | 46 | |
| LABELS | | | | | | | | |
| Add | lress | Label | | | | Refere | nces | |
| * | ·* | 10 | | | | 46 | | 48# |
| FUNCTIO | NS AND | SUBROUT | INES REFE | RENC | ED | | | |
| Туре | Name | | | | | Refere | nces | |
| | RNBET RNSET | | | | | 9 9 | | 45 44 |
| 0001 0002 0003 0004 0005 0006 0007 0008 0009 0010 0011 0012 | 0 000 | OVER TIME USING TO USING TO USING TO USING TO USING TO USE | ME RAPEZOID HE OBSERV RANDOM VA ION. INE TRAP(ON A(NRV, 100), PHA 00), COSTE PRECISION MCON(20,1 | RULE VATIO ARIAE (A, NF NCOS ACON(R(100 I VAI | CS. ON WE ARE BLES IS ' RV, NCOST ST), CE(2 (100), PH O) JUE, X, Y MRAND(2 | , | Y WORKI LLOWED ARS) 00),DEI | FOR THE |
| 0014 | c c | CE(*,20 MCON(*, |), | MRAN | | OST ELEMEN). REPLACE | | |
| 0016 0017 | С | COST EL | | | | | | |
| 0018 0019 | | COMMON | /AB/ COS | STC,C | COSTR | | | |
| 0020 | С | COSTC(1 | 00) : cos | T AC | CUMULAT | OR FOR THE | CONSTA | NT COST |

```
ELEMENTS.
0021
        С
              COSTR(100): COST ACCUMULATOR FOR THE RANDOM
              COMPONENTS.
0022
0023
        C
              CLEAK THE ARRAYS COSTC(100) AND COSTR(100). NOTE:
              THIS ALSO CLEARS THEM IN THE COMMON BLOCK. THE
0024
        C
              FIRST
        С
              STATEMENT AFTER THE CALL STATEMENT IN THE
0025
              MAINPROGRAM
0026
       С
              SHOULD BE TO TRANSFER COSTC(100) TO PROTECTED
              STORAGE.
U027
              DO 2 I=1, NCOST
0028
0029
              DO 2 J=1,100
0030
                 MCON(I,J)=0.0
0031
                 MRAND(I,J)=0.0
0032
            2 CONTINUE
0033
              DO 3 I=1,100
0034
                 COSTC(I) = 0.0
0035
                 COSTR(I) = 0.0
0036
            3 CONTINUE
0037
0038
        С
              THE CURRENT VALUE OF EACH COST ELEMENT IS
              DISTRIBUTED
0039
        C
              OVER TIME. THE NEXT DO STATEMENT ACCOMPLISHES THIS.
0040
        С
             AFTER THE EXIT POINT THE COST ELEMENTS ARE STORED IN
0041
       С
              EITHER THE CONSTANT COST ACCUMULATOR [COSTC(100)]
       С
0042
              OR THE RANDOM COST ACCUMULATOR [COSTR(100)]
0043
0044
              DO 500 I=1, NCOST
0045
       С
0046
              THE CONSTANT COST ELEMENTS PASS THROUGH THE PROGRAM
0047
       С
              ONLY ONE TIME SINCE ONCE CALCULATED THEY REMAIN THE
0048
              SAME FOR ALL NRV ITERATIONS.
0049
0050
              IF(JJ.EQ.1) GO TO 5
0051
              IF(CE(I,1).EQ.1.0) GO TO 500
            5 VALUE=A(JJ,I)
0052
0053
              A1=CE(I,6)
0054
              C1=CE(I,7)
0055
              D1=CE(I,8)
              START=CE(I,9)
0056
0057
              TT=A1 + C1 + D1
0058
              N2=IFIX(TT)
0059
              NN1=IFIX(A1)
0060
              NN2=IFIX(C1)
0061
              NN3=IFIX(D1)
0062
       C Z1 IS THE % OF THE TOTAL AREA UNDER THE TRAPEZOID IN THE
0063
0064
       С
             FIRST TRIANGLE ( PHASE IN).
0065
        С
             Z2 IS THE % OF THE TOTAL AREA UNDER THE TRAPEZOID IN
THE
```

```
0066
             RECTANGULAR REGION ( CONSTANT COST PER YEAR).
0067
       C Z3 IS THE % OF THE TOTAL AREA UNDER THE TRAPEZOID IN THE
0068
             RIGHT HAND TRIANGLE ( PHASE OUT).
0069
0070
              Z1 = A1/(A1 + \nu1 + (2.0 * C1))
0071
              Z2 = C1/(.50 * (A1 +D1+(2.0*C1)))
              Z3 = D1/(A1 + D1 + (2.0*C1))
0072
0073
        C
              PHASE IN ALLOCATION.
        С
              CHECK FOR THE EXISTENCE OF THE FIRST TRIANGLE.
0074
0075
0076
              IF(A1.NE.O.O) THEN
0077
                  B=2.0/A1
0078
              ELSE
0079
                  GO TO 50
0800
              ENDIF
0081
        С
              THE ALLOCATION FOR CONSTANT COST STARTS AT
0082
              STATEMENT # 50
0083
0084
              N1=IFIX(A1)
0085
0086
        C
           IF ALL OF THE AREA IS IN THE TRIANGLE ON THE RIGHT AND
0087
        C
              THERE IS ONE COST ELEMENT THEN YOU ARE DONE WITH
              THE COST
8800
        C
              ALLOCATION FOR THIS COST ELEMENT.
0089
0090
              IF (Z1 .EQ. 1.0 .AND. A1 .EQ. 1.0) THEN
0091
                  PHASIN(1) = VALUE
0092
                  GO TO 300
0093
              ELSE IF (A1 .EQ. 1.0 .AND. Z1 .NE. 1.0) THEN
0094
                  PHASIN(1) = Z1 * VALUE
0095
                  GO TO 50
              ELSE
0096
0097
              ENDIF
0098
              DO 10 II=1,N3
0099
                  DD = FLOAT(II)
0100
                  ZZ(II) = (DD*B)/A1
0101
           10 CONTINUE
0102
               DO 20 II = 1,N1-1
0103
                  DD = FLOAT(II)
                  DEL(II) = 0.50 * (ZZ(II)*DD)
0104
0105
           20 CONTINUE
0106
              X = DEL(1)
0107
               IF (N1-1 .LT. 2) GO TO 26
               DO 25 II = 2,N1-1
0108
0109
                  DEL(II) = DEL(II) - X
0110
                  X = X + DEL(II)
0111
           25 CONTINUE
0112
           26 DEL(N1) = 1.0 - X
0113
0114
        С
               COST COMPONENT MULTIPLIERS
0115
```

```
0116
              DO 27 II=1,N1
0117
                  ZZ(II) = DEL(II) * Z1
0118
           27 CONTINUE
0119
0120
        С
              CALCULATE THE COST DISTRIBUTION FOR THE PHASE IN
              PERIOD
        C
0121
              AND STORE IN PHASIN(100)
0122
0123
              DO 29 II=1,N1
0124
                  PHASIN(II) = ZZ(II) * VALUE
0125
           29 CONTINUE
0126
0127
        С
              CONSTANT COST PART OF THE TIME HORIZON.
              CHECK FOR THE EXISTENCE OF THE RECTANGULAR REGION
0128
        C
0129
              OF THE TRAPEZOID.
0130
0131
           50 IF (C1 .EQ. 0.0) GO TO 100
0132
              DISTRIBUTE COST OVER THE RECTANGULAR REGION.
0133
        C
0134
0135
              X = (Z2/C1) * VALUE
0136
              N1 = IFIX(C1)
              DO 55 II = 1,N1
0137
0138
                  PHACON(II) = X
0139
           55 CONTINUE
0140
0141
              CONSTANT COST PART OF TRAPEZOID IS COMPLETE.
0142
        С
              CALCULATE THE PHASEOUT PART OF THE COST ALLOCATION.
0143
              CHECK FOR THE EXISTENCE OF A PHASE OUT PERIOD.
0144
0145
0146
          100 IF (D1 .EQ. 0.0) GO TO 300
0147
              B = 2.0/D1
              N1 = IFIX(D1)
0148
0149
0150
        C
              IF ALL OF THE AREA IS IN THE PHASE OUT TRIANGLE AND
0151
        С
              THERE IS ONE COST ELEMENT YOU ARE DONE WITH THE
               COST
0152
              ALLOCATION FOR THIS COST ELEMENT.
        C
0153
0154
               IF (Z3 .EQ. 1.0 .AND. D1 .EQ. 1.0) THEN
0155
                   PHAOUT(1) = VALUE
0156
                   GO TO 300
              ELSE IF (D1 .EQ. 1.0 .AND. Z3 .NE. 1.0) THEN
0157
0158
                   PHAOUT(1) = Z3 * VALUE
0159
                   GO TO 300
0160
              ELSE
0161
              ENDIF
0162
              DO 110 II = 1,N1
0163
                  DD = FLOAT(II)
0164
                  ZZ(II) = (DD*B)/D1
0165
          110 CONTINUE
```

```
0166
              DO 120 II = 1,N1-1
0167
                  DD = FLOAT(II)
0168
                  DEL(II) = .50 * (ZZ(II)*DD)
0169
          120 CONTINUE
0170
              X = DEL(1)
              IF (N1-1 .LT. 2) GO TO 126
0171
              DO 125 II = 2,N1-1
0172
0173
                  DEL(II) = DEL(II) - X
0174
                  X = X + DEL(II)
0175
          125 CONTINUE
0176
          126 DEL(N1) = 1.0 - X
0177
               DO 127 II = 1,N1
0178
                  ZZ(II) = DEL(II) * Z3
0179
          127 CONTINUE
0180
0181
        C
              CALCULATE THE COST DISTRIBUTION FOR THE PHASE OUT
        C
0182
              PERIOD AND STORE IN PHAOUT(100).
0183
0184
              J1 = N1
               DO 129 II = 1,N1
0185
0186
                  PHAOUT(II) = ZZ(J1) * VALUE
0187
                  J1 = J1 - 1
0188
          129 CONTINUE
0189
               STATEMENT #300 FINISHES THE COST ALLOCATION BY
0190
        C
0191
        C
               TRAPEZOID SECTOR. THE NEXT BLOCK LINKS THE SEGMENTS
        C
0192
               OF THE TRAPEZOID SEQUENTIALLY AND THE WHOLE
               STRUCTURE
0193
               IS SHIFTED TO THE STARTING POINT (DEFINED BY
               VARIABLE
0194
        C
              START)
0195
          300 CONTINUE
0196
0197
               DO 301 II = 1,100
0198
                  ZZ(II) = 0.0
0199
          301 CONTINUE
0200
               IF (Z1 .EQ. 1.0) THEN
0201
                   DO 305 II = 1,NN1
0202
                      ZZ(II) = PHASIN(II)
          305
0203
                   CONTINUE
0204
                   GO TO 350
               ELSE
0205
0206
                   SUM = Z1 + Z2
               ENDIF
0207
0208
               IF (SUM .EQ. 1.0) THEN
0209
                  DO 306 II = 1,NN1
                     ZZ(II) = PHASIN(II)
0210
          306
                  CONTINUE
0211
0212
                  J1 = 1
0213
                   NEND = NN1 + NN2
                   DO 307 II = NN1+1, NEND
0214
0215
                      ZZ(II) = PHACON(J1)
```

```
0216
                      J1 = J1 + 1
          307
                   CONTINUE
0217
0218
                   GO TO 350
               ELSE
0219
0220
               ENDIF
               SUM = Z1 + Z3
0221
0222
               IF (SUM .EQ. 1.0) THEN
0223
                  DO 310 II = 1,NN1
0224
                     ZZ(II) = PHASIN(II)
0225
          310
                  CONTINUE
0226
                   J1 = 1
                   NEND = NN1 + NN3
0227
0228
                   DO 311 II = NN1+1, NEND
0229
                      ZZ(II) = PHAOUT(J1)
0230
                      J1 = J1+1
0231
          311
                   CONTINUE
0232
                   GO TO 350
0233
               ELSE
0234
               ENDIF
0235
        С
               AT THIS POINT A FULL TRAPEZOID MUST EXIST.
0236
0237
0238
               DO 315 II=1,NN1
0239
                  ZZ(II)=PHASIN(II)
0240
           315 CONTINUE
0241
               J1 = 1
0242
               NEND = NN1 + NN2
0243
               DO 316 II = NN1+1, NEND
                  ZZ(II) = PHACON(J1)
0244
0245
                  J1 = J1+1
           316 CONTINUE
0246
0247
               J1 = 1
               DO 317 II=NEND+1, N2
0248
0249
                  ZZ(II) = PHAOUT(J1)
0250
                  J1 = J1+1
0251
           317 CONTINUE
0252
0253
               SHIFT THE STRUCTURE TO THE STARTING POSITION.
0254
0255
           350 CONTINUE
0256
0257
        C
               IF COST ELEMENT IS OF CONSTANT COST TYPE PUT IN
               MCON(20,100)
               NOTE: 20 COST ELEMENTS BY 100 YEARS FOR THE SYSTEM.
0258
0259
0260
               IF (CE(I,1) \cdot EQ \cdot 1.0) THEN
0261
                  JSTRT = IFIX(START)
0262
                  DO 355 II = 1,N2
0263
                     JSTRT = JSTRT + 1
0264
                     MCON(I, JSTRT) = ZZ(II)
0265
           355
                  CONTINUE
               ELSE
0266
```

```
ENDIF
0267
0268
        С
              IF COST ELEMENT IS OF RANDOM COST TYPE PUT IN
0269
              MRAND(20,100)
        С
              NOTE: 20 COST ELEMENT BY 100 YEARS FOR THE SYSTEM.
0270
0271
              IF (CE(I,1) . EQ. 2.0 . OR. CE(I,1) . EQ. 3.0) THEN
0272
                 JSTRT = IFIX(START)
0273
                 DO 360 II = 1,N2
0274
0275
                    JSTRT = JSTRT + 1
0276
                    MRAND(I, JSTRT) = ZZ(II)
          360
                 CONTINUE
0277
              ELSE
0278
0279
              ENDIF
          500 CONTINUE
0280
0281
              ACCUMULATE INTO COSTC(100) AND COSTR(100)
0282
      С
0283
0284
              DO 510 J = 1, NYEARS
0285
                 X = 0.0
                 Y = 0.0
0286
0287
                 DO 505 I = 1,NCOST
                     X = X + MCON(I,J)
0288
0289
                     Y = Y + MRAND(I,J)
          505
0290
                 CONTINUE
                 COSTC(J) = X
0291
0292
                 COSTR(J) = Y
          510 CONTINUE
0293
0294
              RETURN
0295
              END
```

ENTRY POINTS

Address Type Name References
0-0000000 TRAP 7#

VARIABLES

| Address | Туре | Name | Referenc | ces | | |
|------------|------|------|----------|-----|------|-------|
| ** | R*4 | Al | 53= | 57 | 59 | 70(2) |
| | | | 71 | 72 | 76 | 77 |
| | | | 84 | 90 | 93 | 100 |
| ** | R*4 | В | 77= | 100 | 147= | 164 |
| ** | R*4 | C1 | 54= | 57 | 60 | 70 |
| | | | 71(2) | 72 | 131 | 135 |
| | | | 136 | | | |
| 2-000084E0 | R*4 | D1 | 55= | 57 | 61 | 70 |

| • | | | | | | |
|--------------|-------|--------|----------------|------------|----------|------------|
| , | | | 71 | 72(2) | 146 | 147 |
| | | | 148 | 154 | 157 | 164 |
| ** | R*4 | DD | 99= | 100 | 103= | 104 |
| | | | 163= | 164 | 167= | 168 |
| 2-000084D8 | I*4 | I | 28= | 30 | 31 | 33= |
| | | | 34 | 35 | 44= | 51 |
| | | | 52 | 53 | 54 | 55 |
| | | | 56 | 260 | 264 | 272(2) |
| | | | 276 | 287= | 288 | 289 |
| ** | I*4 | II | 98= | 99 | 100 | 102= |
| | | | 103 | 104(2) | 108= | 109(2) |
| | | | 110 | 116= | 117(2) | 123= |
| | | | 124(2) | 137= | 138 | 162= |
| | | | 163 | 164 | 166= | 167 |
| | | | 168(2) | 172= | 173(2) | |
| | | | 177= | 178(2) | 185= | |
| | | | 197= | 198 | 201= | |
| | | | 209= | 210(2) | 214= | |
| | | | 223= | 224(2) | 228= | |
| | | | 238= | 239(2) | 243= | |
| | | | 248= | 249 | 262= | 264 |
| | | | 274= | 276 | | |
| 2-000084DC | I*4 | J | 29= | 30 | 31 | 284= |
| 2-000064DC | T4 | b | 288 | 289 | 291 | 292 |
| ** | I*4 | J1 | 184= | 186 | 187(2): | |
| ^^ | T ~ 4 | U I | 215 | 216(2)= | 226= | 229 |
| | | | 230(2)= | 241= | | 245(2)= |
| | | | 247= | 249 | 250(2)= | 243 (2) |
| ND 000000148 | T + A | JJ | 7 | 50 | 52 | |
| AP-00000140 | I * 4 | JSTRT | 261= | 263(2)= | 264 | 273= |
| * * | 1 ~ 4 | USIKI | 275(2)= | 276 | 204 | 215- |
| | T 4 | 27.7 | 275(2)— 84= | 98 | 102 | 107 |
| ** | I*4 | Nl | | 112 | 116 | 123 |
| | | | 108 | 137 | 148= | 162 |
| | | | 136= | 171 | 172 | 176 |
| | | | 166 | | 185 | 1/6 |
| | | | 177 | 184 248 | 262 | 274 |
| 2-000084E8 | | N2 | 58= | | | 274 |
| AP-0000000C0 | 1*4 | NCOST | 7 | 8 | 28 | 44 |
| | T 4 4 | 17711D | 287 | 214 | 227- | 228 |
| ** | I * 4 | NEND | 213= | 214 | 227= | 220 |
| | | | 242= | 243 | 248 | 212 |
| 2-000084EC | I*4 | NN1 | 59= | 201 | 209 | 213 |
| | | | 214 | 223 | 227 | 228 |
| | | | 238 | 242 | 243 | |
| 2-000084F0 | I*4 | NN2 | 60= | 213 | 242 | |
| 2-000084F4 | I*4 | NN3 | 61= | 227 | | |
| AP-00000008@ | | NRV | 7 | 8 | | |
| AP-000000180 | | NYEARS | 7 | 284 | <u> </u> | |
| 2-000084E4 | R*4 | START | 56= | 261 | 273 | |
| ** | R*4 | SUM | 206= | 208 | 221= | 222 |
| ** | R*4 | TT | 57= | 58 | | . . |
| 2-000084D0 | R*8 | VALUE | 11 | 52= | 91 | 94 |

| | | | | 24 86 | 135 | 155 | 158 |
|--------------|----------|------------|-------|-------------------|----------------|-------------|-----------------|
| ** | R*8 | x | | 11 | 106= | 109 | 110(2)= |
| | | | | 12 | 135= | 138 | 170= |
| | | | | 73 8(2)= | 174(2)= 291 | 176 | 285= |
| ** | R*8 | Y | | 11 | 286= | 289 (2 | 2)= 292 |
| 2-000084F8 | R*4 | Z 1 | | 70= 17 | 90 200 | 93 206 | 94 221 |
| 2-000084FC | R*4 | Z 2 | | 71= | 135 | 206 | |
| 2-00008500 | R*4 | Z 3 | | 72 = 78 | 154 221 | 157 | 158 |
| ARRAYS | | | | | | | |
| Address | Type | и́ате | Bytes | Dimen | sions | Refere | ences |
| AP-00000004@ | R*4 | A | ** | (*, * |) | 7 52 | 8 |
| AP-00000010@ | R*4 | CE | 1600 | (20, | 20) | 7 | 8 |
| | | | | | • | 51 | 53 |
| | | | | | | 54 | 5 5 |
| | | | | | | 56 | 260 |
| 3-00000000 | R*4 | COSMC | 400 | (100) | | 272(2) | 1.0 |
| 3-0000000 | K*4 | COSTC | 400 | (100) | | 8 34= | 18 291= |
| 3-00000190 | R*4 | COSTR | 400 | (100) | | 8 | 18 |
| | | | | (, | | 35= | 292= |
| 2-00007E90 | R*4 | DEL | 400 | (100) | | 8 | 104= |
| | | | | | | 106 | 109(2)= |
| | | | | | | 110 | 112= |
| | | | | | | 117 170 | 168= |
| | | | | | | 174 | 173(2)= 176= |
| | | | | | | 178 | 170- |
| 2-00000000 | R*8 | MCON | 16000 | (20, | 100) | 12 | 30= |
| | | | | | | 264= | 288 |
| 2-00003E80 | R*8 | MRAND | 16000 | (20, | 100) | 12 276= | 31= |
| 2-000081B0 | R*4 | PHACON | 400 | (100) | | 8 | 289 138= |
| | | | 4.0.0 | (| | 215 | 244 |
| 2-00008340 | R*4 | PHAOUT | 400 | (100) | | 8 158= | 155= |
| | | | | | | 158= 229 | 186= 249 |
| 2-00008020 | R*4 | PHASIN | 400 | (100) | | 8 | 91= |
| | - | | | \ <i>\</i> | | 94= | 124= |
| | | | | | | 202 | 210 |
| | | | | | | 224 | 239 |
| 2-00007D00 | R*4 | ZZ | 400 | (100) | | 8 | 100= |
| | | | | | | 104 | 117= |
| | | | | | | 124 | 164 |

```
168 178=

186 198=

202= 210=

215= 224=

229= 239=

244= 249=

264 276
```

```
0001
0002
               SUBROUTINE CER (J, A, NRV, NCOST, B, AAA,
               XSTAR, AA, X, LASTSET,
0003
              lnumcer, super)
               DIMENSION A(NRV, NCOST), B(20), XSTAR(60), X(NRV, 20)
0004
0005
              1, VARCOV(20, 20), bort(20), super(20, 505)
0006
               DOUBLE PRECISION VAR, RINTER, XLOW, XHIGH, T, TT,
               TTT, XTYPE, xmode
0007
               COMMON /AA/ Z(20)
8000
               PARAMETER (NRR=750)
0009
               REAL R(NRR), RR(NRR), SCALAR(NRR)
0010
               INTEGER NR, ISEED
0011
               LOGICAL lastset
0012
               EXTERNAL RNNOR, RNSET
0013
0014
        С
               B(AAA) HOLDS UP TO 20 TOTAL PARAMETERS IN THE CER.
0015
        C
               XSTAR(AA) HOLDS THE LOW, HIGH AND TYPE BETA PDF FOR
0016
        C
               EACH COST DRIVER. IF THE LOW AND HIGH VALUE ARE THE
               SAME
0017
        C
               FOR ANY COST DRIVER THEN IT IS ASSUMED THAT COST
               DRIVER IS
0018
        C
               THE SAME FOR ALL NRV ITERATIONS (ie. A CONSTANT).
               RINTER= THE RINTERCEPT OF THE CER IF ONE IS
0019
        C
               PRESENT.
0020
        C
               NOTE: AA= 3*AAA
               IF A CER CONTAINS MORE THAN 20 PARAMETERS THEN
0021
        C
        C
               VARCOV(20,20) MUST BE INCREASED AS MUST B(AAA),
0022
0023
        C
               XSTAR(AA) AND X(NRV, AAA) IN THE MAIN PROGRAM.
0024
        C
               CLEAR THE ARRAYS.
0025
0026
0027
               N = IFIX(AAA)
0028
               NN = IFIX(AA)
0029
               IF (lastset .EQ. .FALSE.) THEN
0030
               var = 0.0
               DO 2 I = 1, N
0031
                  DO 3 II = 1, N
0032
0033
                     varcov(I,II) = 0.0
0034
                  continue
0035
             2 continue
0036
               DO 5 I = 1,N
0037
                  B(I) = 0.0
```

```
0038
            5 CONTINUE
              DO 6 I = 1,NRV
0039
0040
              DO 6 II = 1,N
                 X(I,II) = 0.0
0041
0042
            6 CONTINUE
0043
              DO 10 I = 1,NN
0044
                 XSTAR(I) = 0.0
           10 CONTINUE
0045
0046
0047
              print*
0048
              print*,'Enter the estimated variance (s-squared): '
0049
              READ*, VAR
0050
              READ VARIANCE COVARIANCE MATRIX.
0051
        C
              NOTE: VARIANCE OF THE INCERCEPT OCCUPIES POSITION
0052
        С
              (1,1)
0053
        C
              IF AN RINTERCEPT IS PRESENT.
0054
              VARCOV = VARIANCE COVARIANCE MATRIX OF THE CER.
0055
0056
              print*
0057
              print*,'Enter the VARIANCE/COVARIANCE matrix'
0058
              print*
0059
              DO 12 I=1, N
              DO 99 II=1,N
0060
                 print 98, I, II
0061
0062
           98
                 FORMAT(' Enter value (',I2,',',I2,')')
0063
                 read*, VARCOV(I,II)
0064
           99 continue
           12 CONTINUE
0065
0066
              READ THE VALUE OF THE RINTERCEPT IF PRESENT THEN
0067
        C
              THE VALUES OF
0068
        C
              THE SLOPE PARAMETERS. THE VECTOR B(I) WILL HOLD THE
              VALUES OF
        С
              ALL OF THE PARAMETERS
0069
0070
              IF (Z(11) . EQ. 1.0) THEN
0071
0072
                 print*
                 print*, 'Enter the value of the Intercept: '
0073
0074
                 READ*, RINTER
0075
                 B(1) = RINTER
0076
                 print*
                 print*, 'Enter the value of the slope
0077
                 parameter(s).'
0078
                 print*
0079
                  DO 15 I = 2,N
                     print 97, I-1
0080
           97
0031
                     FORMAT(' Enter slope parameter ', I2)
2500
                     READ*, B(I)
0083
           15
                  continue
0084
              ELSE
0085
                  print*
```

```
print*,'Enter the value of the slope
0086
                 parameter(s).'
                 print*
0087
                 DO 20 I = 1, N
8800
                     print 96,I
0089
                     FORMAT(' Enter slope parameter ', I2)
           96
0090
                     READ*, B(I)
0091
                 CONTINUE
           20
0092
              ENDIF
0093
0094
              N IS THE NUMBER OF PARAMETERS IN THE CER, INCLUDING
0095
        C
              RINTERCEPT
0096
        C
              IF ONE IS PRESENT.
        C
              NN IS 3*N.
0097
0098
              READ THE VALUES OF XSTAR.
0099
        C
0100
        C
              NOTE IF AN RINTERCEPT IS PRESENT THE NUMBER
              MUST BE
        С
              THE FIRST ELEMENT TO ENTER AND ITS HIGH AND LOW
0101
              VALUE
              MUST = 1.0
0102
        C
0103
0104
              print*
              print*, 'COST DRIVER CARDS'
0105
0106
              print*
0107
              print*, 'Each cost driver is characterized by 3
               cards.
0108
          print*,'1st Card = Low value of Beta or Triangular pdf'
         print*,'2nd Card = High value of Beta or Triangular pdf'
0109
0110
               print*,'3rd Card = Type of Beta pdf or Mode of
               Triang pdf.'
0111
              print*,'(If the cost driver is NOT a random
               variable (ie it'
0112
               print*,'is a constant) then set the 1st and 2nd
               cards (the'
0113
               print*, 'LOW and HIGH values of the Beta or Triag
               distribution)'
               print*, 'equal to the SAME value. If an intercept
0114
               term IS'
               print*, 'present, then set the first 3 cards equal
0115
              to 1.0.)'
              print*
0116
0117
              k = 1
               DO 40 I = 1, N
0118
                  print*
0119
0120
0121
        С
                  Begin the loop to obtain the cost driver data.
0122
0123
                  print 30, I
0124
            30
                  format(' Do you want cost driver #',I2,' to be
                  modeled')
0125
                  print*, by a Beta or Triangular pdf?'
```

```
print*, 'Enter:'
0126
                  print*,'l for BETA pdf'
0127
                  print*,'2 for TRIANGULAR pdf'
0128
0129
                  read*, bort(i)
                 min = 1
0130
0131
                  max = 2
                  asked = bort(i)
0132
                  call ans(min, max, asked, found)
0133
0134
                  bort(i) = asked
0135
                  print*
                  if (bort(i) .eq. 1.0) then
0136
                     if (Z(11) .eq. 1.0 .and. i .eq. 1) then
0137
                      print*, 'Enter the INTERCEPT values NOW, ie'
0138
0139
                        print*, 'THE NEXT 3 RESPONSES MUST BE 1!'
0140
                     else
                     endif
0141
                  print*, 'Enter the LOW value of the Beta pdf for'
0142
0143
                  print 95,I
           95
                  FORMAT(' cost driver #', I2, ': (for example, if
0144
0145
             print*,'LOW number of components to be evaluated is'
0146
                  print*,'50, enter 50.)'
0147
                  READ*, XSTAR(k)
0148
                  print*, 'Enter the HIGH value of the Beta pdf
                  for'
0149
                  print 74,I
0150
           74
                  FORMAT(' cost driver #',I2,':')
0151
                  read*, XSTAR(k+1)
0152
                  IF (k .GT. 1 .AND. Z(12) .EQ. 1.0) THEN
0153
                     XSTAR(k) = LOG(XSTAR(k))
                     XSTAR(k+1) = LOG(XSTAR(k+1))
0154
0155
                  ELSE
0156
                  ENDIF
0157
                  print*, 'Enter the TYPE of Beta pdf for cost'
0158
                  print 75,I
           75
0159
                  FORMAT(' driver #',I2,': (Enter 1.0 -- 9.0)')
0160
                  read*, XSTAR(k+2)
                  min = 1
0161
0162
                  max = 9
0163
                  asked = xstar(k+2)
0164
                  CALL ANS (min, max, asked, found)
0165
                  xstar(k+2) = asked
0166
                  k = k + 3
0167
                  print*
0168
                  else if (bort(i) .eq. 2.0) then
                     if (Z(11) .eq. 1.0 .and. i .eq. 1) then
0169
0170
                        print*, 'Enter the INTERCEPT values NOW.'
                     else
0171
0172
                     endif
                print*, 'Enter the LOW value of the Triang pdf for'
0173
0174
                     print 31, I
0175
           31
                     format(' cost driver #',I2,': (for example,
```

```
1
                     if the')
                     print*,'LOW number of components to be
0176
                     evaluated is'
0177
                     print*,'50, enter 50.)'
                     read*, XSTAR(k)
0178
                     print*, 'Enter the HIGH value of the Triang
0179
                     pdf for'
                     print 32, I
format(' cost driver #',I2,':')
0180
0181
            32
                     read*, XSTAR(k+1)
0182
                     print*, 'Enter the MODE or BEST GUESS of the
0183
                     Triang'
                     print 33, I
0184
0185
            33
                     format(' pdf for cost driver #',I2,':')
                     read*, XSTAR(k+2)
0186
                     if (k .gt. 1 .and. Z(12) .eq. 1.0) then
0187
                         XSTAR(k) = LOG(XSTAR(k))
0188
                         XSTAR(k+1) = LOG(XSTAR(k+1))
0189
                         XSTAR(k+2) = LOG(XSTAR(k+2))
0190
0191
                     else
0192
                     endif
0193
                     k = k + 3
0194
                     else
0195
                     endif
0196
            40 CONTINUE
0197
               call check(var, varcov, xstar, n, b, bort)
0198
               Write the estimated variance, var/cov matrix, slope
0199
        С
               parameters, and cost driver values to the file
0200
        С
               MOREINPT. DAT
0201
0202
               write (02,200) var
           200 format (f31.16)
0203
               do 201 I = 1,n
0204
0205
               do 201 II = 1,n
                  write (02,202) varcov(I,II)
0206
                  format (f31.16)
0207
           202
0208
           201 continue
0209
               do 203 I = 1,n
                  write (02,204) B(I)
0210
0211
           204
                  format (f31.16)
           203 continue
0212
0213
               k = 1
0214
               do 205 I = 1,n
                  write (02,206) XSTAR(k)
0215
0216
           206
                  format (f15.8)
0217
                  write (02,80) XSTAR(k+1)
                  format (f15.8)
0218
            80
0219
                  write (02,81) XSTAR(k+2)
0220
                  format (f15.8)
            81
                  k = k + 3
0221
0222
           205 continue
```

```
0223
              do 207 i = 1, n
                  write(02,208) bort(i)
0224
          208
0225
                  format(f5.3)
0226
          207 continue
              ELSE IF (lastset .EQ. .TRUE.) THEN
0227
0228
0229
               The data set entered on the previous run is being
        С
               entered,
               therefore its values have to be read in from the
0230
        С
              file,
0231
              MOREINPT.DAT.
        С
0232
0233
                  iii = 2
                  var = super(numcer,1)
0234
0235
                  DO 137 I = 1, N
                     DO 138 II = 1, N
0236
                        varcov(i,ii) = super(numcer,iii)
0237
0238
                        iii = iii + 1
0239
          138
                     continue
          137
                  continue
0240
0241
                  IF (Z(11) . EQ. 1.0) THEN
0242
                     RINTER = super(numcer,iii)
                     B(1) = RINTER
0243
                     iii = iii + 1
0244
0245
                     DO 141 I = 2, N
                        b(i) = super(numcer, iii)
0246
                        iii = iii + 1
0247
0248
          141
                     continue
0249
                  ELSE
0250
                     DO 143 I = 1, N
                        b(i) = super(numcer, iii)
0251
0252
                        iii = iii + 1
0253
          143
                     continue
0254
                  ENDIF
                  k = 1
0255
0256
                  DO 145 I = 1, N
                     XSTAR(k) = super(numcer,iii)
0257
0258
                     XSTAR(k+1) = super(numcer, iii+1)
0259
                     XSTAR(k+2) = super(numcer, iii+2)
                     k = k + 3
0260
                     iii = iii + 3
0261
0262
          145
                  continue
0263
                  do 147 i = 1, n
                     bort(i) = super(numcer,iii)
0264
                     iii = iii + 1
0265
          147
                  continue
0266
0267
               ELSE
0268
               ENDIF
0269
0270
        C
               CHECK TO SEE IF THE COST DRIVER HAS THE SAME LOW
               AND
0271
        C
               HIGH VALUE. IF SO, THAT VALUE IS THE SAME FOR ALL
```

```
NRV
              RUNS. ALL OTHER COST DRIVERS MUST PASS THROUGH THE
0272
        С
              RANDOM NUMBER GENERATOR FOR THE APPROPRIATE BETA
        C
0273
               PDF.
0274
               ITA=1
0275
               ITB=2
0276
               ITC=3
0277
               DO 100 I = 1,N
0278
                if (bort(i) .eq. 1.0) then
0279
                   IF (XSTAR(ITA) .EQ. XSTAR(ITB)) THEN
0280
                    DO 50 II = 1,NRV
0281
                       X(II,I) = XSTAR(ITA)
0282
0283
           50
                    CONTINUE
                   ELSE
0284
                    XLOW = XSTAR(ITA)
0285
                    XHIGH = XSTAR(ITB)
0286
                    XTYPE = XSTAR(ITC)
0287
                    CALL BETA1 (J, XLOW, XHIGH, XTYPE, NRV, R)
0288
0289
                    DO 60 II = 1,NRV
                       X(II,I) = R(II)
0290
0291
            60
                    CONTINUE
                   ENDIF
0292
                  ITA = ITA+3
0293
               ITB = ITB+3
0294
0295
               ITC = ITC+3
               else if (bort(i) .eq. 2.0) then
0296
0297
               if (xstar(ita) .eq. xstar(itb)) then
                  do 71 ii = 1,nrv
0298
0299
                     x(ii,i) = xstar(ita)
0300
            71
                  continue
               else
0301
0302
               xlow = xstar(ita)
0303
               xhigh = xstar(itb)
0304
               xmode = xstar(itc)
               call triag1(j,xlow,xhigh,xmode,nrv,r)
0305
               do 70 \text{ ii} = 1, nrv
0306
                  x(ii,i) = r(ii)
0307
            70 continue
0308
0309
               endif
               ita = ita + 3
0310
               itb = itb + 3
0311
               itc = itc + 3
0312
0313
               else
0314
               endif
           100 CONTINUE
0315
0316
               DRAW NRV RANDOM SAMPLES FROM NORMAL(0,1).
0317
        С
               STORE THEM IN VECTOR RR(NRV).
0318
0319
               NR = NRV
0320
0321
               CALL RNSET(0)
```

```
0322
               CALL RNNOR (NR, RR)
0323
               IF (Z(13) . EQ. 1.0) THEN
0324
                  if (Z(20) .eq. 1.0) then
0325
                      XLOW = Z(14)
0326
                      XHIGH = Z(15)
                      XTYPE = Z(16)
0327
0328
                      IF (Z(14) . EQ. Z(15)) THEN
                         DO 105 KKK = 1,NRV
0329
0330
                            SCALAR(KKK) = Z(14)
0331
           105
                         CONTINUE
0332
                     ELSE
0333
                         CALL BETA1 (J, XLOW, XHIGH, XTYPE, NRV, SCALAR)
0334
                     ENDIF
0335
                  else if (Z(20) \cdot eq. 2.0) then
                      xlow = Z(14)
0336
0337
                      xhigh = Z(15)
0338
                     xmode = Z(16)
0339
                      if (Z(14) .eq. Z(15)) then
0340
                         do 7 kkk = 1, nrv
0341
                            scalar(kkk) = Z(14)
0342
             7
                         continue
0343
                      else
0344
                         CALL TRIAG1(j,xlow,xhigh,xmode,nrv,scalar)
0345
                      endif
0346
                  else
0347
                  endif
0348
               ELSE
0349
               ENDIF
0350
               DO 300 I = 1,NRV
0351
                DO 111 K = 1, N
0352
                T = 0.0
0353
                DO 110 L = 1, N
0354
                   T = T + (X(I,L)*VARCOV(L,K))
0355
           110
                CONTINUE
0356
                R(K) = T
0357
           111
                CONTINUE
0358
                T = 0.0
0359
                DO 115 II = 1,N
0360
                   T = T + (R(II) *X(I,II))
0361
           115
                CONTINUE
0362
        C
                T IS THE QUADRATIC FORM X'(VARCOV)X
0363
0364
0365
                T = VAR + T
0366
                T = DSQRT(T)
0367
                TT = RR(I) *T
0368
                TTT = 0.0
0369
                DO 120 II = 1,N
0370
                   TTT = TTT + (X(I,II)*B(II))
0371
           120
                CONTINUE
0372
                T = TT + TTT
0373
```

```
0374 C
            CHECK TO SEE IF THE DEPENDENT VARIABLE IS IN LOG
            FORM
       С
0375
             (IE. CER WAS ESTIMATED BY TAKING LOG OF BASE E. IF
       С
             SO TAKE THE ANITLOG OF THE FORECAST.
0376
0377
0378
              IF (Z(12) .EQ. 1.0) THEN
                T = DEXP(T)
0379
0380
             ELSE
             ENDIF
0381
0382
      С
0383
             T IS THE FORECASTED VALUE OF THE CER FOR RANDOM
0384
      С
             NUMBER # I
      С
             STORE THE VALUE IN THE A(NRV, NCOST) MATRIX.
0385
0386
0387
              IF (Z(13) . EQ. 1.0) THEN
                A(I,J) = SCALAR(I)*T
0388
0389
              ELSE
                A(I,J) = T
0390
0391
              ENDIF
          300 CONTINUE
0392
0393
              RETURN
0394
              END
```

ENTRY POINTS

Address Type Name References
0-00000000 CER 2#

VARIABLES

| Name | Referenc | es | | |
|-------|-----------------------------|---|---|---|
| AA | 2 | 28 | | |
| AAA | 2 | 27 | | |
| ASKED | 132= | 133A | 134 | 163= |
| | 164A | 165 | | |
| FOUND | 133A | 164A | | |
| I | 31= | 33 | 36= | 37 |
| | 39= | 41 | 43= | 44 |
| | 59= | 61 | 63 | 79= |
| | 80 | 82 | 88= | 89 |
| | 91 | 118= | 123 | 129 |
| | 132 | 134 | 136 | 137 |
| | 143 | 149 | 158 | 168 |
| | 169 | 174 | 180 | 184 |
| | 204= | 206 | 209= | 210 |
| | 214= | 223= | 224 | 235= |
| | 237 | 245= | 246 | 250= |
| | AA AAA ASKED FOUND | AA 2 AAA 2 ASKED 132= 164A FOUND 133A I 31= 39= 59= 80 91 132 143 169 204= 214= | AA 2 28 AAA 2 27 ASKED 132= 133A 164A 165 FOUND 133A 164A I 31= 33 39= 41 59= 61 80 82 91 118= 132 134 143 149 169 174 204= 206 214= 223= | AAA 2 27 ASKED 132= 133A 134 164A 165 FOUND 133A 164A I 31= 33 36= 39= 41 43= 59= 61 63 80 82 88= 91 118= 123 132 134 136 143 149 158 169 174 180 204= 206 209= 214= 223= 224 |

| | | | 251 278= 296 354 388(2) | 256= 279 299 360 390 | 263= 282 307 367 | 264 290 350= 370 |
|--------------|-------|---------|-------------------------------------|----------------------------------|--|----------------------------|
| ** | I*4 | II | 32= 60= 206 282 | 33 61 236= 289= | 40= 63 237 290(2) | 41 205= 281= 298= |
| ** | I*4 | III | 299 360(2) 233= 244(2)= | 306= 369= 237 246 | 307(2) 370(2) 238(2)= 247(2)= | 359= 242 251 |
| | | | 252(2)= 261(2)= | 257 264 | 258 265(2)= | 259 |
| ** | I*4 | ISEED | 10 | | (- / | |
| ** | I * 4 | ITA | 275= | 280 | 282 | 285 |
| | | | 293(2)= | 297 | 299 | 302 |
| | | | 310(2)= | | | |
| ** | I*4 | ITB | 276 - | 280 | 286 294 | 1(2)= |
| | | | 297 | 303 | 311(2)= | ` . |
| 2-00002A48 | I * 4 | ITC | 277= | 287 | 295(2)= | 304 |
| | | | 312(2)= | | • • | |
| AP-00000004@ | I*4 | J | 2 | 288A | 305A | 333A |
| | | | 344A | 388 | 390 | |
| ** | I * 4 | K | 117= | 147 | 151 | 152 |
| | | | 153(2) | 154(2) | 160 | 163 |
| | | | 165 | 166(2)= | 178 | 182 |
| | | | 186 | 187 | 188(2) 18 | 39(2) |
| | | | 190(2) | 193(2)= | 213= | 215 |
| | | | 217 | 219 | 221(2)= | 255= |
| | | | 257 | 258 | 259 260 | 0(2)= |
| | | | 351= | 354 | 356 | |
| ** | I * 4 | KKK | 329= | 330 | 340= | 341 |
| ** | I * 4 | L | 353= | 354(2) | | |
| AP-00000028@ | | LASTSET | 2 | 11 | 29 | 227 |
| 2-00002A24 | I * 4 | MAX | 131= | 133A | 162= | 164A |
| 2-00002A20 | I * 4 | MIN | 130= | 133A | 161= | 164A |
| 2-000029EC | I * 4 | N | 27= | 31 | 32 | 36 |
| | | | 40 | 59 | 60 | 79 |
| | | | 88 | 118 | 197A | 204 |
| | | | 205 | 209 | 214 | 223 |
| | | | 235 | 236 | 245 | 250 |
| | | | 256 | 263 | 278 | 351 |
| 3D 000000100 | T 4 | MOOOM | 353 | 359 | 369 | |
| AP-00000100 | I * 4 | NCOST | 2 | 4 | | |
| 2-000029E8 | I * 4 | NN | 28= | 43 | 2223 | |
| AP-0000000C0 | I * 4 | NR | 10 2 | 320= | 322A | 202 |
| AF-0000000C@ | I*4 | NRV | 288A | 4(2) | 39 | 281 |
| | | | 306 | 289 320 | 208 508 | 305A |
| | | | 340 | | 329 | 333A |
| | | • | 340 | 344A | 350 | |

| AP-0000002de | I*4 | NUMCER | 2 | 234 | 237 | 242 |
|--------------|-----|--------|------|---------|-----------|-------|
| | | | 246 | 251 | 257 | 258 |
| | | | 259 | 264 | | |
| 2-000029C0 | R*8 | RINTER | 6 | 74= | 75 | 242= |
| | | | 24 | | | |
| ** | R*8 | T | 6 | 352= | 354(2)= | 356 |
| | | | 358= | 360(2)= | 365(2) 36 | 6(2)= |
| | | | 367 | 372= | 379(2)= | 388 |
| | | | 390 | | | |
| ** | R*8 | TT | 6 | 367= | 372 | |
| ** | R*8 | TTT | 6 | 368= | 370(2)= | 372 |
| 2-000029B8 | R*8 | VAR | 6 | 30= | 49= | 197A |
| | | | 202 | 234= | 365 | |
| 2-000029D0 | R*8 | XHIGH | 6 | 286= | 288A | 303= |
| | | | 305A | 326= | 333A | 337= |
| | | | 344A | | | |
| 2-000029C8 | R*8 | XLOW | 6 | 285= | 288A | 302= |
| | | | 305A | 325= | 333A | 336= |
| | | | 344A | | | |
| 2-000029E0 | R*8 | XMODE | 6 | 304= | 305A | 338= |
| | | | 344A | | | |
| 2-000029D8 | R*8 | XTYPE | 6 | 287= | 288A | 327= |
| | | | 333A | | | |

ARRAYS

| Address ' | Type | Name | Bytes | Dimensions | Reference | es |
|--------------|--------------|--------|-------|------------|--------------|------------------------|
| AP-00000008@ | R*4 | A | ** | (*, *) | 2 | 4 |
| 3D 000000148 | D + 4 | D | 0.0 | (20) | 388= | 390= |
| AP-000000140 | K*4 | В | 80 | (20) | 2 37= | 4 75= |
| | | | | | 82= | 75 - 91= |
| | | | | | 197A | 210 |
| | | | | | 243= | 246= |
| | | | | | 251= | 370 |
| 2-00000640 | R*4 | BORT | 80 | (20) | 4 | 129= |
| | | | | , | 132 | 134= |
| | | | | | 136 | 168 |
| | | | | | 197A | 224 |
| | | | | | 264= | 279 |
| | | | | | 296 | |
| 2-00000690 | R*4 | R | 3000 | (750) | 9 | 288A |
| | | | | | 290 | 305A |
| | | | | • | 307 | 356= |
| 0 00001040 | D 1 4 | 22 | 2000 | (250) | 360 | |
| 2-00001248 | R*4 | RR | 3000 | (750) | 9 | 322A |
| 2-00001E00 | R*4 | SCALAR | 3000 | (750) | 367 | 220- |
| 2-00001E00 | K^4 | SCALAR | 3000 | (750) | 9 333A | 330= |
| | | | | | 333A 344A | 341= 388 |
| AP-00000030@ | R*4 | SUPER | 40400 | (20, 505) | 2 | 4 |

| | | | | | 234 242 251 258 264 | 237 246 257 259 |
|---------------|-------|--------|------|----------|--|--|
| 2-00000000 | R*4 | VARCOV | 1600 | (20, 20) | 4 63= 206 354 | 33= 197A 237= |
| AP-00000024@ | R*4 | x | ** | (*, 20) | 2 41= 290= 307= 360 | 4 282= 299= 354 370 |
| AP-0000001C@ | R*4 | XSTAR | 240 | (60) | 2 44= 151= 154(2)= 163 178= 186= 189(2)= 197A 217 257= 259= 282 286 297(2) 302 304 | 4 147= 153(2)= 160= 165= 182= 188(2)= 190(2)= 215 219 258= 280(2) 285 287 299 303 |
| 3-0000000 | R*4 | Z | 80 | (20) | 7 137 169 241 324 326 328(2) 335 337 339(2) 378 | 71 152 187 323 325 327 330 336 338 341 387 |
| PARAMETER CON | STANT | S | | | | |
| Type Name | | | | | References | |
| I*4 NRR | | | | | 8# | 9(3) |

FUNCTIONS AND SUBROUTINES REFERENCED

Type Name References

```
CHECK
                                   197
        MTH$ALOG
  R*4
                                   153
                                             154
                                                        188
                                                                  189
                                   190
   R*8
       MTH$DEXP
                                   379
  R*8 MTH$DSQRT
                                   366
        RNNOR
                                    12
                                             322
        RNSET
                                    12
                                             321
        TRIAG1
                                   305
                                             344
0001
0002
              subroutine check(var, varcov, xstar, n, b, bort)
0003
0004
              dimension xstar(60), varcov(20,20), B(20), bort(20)
0005
              double precision var
0006
              logical done
0007
              common /aa/ Z(20)
8000
0009
              call clrscr
0010
              x = 0.0
0011
              print*,'The estimated variance (s-squared),
              covariance matrix,'
0012
              print*, 'slope parameters, and cost driver cards
              have just been'
0013
              print*,'entered.'
              print*, 'Do you wish to review or edit any of
0014
              these?'
0015
              print*
              print*,'Enter:'
0016
0017
              print*,'1 for YES'
              print*,'2 for NO'
0018
0019
              read*, yorn
              min = 1
0020
0021
              max = 2
0022
              asked = yorn
0023
              call ans(min, max, asked, found)
0024
              yorn = asked
0025
               if (yorn .eq. 1.0) then
0026
                  print*
0027
              print*,'Do not be surprised if some round-off has'
              print*, 'occurred -- this will happen at times due'
0028
0029
              print*, 'the size (large or small) of the
               variables.'
0030
                  print*
0031
                  print 80, var
0032
           80
                  format(' 1. variance (s-squared) = ',F31.16)
0033
                  print*
0034
                  k = 2
0035
                  do 81 I = 1, n
```

133

288

164

333

ANS

BETA1

```
do 81 II = 1,n
0036
0037
                     print 82, k,I,II,varcov(I,II)
                     format(I3,'. varcov (',I2,',',I2,') =
0038
           82
                     ',F31.16)
0039
                     k = k + 1
0040
           81
                  continue
0041
                  print*
0042
                  print*, 'Press RETURN to continue . . . '
0043
0044
                  k = n*n + 2
0045
                  if (Z(11) .eq. 1.0) then
0046
                     print 83, k, B(1)
0047
           83
                     format(I3,'. intercept =
                                                     ',F31.16)
0048
                     do 84 I = 2,n
0049
                        k = k + 1
0050
                        print 85, k, I-1, B(I)
0051
           85
                        format(I3,'. slope param ',I2,' =
                         ',F31.16)
0052
           84
                     continue
0053
                  else
0054
                     do 87 I = 1,n
0055
                        print 86, k, I, B(I)
0056
           86
                        format(I3,'. slope param ',I2,' =
                         ',F31.16)
0057
                        k = k + 1
0058
           87
                     continue
0059
                  endif
0060
                  print*
0061
                  k = ((n*n) + n + 2)
                  kk = 1
0062
0063
                  do 88 I = 1, n
0064
                     print 89, I
0065
           89
                     format(' Cost Driver for Element #',I2,':')
0066
                     print 90, k,XSTAR(kk)
0067
           90
                     format(I3,'. LOW value = ',F15.8)
                     print 91, k+1,XSTAR(kk+1)
0068
0069
           91
                     format(I3,'. HIGH value = ',F15.8)
0070
                     if (bort(i) .eq. 1.0) then
0071
                        print 92, k+2,XSTAR(kk+2)
                         format(I3,'. Beta TYPE = ',F15.8)
0072
           92
0073
                     else if (bort(i) .eq. 2.0) then
0074
                        print 40, k+2, XSTAR(kk+2)
0075
                         format(I3,'. MODE value = ',f15.8)
            40
0076
                     else
                     endif
0077
0078
                     print*
0079
                     k = k + 3
0800
                     kk = kk + 3
0081
           88
                  continue
0082
                  print*
0083
                  print*, 'Do you want to edit any of these?'
0084
                  print*, 'Enter:'
```

```
0085
                  print*,'1 for YES'
                  print*,'2 for NO'
0086
0087
                  read*, yorn
                  asked = yorn
0088
0009
                  call ans(min, max, asked, found)
0090
                  yorn = asked
0091
                  if (yorn .eq. 1) then
0092
                     print*
0093
                 print*, 'How many values would you like to edit?'
0094
                     print*,'(Enter 0 to exit)'
0095
                     read*, numchanges
                     done = .false.
0096
0097
          888
                     if (done .eq. .false.) then
                     if (numchanges .qt. 0) then
0098
                        do 93 iii = 1, numchanges
0099
0100
           94
                           print*
                           print*,'Enter the # of the value to be'
0101
0102
                           print*, 'changed (from the left hand
                           column) '
                           read*, jjj
0103
0104
                           jcount = 1
0105
                           ic = 1
0106
                           kcount = n*n
0107
                           if (jjj) .lt. 1 .or. jjj .qt. (n*n + 4*n)
                           + 1)) then
0108
                               go to 94
                           else if (jjj .eq. 1) then
0109
0110
                                  print*
0111
                                  print*, 'Enter the NEW variance
                                  (s-squared):'
0112
                                  read*, var
0113
                           else if (jjj .gt. 1 .and. jjj .le.
                            (n*n+1)) then
           25
                                  if (ic .le. kcount) then
0114
0115
                                     isum = ic*n
0116
                                     if ((jjj-1) .le. isum) then
0117
                                        I = jcount
0118
                                        II = (jjj - 1 -
                                         (jcount-1)*n)
0119
                                         ic = n*n+1
                                        go to 25
0120
0121
                                     else
0122
                                         ic = ic + 1
0123
                                         isum = ic*n
0124
                                        jcount = jcount + 1
0125
                                        go to 25
0126
                                     endif
0127
                                  else
0128
                                  endif
0129
                                  print 8, I,II
0130
                         format(' Enter the NEW
             8
                         VARCOV(',I2,',',I2,')')
```

```
0131
                                   read*, varcov(I,II)
0132
                         else if (jjj .gt. (n*n+1) .and. jjj .le.
0133
              1(n*n+n+1)) then
0134
                                   icount = jjj - (n*n+1)
                                   if (Z(11) .eq. 1.0) then
0135
0136
                                      if (icount .eq. 1) then
0137
                                         print*
0138
                                         print*, 'Enter the NEW
                                         INTERCEPT: '
0139
                                         read*, B(1)
0140
                                         rinter = B(1)
0141
                                      else
                                         print*
0142
                                         print 15, icount-1
0143
0144
           15
                                         format(' Enter the NEW
                                         Slope Param', I3)
0145
                                         read*, B(icount)
0146
                                      endif
0147
                                  else
0148
                                      print*
0149
                                      print 16, icount
0150
            16
                                      format(' Enter the NEW Slope
                                      Param', I3)
0151
                                      read*, B(icount)
0152
                                   endif
0153
                               else if (jjj .gt. (n*n + n + 1))
                               then
0154
                                   icount = jjj - (n*n+n+1)
0155
                                  print*
                                  print 33, icount format(' Enter the NEW XSTAR
0156
0157
            33
                                   (',I2,') term:')
                                  read*, XSTAR(icount)
0158
0159
                                else
0160
                               endif
0161
            93
                         continue
0162
                      else
0163
                         done = .true.
0164
                      endif
0165
                     print*
0166
                     print*, 'Do you wish to make further changes?'
                     print*, 'Enter:'
0167
                     print*,'1 for YES'
0168
                     print*,'2 for NO'
0169
0170
                     read*, yorn
0171
                     asked = yorn
0172
                     call ans(min, max, asked, found)
0173
                     yorn = asked
0174
                      if (yorn .eq. 1.0) then
0175
                         go to 888
0176
                     else
0177
                         done = .true.
```

| | • | |
|------|--------|-------|
| 0178 | , | endif |
| 0179 | | else |
| 0180 | | endif |
| 0181 | els | e |
| 0182 | end | if |
| 0183 | else | |
| 0184 | endif | |
| 0185 | return | |
| 0186 | end | |
| | | |

ENTRY POINTS

| Address | Туре | Name | References | | | | |
|------------------|------------|------------|--------------------------------|-----------------------------|--------------------------------|--------------------|--|
| 0-0000000 | | CHECK | 3# | | | | |
| VARIABLES | | | | | | | |
| Address | Туре | Name | Referenc | es | | | |
| 2-00000010 | R*4 | ASKED | 22= 89A 173 | 23A 90 | 24 171= | 88= 172A | |
| 2-00000000 | J.*4 | DONE | 6 177= | 96= | 97 | 163= | |
| 2-00000014 ** | R*4 I*4 | FOUND I | 23A 35= 54= 70 131 | 89A 37(2) 55(2) 73 | 172A 48= 63= 117= | 50(2) 64 129 | |
| ** | I*4 | IC | 105= 122(2)= | 114 123 | 115 | 119= | |
| ** | I*4 | ICOUNT | 134= 149 158 | 136 151 | 143 154= | 145 156 | |
| 2-00000018 | I*4 | II | 36= 131 | 37(2) | 118= | 129 | |
| ** | I*4 | III | 99= | | | | |
| ** | I*4 | ISUM | 115≔ | 116 | 123= | | |
| ** | I*4 | JCOUNT | 104= | 117 | 118 | 124(2)= | |
| 2-00000020 | I*4 | JJJ | 103= 116 153 | 107(2) 118 154 | 109 132(2) | 113(2) 134 | |
| ** | I*4 | K | 34= 46 57(2)= 71 | 37 49(2)= 61= 74 | 39(2) = 50 66 79(2) = | 44= 55 68 | |
| ** | I*4 | KCOUNT | 106= | 114 | · - \—/ | | |
| ** | I * 4 | KK | 62= 74 | 66 80(2)= | 68 | 71 | |
| 2-0000000C | I*4 | MAX | 21= | 23A | 89A | 172A | |

| 2-0000 AP-0000 2-0000 AP-0000 | 00010@ 0001C * 00004@ | I*4 R*4 | MIN N NUMCHANG RINTER VAR X YORN | 118 134 | (2) (2) = = = | 23A 35 54 107(3) 119(2) 153(3) 98 5 22 88 171 | 89A 36 61(3) 113(2) 123 154(3) 99 31 24= 90= 173= | 172A 44(2) 63 115 132(5) 112= 25 91 174 |
|---|--------------------------------|------------|--|------------|---------------------------|---|---|---|
| ARRAYS | | | | | | | | |
| Add | ress ! | Type | Name | Bytes | Dime | nsions | Reference | es |
| AP-000 | 000140 | R*4 | В | 80 | (20) | | 3 46 55 140 151= | 4 50 139= 145= |
| AP-000 | 000180 | R*4 | BORT | 80 | (20) | | 3 | 4 |
| AP-000 | 980000 | R*4 | VARCOV | 1600 | (20, | 20) | 70 3 | 73 4 |
| AP-000 | | | XSTAR | 240 | (60) | | 37 3 66 71 158= | 131= 4 68 74 |
| 3-000 | 00000 | R*4 | Z | 80 | (20) | | 7 135 | 45 |
| FUNCTIO | NS AND | SUBR | OUTINES R | EFEREN | ICED | | | |
| Type | Name | | | | Refer | ences | | |
| | ANS CLRSC | R | | | 23 9 | 89 | 172 | |
| 0001 0002 0003 SUBROUTINE BETA1(J,XLOW,XHIGH,XTYPE,NRV,R) 0004 INTEGER ISEED 0005 PARAMETER (NR=750) 0006 REAL PIN,QIN,R(NR) 0007 EXTERNAL RNBET,RNSET 0008 0009 C CHECK FOR TYPE OF BETA DISTRIBUTION. | | | | | | | | |

```
0011
              IF (XTYPE .EQ. 1.0) THEN
0012
                  PIN = 2.5
0013
                  QIN = 1.5
0014
              ELSE IF (XTYPE .EQ. 2.0) THEN
                 PIN = 2.35
0015
0016
                  QIN = 2.35
              ELSE IF (XTYPE .EQ. 3.0) THEN
0017
0018
                  PIN = 1.5
0019
                  QIN = 2.5
              ELSE IF (XTYPE .EQ. 4.0) THEN
0020
0021
                  PIN = 4.0
                  QIN = 2.0
0022
              ELSE IF (XTYPE .EQ. 5.0) THEN
0023
0024
                  PIN = 3.75
0025
                  QIN = 3.75
0026
              ELSE IF (XTYPE .EQ. 6.0) THEN
0027
                  PIN = 2.0
                  QIN = 4.0
0028
0029
              ELSE IF (XTYPE .EQ. 7.0) THEN
0030
                  PIN = 5.5
0031
                  QIN = 2.5
              ELSE IF (XTYPE .EQ. 8.0) THEN
0032
0033
                  PIN = 5.0
0034
                  QIN = 5.0
0035
              ELSE IF (XTYPE .EQ. 9.0) THEN
0036
                  PIN = 2.5
                  QIN = 5.5
0037
              ELSE
0038
0039
              ENDIF
0040
0041
              CALL RNSET(0)
0042
              CALL RNBET (NR, PIN, QIN, R)
0043
              DO 10 I = 1,NR
0044
                  R(I) = XLOW+((XHIGH-XLOW)*R(I))
0045
           10 CONTINUE
0046
              RETURN
0047
              END
```

ENTRY POINTS

Address Type Name References
0-00000000 BETA1 3#

VARIABLES

Address Type Name References

** I*4 I 43= 44(2)

| ** AP-00000004@ AP-00000014@ 2-00000000 | I*4 I*4 I*4 R*4 | ISEED J NRV PIN | - | 4 3 3 6 21= 33= | 12= 24= 36= | 15= 27= 42A | 18= 30= |
|--|--------------------------|--------------------------|---------|--------------------------------|-------------------------|-------------------|------------|
| 2-00000004 | R*4 | QIN | | 6 22= 34= | 13= 25= 37= | 16= 28= 42A | 19= 31= |
| AP-0000000000 AP-000000008@ AP-00000010@ | R*4 | XHIGH XLOW XTYPE | : | 3 3 3 20 | 44 44(2) 11 23 | 14 26 | 17 29 |
| 32 35 ARRAYS | | | | | | | |
| Address | Type | Name | Bytes | Dimensio | ns Refere | ences | |
| AP-00000018@ | R*4 | R | 3000 | (750) | 3 44(2)= | | 6 42A |
| PARAMETER CON | STANT | S | | | | | |
| Type Name | | | | Referen | ces | | |
| I*4 NR | | | | 5# | 6 | 42 | 43 |
| FUNCTIONS AND | SUBR | OUTINES | REFEREN | CED | | | |
| Type Name | | | | | Referen | ces | |
| RNBET RNSET | | | | | 7 7 | | 42 41 |

| + | | |
|-----|-----|--------------------------------------|
| į | | KEY TO REFERENCE FLAGS |
| - [| = | - Value Modified |
| - [| # | - Defining Reference |
| -[| A | - Actual Argument, possibly modified |
| 1 | D | - Data Initialization |
| ļ | (n) | - Number of occurrences on line |

COMMAND QUALIFIERS

FORTRAN/LIS/CROSS TT.FOR

```
/CHECK=(N)BOUNDS,OVERFLOW,NOUNDERFLOW)
/DEBUG=(NOSYMBOLS,TRACEBACK)
/SHOW=(NODICTIONARY,NOINCLUDE,MAP,NOPREPROCESSOR,SINGLE)
```

```
/STANDARD=(NOSEMANTIC, NOSOURCE_FORM, NOSYNTAX)
  /WARNINGS=(NODECLARATIONS, GENERAL, NOULTRIX, NOVAXELN)
  /CONTINUATIONS=19 /CROSS_REFERENCE /NOD_LINES
/NOEXTEND_SOURCE
       /NOG FLOATING /14 /NOMACHINE_CODE /OPTIMIZE
  /F77
/NOPARALLEL
  /NOANALYSIS DATA
  /NODIAGNOSTICS
  /LIST=GOR91M: [JGIBSON]TT.LIS;37
  /OBJECT=GOR91M: [JGIBSON]TT.OBJ;1
```

COMPILATION STATISTICS

Run Time: 9.48 seconds Run Time.
Elapsed Time: 11.02 seconds

Page Faults: 1936

Dynamic Memory: 1494 pages

Bibliography

- 1. Department of the Air Force. <u>Cost Estimating</u>
 <u>Procedures</u>. AFSCM 173-1. Washington: HQ AFSC, 17
 April 1972.
- 2. Office of the Assistant Secretary of Defense. <u>Cost and Operational Effectiveness Analysis (COEA) Guidelines</u>. DoD Directive 5000.1. Washington: Government Printing Office, February 1990.
- 3. Pritsker, A. Alan B. <u>Introduction to Simulation and SLAM II</u>, (third edition). New York: Systems Publishing Corporation, 1986.
- 4. Seldon, Robert M. <u>Life Cycle Costing: A Better Method of Government Procurement</u>. Boulder, CO: Westview Press, 1979.
- 5. Sobol, I. M. <u>The Monte Carlo Method</u>. Moscow: Mir Publishers, 1975.
- 6. Sumner, Capt David L. An Interactive Life Cycle Cost Forecasting Tool. MS thesis, AFIT/GOR/ENS/90M-17. School of Engineering, Air Force Institute of Technology (AU), Wright-Patterson AFB, OH.
- 7. Tadikamalla, Pandu R. "Computer Generation of Gamma Random Variables II," <u>Communications of the ACM</u>, 21:925-928 (November 1978).